



U.S. Department  
of Transportation

**National Highway  
Traffic Safety  
Administration**

400 Seventh Street, S.W.  
Washington, D.C. 20590


Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

\*\*\*    \*\*\*    \*\*\*



AUTO SAFETY HOTLINE  
(800) 424-9393  
Wash. D.C. Area 366-0123



## CASE SUMMARY

PSU 74 CASE NO. 195J TYPE OF ACCIDENT Minivan-Car/Angle collision

### A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

(Provide a summary of the accident sequence as well as any particular event of the accident that is noteworthy. Injury mechanism and vehicle crashworthiness is the focus, not driver culpability. Do not include any personal identifiers.)

See Attached

### B. VEHICLE PROFILE(S)

Vehicle No.	Class of Vehicle	Year/Make/Model	Most Severe Damage Based on Vehicle Inspection		Component Failure
			Damage Plane	Severity Description	

DO NOT SANITIZE THIS FORM



# C. PERSON PROFILE(S)

Vehicle No.	Person Role	Seat Position	Restraint Use	Most Severe Injury (TO BE COMPLETED BY ZONE CENTER)			
				Body Region	Injury Type	AIS	Injury Source

## Body Region

Abdomen  
 Ankle—foot  
 Arm (upper)  
 Back-thoracolumbar spine  
 Brain  
 Chest  
 Ears  
 Eye  
 Elbow  
 Face  
 Forearm  
 Head—skull  
 Heart  
 Kidneys  
 Knee  
 Leg (lower)  
 Liver  
 Lower limbs(s) (whole or unknown part)  
 Mouth  
 Neck—cervical spine  
 Nose

Pelvic—hip  
 Pulmonary—lungs  
 Shoulder  
 Spleen  
 Thigh  
 Thyroid, other endocrine gland  
 Upper limb(s) (whole or unknown part)  
 Vertebrae  
 Whole body  
 Wrist—hand

## Injury Type

Abrasion  
 Amputation  
 Avulsion  
 Burn  
 Concussion  
 Contusion  
 Crush  
 Detachment, separation  
 Dislocation

Fracture  
 Fracture and dislocation  
 Laceration  
 Other  
 Perforation, puncture  
 Rupture  
 Sprain  
 Strain  
 Total severance, transection  
 Unknown

## Abbreviated Injury Scale

- (1) Minor injury
- (2) Moderate injury
- (3) Serious injury
- (4) Severe injury
- (5) Critical injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

DO NOT SANITIZE THIS FORM

PSU74

1996 Case Summary Form

CASE 195J

TYPE OF ACCIDENT: CAR-CAR/ANGLE COLLISION

A. DESCRIPTION OF THE ACCIDENT SEQUENCE AND ACCIDENT PECULIARITIES

VEHICLE 1 WAS HEADED EAST ON A FIVE LANE DIVIDED STREET. VEHICLE 2 WAS HEADED NORTH ON A UNDIVIDED TWO WAY STREET. DUE TO CONSTRUCTION, VEHICLE 2 WAS TRAVELLING NORTH ON A SOUTHBOUND LANE. AS VEHICLE 2 ENTERED THE INTERSECTION, IT WAS STRUCK ON THE LEFT SIDE BY THE FRONT OF VEHICLE 1. BOTH VEHICLES WERE HEADED NORTH AFTER THE ACCIDENT. BOTH VEHICLES WERE TOWED DUE TO DAMAGE. THE DRIVER OF VEHICLE 2 AND THE PASSENGER OF VEHICLE 1 WERE INJURED IN THE ACCIDENT. A CHILD IN THE PASSENGER SEAT OF VEHICLE 1 RECEIVED SERIOUS INJURIES FROM THE AIRBAG.

01

PSU74

1996 Case Summary Form

CASE 195J

TYPE OF ACCIDENT: CAR-CAR/ANGLE COLLISION

B. VEHICLE PROFILE(S)

V e h. No	Class of Vehicle	Year/Make/ Model	Most Severe Damage Based on Vehicle Inspection		
			Damage Plane	Severity Descr.	Component Failure
1	VAN	95/PLY/VOYAGER	FRONT	MINOR	NONE
2	SUB COMPACT	90/EAGLE/TALON	LEFT	MINOR	NONE

01

PSU74

1996 Case Summary Form


CASE 195J

TYPE OF ACCIDENT: CAR-CAR/ANGLE COLLISION

C. PERSON PROFILE(S)

Most Severe Injury  
(TO BE COMPLETED BY ZONE CENTER)

V e h. No	Person Role	Seat Positon	Restraint Use	Body Region	Injury Type	A I S		Injury Source
1	DRIVER	L. FRONT	AIRBAG	ARM	FRACTURE	2	LEFT A	PILLAR
1	PASS.	R. FRONT	AIRBAG	SPINE	DISLOCATION	6	AIR	BAG
2	DRIVER	L. FRONT	L & S	SCALP	CONTUSION	1	ROOF	SIDE RAIL



**NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM**

Case Number—Stratum 195J

## CRASH DATA

- \* reference point and reference line relative to physical features present at the scene
- \* scaled documentation of all accident induced physical evidence
- \* scaled documentation of all roadside objects contacted
- \* scaled representations of the vehicle(s) at pre-impact, impact, and final rest based upon either:
  - a) physical evidence, or
  - b) reconstructed accident dynamics

	VEH. #1	VEH. #2	VEH. #3
Heading Angle	90	10	
Surface Type	Concrete		
Surface Condition	Wet	Wet	
Coefficient of Friction	.70	.70	
Grade (v/h) Measurement (between impact and final rest)	9/122	5/122	
Grade (v/h) Measurement (at location of rollover initiation)			
Grade (v/h) Measurement (at pre-crash location)	9/122	5/122	

Reference line: North edge of

[illegible]

# ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM

# ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM

PSU No. 74

Case Number—Stratum 1955



Indicate  
North



PSU No. 74

Case Number—Stratum 1955

Indicate  
North






# ACCIDENT COLLISION DIAGRAM

NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM

PSU No. 24

Case Number—Stratum 1955

Indicate  
North





## ACCIDENT FORM

1. Primary Sampling Unit Number 74

2. Case Number - Stratum 1953

### IDENTIFICATION

3. Number of General Vehicle  
Forms Submitted 02

4. Date of Accident  
(Month, Day, Year) 10/19/96

5. Time of Accident 1051

Code reported military time of accident.

NOTE: Midnight = 2400  
Unknown = 9999

### SPECIAL STUDIES - INDICATORS

Check (✓) each special study (SS15-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6.      SS15 Administrative Use 0

7.      SS16 Pedestrian Crash Data Study 0  
(Data for this special study available  
in a separate file.)

8.      SS17 Impact Fires 0

9.      SS18 Unsafe Driver Actions 0

10.      SS19 Run Off Road 0

### NUMBER OF EVENTS

11. Number of Recorded Events  
in This Accident 01

Code the number of events which occurred  
in this accident.

### ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object in the right columns.

Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. <u>0</u> <u>1</u>	13. <u>01</u>	14. <u>20</u>	15. <u>F</u>	16. <u>02</u>	17. <u>01</u>	18. <u>L</u>
19. <u>0</u> <u>2</u>	20. <u>    </u>	21. <u>    </u>	22. <u>    </u>	23. <u>    </u>	24. <u>    </u>	25. <u>    </u>
26. <u>0</u> <u>3</u>	27. <u>    </u>	28. <u>    </u>	29. <u>    </u>	30. <u>    </u>	31. <u>    </u>	32. <u>    </u>
33. <u>0</u> <u>4</u>	34. <u>    </u>	35. <u>    </u>	36. <u>    </u>	37. <u>    </u>	38. <u>    </u>	39. <u>    </u>
40. <u>0</u> <u>5</u>	41. <u>    </u>	42. <u>    </u>	43. <u>    </u>	44. <u>    </u>	45. <u>    </u>	46. <u>    </u>

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT



## CODES FOR CLASS OF VEHICLE

(00) Not a motor vehicle	(31) Large pickup truck (≤ 4,536 kgs GVWR)
(01) Subcompact/mini (wheelbase < 254 cm)	(38) Other pickup truck (≤ 4,536 kgs GVWR)
(02) Compact (wheelbase ≥ 254 but < 265 cm)	(39) Unknown pickup truck type (≤ 4,536 kgs GVWR)
(03) Intermediate (wheelbase ≥ 265 but < 278 cm)	(45) Other light truck (≤ 4,536 kgs GVWR)
(04) Full size (wheelbase ≥ 278 but < 291 cm)	(48) Unknown light truck type (≤ 4,536 kgs GVWR)
(05) Largest (wheelbase ≥ 291 cm)	(49) Unknown light vehicle type
(09) Unknown passenger car size	(50) School bus (excludes van based)(> 4,536 kgs GVWR)
(14) Compact utility vehicle	(58) Other bus (> 4,536 kgs GVWR)
(15) Large utility vehicle (≤ 4,536 kgs GVWR)	(59) Unknown bus type
(16) Utility station wagon (≤ 4,536 kgs GVWR)	(60) Truck (> 4,536 kgs GVWR)
(19) Unknown utility type	(67) Tractor without trailer
(20) Minivan (≤ 4,536 kgs GVWR)	(68) Tractor-trailer(s)
(21) Large van (≤ 4,536 kgs GVWR)	(78) Unknown medium/heavy truck type
(24) Van Based school bus (≤ 4,536 kgs GVWR)	(79) Unknown light/medium/heavy truck type
(28) Other van type (≤ 4,536 kgs GVWR)	(80) Motored cycle
(29) Unknown van type (≤ 4,536 kgs GVWR)	(90) Other vehicle
(30) Compact pickup truck (≤ 4,536 kgs GVWR)	(99) Unknown

## CODES FOR GENERAL AREA OF DAMAGE (GAD)

CDS APPLICABLE AND OTHER VEHICLES	(O) Not a motor vehicle	(R) Right side	(T) Top
	(N) Noncollision	(L) Left side	(U) Undercarriage
	(F) Front	(B) Back	(9) Unknown
TDC APPLICABLE VEHICLES	(O) Not a motor vehicle	(L) Left side	(C) Rear of cab
	(N) Noncollision	(B) Back of unit with cargo area (rear of trailer or straight truck)	(V) Front of cargo area
	(F) Front	(D) Back (rear of tractor)	(T) Top
	(R) Right side		(U) Undercarriage
			(9) Unknown

## CODES FOR VEHICLE NUMBER OR OBJECT CONTACTED

(01-30) — Vehicle Number		(57) Fence
Noncollision		(58) Wall
(31) Overturn — rollover (excludes end-over-end)		(59) Building
(32) Rollover — end-over-end		(60) Ditch or culvert
(33) Fire or explosion		(61) Ground
(34) Jackknife		(62) Fire hydrant
(35) Other intraunit damage (specify):		(63) Curb
(36) Noncollision injury		(64) Bridge
(38) Other noncollision (specify):		(68) Other fixed object (specify):
(39) Noncollision — details unknown		(69) Unknown fixed object
Collision With Fixed Object		Collision with Nonfixed Object
(41) Tree (≤ 10 cm in diameter)		(70) Passenger car, light truck, van, or other vehicle not in-transport
(42) Tree (> 10 cm in diameter)		(71) Medium/heavy truck or bus not in-transport
(43) Shrubbery or bush		(72) Pedestrian
(44) Embankment		(73) Cyclist or cycle
(45) Breakaway pole or post (any diameter)		(74) Other nonmotorist or conveyance
Nonbreakaway Pole or Post		(75) Vehicle occupant
(50) Pole or post (≤ 10 cm in diameter)		(76) Animal
(51) Pole or post (> 10 cm but ≤ 30 cm in diameter)		(77) Train
(52) Pole or post (> 30 cm in diameter)		(78) Trailer, disconnected in transport
(53) Pole or post (diameter unknown)		(79) Object fell from vehicle in-transport
(54) Concrete traffic barrier		(88) Other nonfixed object (specify):
(55) Impact attenuator		(89) Unknown nonfixed object
(56) Other traffic barrier (includes guardrail) (specify):		(98) Other event (specify):
		(99) Unknown event or object



## GENERAL VEHICLE FORM

1. Primary Sampling Unit Number 74

2. Case Number - Stratum 195J

3. Vehicle Number 01

### VEHICLE IDENTIFICATION

4. Vehicle Model Year 95  
Code the last two digits of the model year  
(99) Unknown

5. Vehicle Make (specify): 09  
Plymouth  
Applicable codes are found in your  
NASS Data Collection, Coding and  
Editing Manual.  
(99) Unknown

6. Vehicle Model (specify): 442  
Voyager  
Applicable codes are found in your  
NASS Data Collection, Coding and  
Editing Manual.  
(99) Unknown

7. Body Type 20  
Note: Applicable codes may be found on  
the back of this page. ✓

8. Vehicle Identification Number

2P4G425 [REDACTED]

Left justify; Slash zeros and letter Z (0 and Z)  
No VIN—Code all zeros  
Unknown—Code all nines

9. Vehicle Special Use (This Trip) 0

- (0) No special use  
(1) Taxi  
(2) Vehicle used as school bus  
(3) Vehicle used as other bus  
(4) Military  
(5) Police  
(6) Ambulance  
(7) Fire truck or car  
(8) Other (specify): \_\_\_\_\_  
(9) Unknown

### OFFICIAL RECORDS

10. Police Reported Vehicle Disposition 1  
(0) Not towed due to vehicle damage  
(1) Towed due to vehicle damage  
(9) Unknown

11. Police Reported Travel Speed 999  
Code to the nearest kmph (NOTE: 000 means  
less than 0.5 kmph)  
(160) 159.5 kmph and above  
(999) Unknown

99 mph X 1.6093 = 999 kmph

12. Speed Limit 064  
(000) No statutory limit  
Code posted or statutory speed limit in kmph  
(999) Unknown

40 mph X 1.6093 = 064 kmph

13. Police Reported Alcohol Presence For Driver 0  
(0) No alcohol present  
(1) Yes alcohol present  
(7) Not reported  
(8) No driver present  
(9) Unknown

14. Alcohol Test Result For Driver 96  
Code actual value (decimal implied  
before first digit—0.xx)  
(95) Test refused  
(96) None given  
(97) AC test performed, results unknown  
(98) No driver present  
(99) Unknown

Source: [REDACTED]

15. Police Reported Other Drug Presence For Driver 0  
(0) No other drug(s) present  
(1) Yes other drug(s) present  
(7) Not reported  
(8) No driver present  
(9) Unknown

16. Other Drug Specimen Test Result For Driver 0  
(0) No specimen test given  
(1) Drug(s) not found in specimen  
(2) Drug(s) found in specimen, (specify):  
(3) Specimen test given, results unknown or not  
obtained  
(8) No driver present  
(9) Unknown if specimen test given

17. Driver's Zip Code [REDACTED]  
(00001) Driver not a resident of U.S. or territories  
Code actual 5-digit zip code  
(99998) No driver present  
(99999) Unknown

18. Driver's Race/Ethnic Origin 1  
(1) White (non-Hispanic)  
(2) Black (non-Hispanic)  
(3) White (Hispanic)  
(4) Black (Hispanic)  
(5) American Indian, Eskimo or Aleutian  
(6) Asian or Pacific Islander  
(7) Other (specify): attorney

(8) No driver present  
(9) Unknown

# CODES FOR BODY TYPE

## CDS APPLICABLE VEHICLES

### Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): \_\_\_\_\_
- (09) Unknown automobile type

### Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

### Utility Vehicles ( $\leq 4,536$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Passport, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Hummer, Landcruiser, Rover, Scout, Yukon)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

### Van Based Light Trucks ( $\leq 4,536$ kgs GVWR)

- (20) Minivan (Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Vista, Aerostar, Windstar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Expo Wagon, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ( $\leq 4,536$  kgs GVWR)
- (23) Van based motorhome ( $\leq 4,536$  kgs GVWR)
- (24) Van based school bus ( $\leq 4,536$  kgs GVWR)
- (25) Van based other bus ( $\leq 4,536$  kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): \_\_\_\_\_
- (29) Unknown van type

### Light Conventional Trucks (Pickup style cab, $\leq 4,536$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500, T100)
- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

### Other Light Trucks ( $\leq 4,536$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

## OTHER VEHICLES

### Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): \_\_\_\_\_
- (59) Unknown bus type

### Medium/Heavy Trucks ( $> 4,536$ kgs GVWR)

- (60) Step van ( $> 4,536$  kgs GVWR)
- (61) Single unit straight truck ( $4,536$  kgs  $<$  GVWR  $\leq 8,845$  kgs)
- (62) Single unit straight truck ( $8,845$  kgs  $<$  GVWR  $\leq 11,793$  kgs)
- (63) Single unit straight truck ( $> 11,793$  kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

### Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): \_\_\_\_\_
- (89) Unknown motored cycle type

### Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

**PRECRASH ENVIRONMENTAL DATA**

19. Relation To Interchange Or Junction 2  
 (0) Non-interchange area and non-junction  
 (1) Interchange area related  
*Non-Interchange junctions*  
 (2) Intersection related  
 (3) Driveway, alley access related  
 (4) Other junction (specify) \_\_\_\_\_  
 (5) Unknown type of junction  
 (9) Unknown
20. Trafficway Flow 1  
 (0) Not physically divided (two way traffic)  
 (1) Divided trafficway-median strip without positive barrier  
 (2) Divided trafficway-median strip with positive barrier  
 (3) One way traffic  
 (9) Unknown
21. Number Of Travel Lanes 2  
 (1) One  
 (2) Two  
 (3) Three  
 (4) Four  
 (5) Five  
 (6) Six  
 (7) Seven or more  
 (9) Unknown
22. Roadway Alignment 1  
 (1) Straight  
 (2) Curve right  
 (3) Curve left  
 (9) Unknown
23. Roadway Profile 4 X  
 (1) Level  
 (2) Uphill grade (> 2%)  
 (3) Hill crest  
 (4) Downhill grade (> 2%)  
 (5) Sag  
 (9) Unknown
24. Roadway Surface Type 1  
 (1) Concrete  
 (2) Bituminous (asphalt)  
 (3) Brick or block  
 (4) Slag, gravel, or stone  
 (5) Dirt  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown
25. Roadway Surface Condition 3 X  
 (1) Dry  
 (2) Wet  
 (3) Snow or slush  
 (4) Ice  
 (5) Sand, dirt, or oil  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown
26. Light Conditions 1  
 (1) Daylight  
 (2) Dark  
 (3) Dark, but lighted  
 (4) Dawn  
 (5) Dusk  
 (9) Unknown
27. Atmospheric Conditions 0  
 (0) No adverse atmospheric-related driving conditions  
 (1) Rain  
 (2) Sleet/hail  
 (3) Snow  
 (4) Fog  
 (5) Rain and fog  
 (6) Sleet and fog  
 (7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): \_\_\_\_\_  
 (9) Unknown
28. Traffic Control Device 1  
 (0) No traffic control(s)  
 (1) Traffic control signal (not RR crossing)  
*Regulatory*  
 (2) Stop sign  
 (3) Yield sign  
 (4) School zone sign  
 (5) Other regulatory sign (specify): \_\_\_\_\_  
 (6) Warning sign (not RR crossing)  
 (7) Unknown sign  
 (8) Miscellaneous/other controls including RR controls (specify): \_\_\_\_\_  
 (9) Unknown
29. Traffic Control Device Functioning 2  
 (0) No traffic control device  
 (1) Traffic control device not functioning (specify): \_\_\_\_\_  
 (2) Traffic control device functioning properly  
 (9) Unknown

**PRECRASH DRIVER RELATED DATA****30. Driver's Distraction/Inattention To Driving**  
(Prior To Recognition Of Critical Event)

- (00) No driver present  
 (01) Attentive or not distracted  
 (02) Looked but did not see

*Distractions*

- (03) By other occupant(s), (specify): \_\_\_\_\_

- (04) By moving object in vehicle (specify): \_\_\_\_\_

- (05) While talking or listening to cellular phone (specify location and type of phone): \_\_\_\_\_

- (06) While dialing cellular phone (specify location and type of phone): \_\_\_\_\_

- (07) While adjusting climate controls

- (08) While adjusting radio, cassette, CD (specify): \_\_\_\_\_

- (09) While using other device/controls integral to vehicle (specify): \_\_\_\_\_

- (10) While using or reaching for device/object brought into vehicle (specify): \_\_\_\_\_

- (11) Sleepy or fell asleep

- (12) Distracted by outside person, object, or event (specify): \_\_\_\_\_

- (13) Eating or drinking

- (14) Smoking related

- (17) Distracted/inattentive, details unknown

- (98) Other, distraction (specify): \_\_\_\_\_

*Construction area*

- (99) Unknown

**31. Pre-Event Movement (Prior to Recognition of Critical Event)**

- (00) No driver present  
 (01) Going straight  
 (02) Decelerating in traffic lane  
 (03) Accelerating in traffic lane  
 (04) Starting in traffic lane  
 (05) Stopped in traffic lane  
 (06) Passing or overtaking another vehicle  
 (07) Disabled or parked in travel lane  
 (08) Leaving a parking position  
 (09) Entering a parking position  
 (10) Turning right  
 (11) Turning left  
 (12) Making a U-turn  
 (13) Backing up (other than for parking position)  
 (14) Negotiating a curve  
 (15) Changing lanes  
 (16) Merging  
 (17) Successful avoidance maneuver to a previous critical event  
 (97) Other (specify): \_\_\_\_\_  
 (99) Unknown

**32. Critical Precrash Event****THIS VEHICLE LOSS OF CONTROL DUE TO:**

- (01) Blow out or flat tire  
 (02) Stalled engine  
 (03) Disabling vehicle failure (e.g., wheel fell off) (specify): \_\_\_\_\_  
 (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): \_\_\_\_\_  
 (05) Poor road conditions (puddle, pot hole, ice, etc.) (specify): \_\_\_\_\_  
 (06) Traveling too fast for conditions  
 (08) Other cause of control loss (specify): \_\_\_\_\_  
 (09) Unknown cause of control loss

**THIS VEHICLE TRAVELLING**

- (10) Over the lane line on left side of travel lane  
 (11) Over the lane line on right side of travel lane  
 (12) Off the edge of the road on the left side  
 (13) Off the edge of the road on the right side  
 (14) End departure  
 (15) Turning left at intersection  
 (16) Turning right at intersection  
 (17) Crossing over (passing through) intersection  
 (18) This vehicle decelerating  
 (19) Unknown travel direction

**OTHER MOTOR VEHICLE IN LANE**

- (50) Other vehicle stopped  
 (51) Traveling in same direction with lower steady speed  
 (52) Traveling in same direction while decelerating  
 (53) Traveling in same direction with higher speed  
 (54) Traveling in opposite direction  
 (55) In crossover  
 (56) Backing  
 (59) Unknown travel direction of other motor vehicle in lane

**OTHER MOTOR VEHICLE ENCROACHING INTO LANE**

- (60) From adjacent lane (same direction)—over left lane line  
 (61) From adjacent lane (same direction)—over right lane line  
 (62) From opposite direction—over left lane line  
 (63) From opposite direction—over right lane line  
 (64) From parking lane  
 (65) From crossing street, turning into same direction  
 (66) From crossing street, across path  
 (67) From crossing street, turning into opposite direction  
 (68) From crossing street, intended path not known  
 (70) From driveway, turning into same direction  
 (71) From driveway, across path  
 (72) From driveway, turning into opposite direction  
 (73) From driveway, intended path not known  
 (74) From entrance to limited access highway  
 (78) Encroachment by other vehicle—details unknown

**PEDESTRIAN, PEDALCYCLIST, OR OTHER NONMOTORIST**

- (80) Pedestrian in roadway  
 (81) Pedestrian approaching roadway  
 (82) Pedestrian—unknown location  
 (83) Pedalcyclist or other nonmotorist in roadway (specify): \_\_\_\_\_  
 (84) Pedalcyclist or other nonmotorist approaching roadway, (specify): \_\_\_\_\_  
 (85) Pedalcyclist or other nonmotorist—unknown location (specify): \_\_\_\_\_

**OBJECT OR ANIMAL**

- (87) Animal in roadway  
 (88) Animal approaching roadway  
 (89) Animal—unknown location  
 (90) Object in roadway  
 (91) Object approaching roadway  
 (92) Object—unknown location  
 (98) Other critical precrash event (specify): \_\_\_\_\_  
 (99) Unknown

## 33. Attempted Avoidance Maneuver

- 03 04
- ↑  
from  
pav
- (00) No driver present
  - (01) No avoidance maneuver
  - (02) Braking (no lockup)
  - (03) Braking (lockup)
  - (04) Braking (lockup unknown)
  - (05) Releasing brakes
  - (06) Steering left
  - (07) Steering right
  - (08) Braking and steering left
  - (09) Braking and steering right
  - (10) Accelerating
  - (11) Accelerating and steering left
  - (12) Accelerating and steering right
  - (98) Other action (specify):

(99) Unknown

## 34. Pre-Impact Stability

- 2 X
- (0) No driver present
  - (1) Tracking
  - (2) Skidding longitudinally—rotation less than 30 degrees
  - (3) Skidding laterally—clockwise rotation
  - (4) Skidding laterally—counterclockwise rotation
  - (7) Other vehicle loss-of-control (specify):

(9) Precrash stability unknown

## 35. Pre-Impact Location

- 1
- (0) No driver present
  - (1) Stayed in original travel lane
  - (2) Stayed on roadway but left original travel lane
  - (3) Stayed on roadway, not known if left original travel lane
  - (4) Departed roadway
  - (5) Remained off roadway
  - (6) Returned to roadway
  - (7) Entered roadway
  - (9) Unknown

## 36. Accident Type

(Note: Applicable codes on back of this page)




















































(00) No impact

Code the number of the diagram that best describes the accident circumstance

(98) Other accident type (specify):

(99) Unknown

**STOP HERE IF GV07 DOES NOT EQUAL 01 - 49**

Category	Configuration	ACCIDENT TYPES (Includes Intent)				
I Single Driver	A Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN
	B Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN
	C Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER 16 SPECIFICS UNKNOWN
II Same Trafficway Same Direction	D Rear-End	 20 STOPPED 21, 22, 23	 22 SLOWER 24, 25, 26, 27	 24 DECEL. 28, 29, 30, 31	 26 AVOID COLLISION WITH VEH.	(EACH • 32) SPECIFICS OTHER (EACH • 33) SPECIFICS UNKNOWN
	E Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	(EACH • 42) SPECIFICS OTHER (EACH • 43) SPECIFICS UNKNOWN
	F Sideswipe Angle	 44 LATERAL MOVE	 46 LATERAL MOVE	 48 AVOID COLLISION WITH VEH.	 50 AVOID COLLISION WITH OBJECT	(EACH • 48) SPECIFICS OTHER (EACH • 49) SPECIFICS UNKNOWN
III Same Trafficway Opposite Direction	G Head-On	 50 LATERAL MOVE	 52 AVOID COLLISION WITH VEH.	 54 AVOID COLLISION WITH OBJECT	 56 AVOID COLLISION WITH VEH.	(EACH • 52) SPECIFICS OTHER (EACH • 53) SPECIFICS UNKNOWN
	H Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	(EACH • 54) SPECIFICS OTHER (EACH • 55) SPECIFICS UNKNOWN
	I Sideswipe Angle	 64 LATERAL MOVE	 66 LATERAL MOVE	 68 AVOID COLLISION WITH VEH.	 70 AVOID COLLISION WITH OBJECT	(EACH • 64) SPECIFICS OTHER (EACH • 65) SPECIFICS UNKNOWN
IV Change Trafficway Vehicle Turning	J Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 70 INITIAL SAME DIRECTIONS	 72 AVOID COLLISION WITH VEH.	 74 AVOID COLLISION WITH OBJECT	(EACH • 74) SPECIFICS OTHER (EACH • 75) SPECIFICS UNKNOWN
	K Turn Into Path	 76 TURN INTO SAME DIRECTION	 78 TURN INTO OPPOSITE DIRECTIONS	 80 AVOID COLLISION WITH VEH.	 82 AVOID COLLISION WITH OBJECT	(EACH • 76) SPECIFICS OTHER (EACH • 77) SPECIFICS UNKNOWN
V Intersecting Paths (Vehicle Damage)	L Straight Paths	 86 AVOID COLLISION WITH VEH.	 88 AVOID COLLISION WITH OBJECT	 90 AVOID COLLISION WITH VEH.	 92 AVOID COLLISION WITH OBJECT	(EACH • 86) SPECIFICS OTHER (EACH • 87) SPECIFICS UNKNOWN
VI Miscellaneous	M Backing Etc.	 92 BACKING VEH.	 94 OTHER VEH. OR OBJECT	 96 OTHER ACCIDENT TYPE	 98 UNKNOWN ACCIDENT TYPE	 100 NO IMPACT

**OCCUPANT RELATED**

37. Driver Presence in Vehicle 1  
 (0) Driver not present  
 (1) Driver present  
 (9) Unknown
38. Number of Occupants This Vehicle 02  
 (00-96) Code actual number of occupants for this vehicle  
 (97) 97 or more  
 (99) Unknown
39. Number of Occupant Forms Submitted 02

**AIR BAG RELATED**

40. Is this an AOPS Vehicle? 1  
 (0) No (includes unknown)  
 (1) Yes - researcher determined  
 (2) VIN determined air bag system  
 (3) VIN determined automatic (passive) belts  
 (4) VIN determined air bag and automatic (passive) belts
41. Air Bag(s) Deployment, First Seat Frontal 6  
 (0) Not equipped or not available  
 (1) No air bags deployed
- Single Air Bag Vehicle*  
 (2) Driver air bag deployed  
 (3) Driver air bag, unknown if deployed
- Multiple Air Bag Vehicle*  
 (4) Driver side only deployed  
 (5) Passenger side only deployed  
 (6) Driver and passenger side deployed  
 (7) Driver and passenger side unknown if deployed  
 (8) Air bag(s) deployed, details unknown  
 (9) Unknown
42. Air Bag(s) Deployment, Other Than First Seat Frontal 0  
 (0) Not equipped with an "other" air bag  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

Specify type of "other" air bag present: \_\_\_\_\_

**VEHICLE WEIGHT ITEMS**

43. Vehicle Curb Weight 1.56 0  
 Code weight to nearest 10 kilograms.  
 (045) Less than 454 kilograms  
 (612) 6,124 kilograms or more  
 (999) Unknown  
3,400 lbs X .4536 = 1,552 kgs  
 Source: 1995 \_\_\_\_\_

44. Vehicle Cargo Weight 0, 0 0 0  
 Code weight to nearest 10 kilograms.  
 (000) Less than 5 kilograms  
 (454) 4,536 kilograms or more  
 (999) Unknown  
 \_\_\_\_\_ lbs X .4536 = 0 0 0 kgs  
 Source: \_\_\_\_\_

**ROLLOVER DATA**

45. Rollover 00  
 (00) No rollover (no overturning)  
*Rollover (primarily about the longitudinal axis)*  
 (01-16) Code the number of quarter turns  
 (17) Rollover, 17 or more quarter turns (specify): \_\_\_\_\_  
 (98) Rollover--end-over-end (i.e., primarily about the lateral axis)  
 (99) Rollover (overturn), details unknown
46. Rollover Initiation Type 00  
 (00) No rollover  
 (01) Trip-over  
 (02) Flip-over  
 (03) Turn-over  
 (04) Climb-over  
 (05) Fall-over  
 (06) Bounce-over  
 (07) Collision with another vehicle  
 (08) Other rollover initiation type specify): \_\_\_\_\_  
 (98) Rollover--end-over-end  
 (99) Unknown rollover initiation type
47. Location of Rollover Initiation 0  
 (0) No rollover  
 (1) On roadway  
 (2) On shoulder--paved  
 (3) On shoulder--unpaved  
 (4) On roadside or divided trafficway median  
 (8) Rollover--end-over-end  
 (9) Unknown
48. Rollover Initiation Object Contacted 00  
 (Note: Applicable codes on back of page)
49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 0  
 (0) No rollover  
 (1) Wheels/tires  
 (2) Side plane  
 (3) End plane  
 (4) Undercarriage  
 (5) Other location on vehicle (specify): \_\_\_\_\_  
 (6) Non-contact rollover forces (specify): \_\_\_\_\_  
 (8) Rollover--end-over-end  
 (9) Unknown
50. Direction of Initial Roll 0  
 (0) No rollover  
 (1) Roll right - primarily about the longitudinal axis  
 (2) Roll left - primarily about the longitudinal axis  
 (8) Rollover--end-over-end  
 (9) Unknown roll direction



## CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

### Noncollision

- (31) Turn-over — fall-over
- (32) No rollover impact initiation (end-over-end)
- (34) Jackknife

### Collision With Fixed Object

- (41) Tree ( $\leq 10$  cm in diameter)
- (42) Tree ( $> 10$  cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment
- (45) Breakaway pole or post (any diameter)

### Nonbreakaway Pole or Post

- (50) Pole or post ( $\leq 10$  cm in diameter)
- (51) Pole or post ( $> 10$  cm but  $\leq 30$  cm in diameter)
- (52) Pole or post ( $> 30$  cm in diameter)
- (53) Pole or post (diameter unknown)
- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)  
(specify): \_\_\_\_\_

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): \_\_\_\_\_

- (69) Unknown fixed object \_\_\_\_\_

### Collision with Nonfixed Object

- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): \_\_\_\_\_
- (89) Unknown nonfixed object \_\_\_\_\_
- (98) Other event (specify): \_\_\_\_\_
- (99) Unknown event or object \_\_\_\_\_

**VERRIDE/UNDERRIDE (THIS VEHICLE)**51. Front Override/Underride (this Vehicle) 052. Rear Override/Underride (this Vehicle) 0

- (0) No override/underride, or not an end-to-end impact between two CDS applicable vehicles, and no medium/heavy truck or bus underride

*Override (see specific CDC)**[Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)]*

- (1) 1st CDC  
(2) 2nd CDC  
(3) Other not automated CDC (specify):  
\_\_\_\_\_

*Underride (see specific CDC)**[Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)]*

- (4) 1st CDC  
(5) 2nd CDC  
(6) Other not automated CDC (specify):  
\_\_\_\_\_

- (7) Medium/heavy truck or bus override (of any configuration)  
(9) Unknown

**HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V**

Values: (000)-(359) Code actual value  
(996) Non-horizontal impact  
(997) Noncollision  
(998) Impact with object  
(999) Unknown

53. Heading Angle For This Vehicle 09054. Heading Angle For Other Vehicle 000**RECONSTRUCTION DATA**55. Towed Trailing Unit 0

- (0) No towed unit  
(1) Yes—towed trailing unit  
(9) Unknown

56. Documentation of Trajectory Data for This Vehicle 1

- (0) No  
(1) Yes

57. Post Collision Condition of Tree or Pole (For Highest Delta V) 0

- (0) Not collision (for highest delta V) with tree or pole  
(1) Not damaged  
(2) Cracked/sheared  
(3) Tilted <45 degrees  
(4) Tilted ≥45 degrees  
(5) Uprooted tree  
(6) Separated pole from base  
(7) Pole replaced  
(8) Other (specify):  
\_\_\_\_\_

(9) Unknown

**ACCIDENT RECONSTRUCTION PROGRAMS HIGHEST DELTA V**58. Basis for Total (Resultant) Delta V (highest) 03

- (00) No vehicle inspection

*Delta V Calculated*

- (01) Reconstruction program-damage only routine  
(02) Reconstruction program-damage and trajectory routine  
(03) Missing vehicle algorithm

*Delta V Not Calculated*

- (04) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.

*All vehicles within scope (CDC applicable) of reconstruction program but one of the collision conditions is beyond the scope of the reconstruction program or other acceptable reconstruction technique, regardless of adequacy of damage data.*

- (05) Rollover  
(06) Other non-horizontal forces  
(07) Sideswipe type damage  
(08) Severe override  
(09) Yielding object  
(10) Overlapping damage  
(11) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available, (specify):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

(98) Other, (specify): \_\_\_\_\_

due to impact v<sup>2</sup> low  
hit on LF wheel

**COMPUTER GENERATED CRASH SEVERITY**59. Total Delta V Highest18 Nearest kmph (highest) 018           Nearest kmph (secondary)

(NOTE: 000 means less than 0.5 kmph)  
 (160) 159.5 kmph and above  
 (999) Unknown

60. Longitudinal Component of Delta V Highest-14 Nearest kmph (highest) -014           Nearest kmph (secondary)

(NOTE:   000 means greater than  
 -0.5 kmph and less than +0.5 kmph)  
 (±160) ±159.5 kmph and above  
 (  999) Unknown

61. Lateral Component of Delta V Highest-12 Nearest kmph (highest) -012           Nearest kmph (secondary)

(NOTE:   000 means greater than -0.5 kmph and  
 less than +0.5 kmph)  
 (±160) ±159.5 kmph and above  
 (  999) Unknown

62. Energy Absorption Highest40388 Nearest 100 joules (highest)           Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)  
 (9997) 999,650 joules or more  
 (9999) Unknown

63. Impact Speed Highest           Nearest kmph (highest) 998           Nearest kmph (secondary)

(NOTE: 000 means  
 less than 0.5 kmph)  
 (160) 159.5 kmph and above  
 (998) Trajectory algorithm not run  
 (999) Unknown

**DELTA V CONFIDENCE LEVEL**64. Confidence In Reconstruction Program Results (For Highest Delta V) 4 X

- (0) No reconstruction  
 (1) Collision fits model — results appear reasonable  
 (2) Collision fits model — results appear high  
 (3) Collision fits model — results appear low  
 (4) Borderline reconstruction — results appear reasonable

**OTHER SPEED ESTIMATE**65. Barrier Equivalent Speed Highest15.9 Nearest kmph (highest) 016           Nearest kmph (secondary)

(NOTE: 000 means  
 less than 0.5 kmph)  
 (160) 159.5 kmph and above  
 (999) Unknown

ESTIMATED DELTA V	INSPECTION TYPE
<p>66. Estimated Highest Delta V (Researcher Determined) <u>0</u> <u>3</u></p> <p>(0) Reconstruction Delta V coded</p> <p><i>Estimated Delta V</i></p> <p>(1) Less than 10 kmph (2) ≥ 10 kmph but &lt; 25 kmph (3) ≥ 25 kmph but &lt; 40 kmph (4) ≥ 40 kmph but &lt; 55 kmph (5) ≥ 55 kmph</p> <p><i>Other estimates of damage severity</i></p> <p>(6) Minor (7) Moderate (8) Severe (9) Unknown</p>	<p>67. Type of Vehicle Inspection <u>3</u></p> <p>(0) No inspection (1) Vehicle fully repaired-no damage evident (2) Partial inspection (specify): _____ (3) Complete inspection</p>
	<p><b>DELTA V EVENT NUMBER</b></p> <p>68. Delta V Event Number <u>01</u></p> <p>_____ Code the accident event sequence number that resulted in the Delta V that has been coded above for this vehicle</p> <p>(99) Unknown</p>
<p><b>*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV67 = 0), ***</b></p> <p><b>DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS</b></p> <p><b>*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***</b></p> <p><b>THE EXTERIOR VEHICLE, INTERIOR VEHICLE, OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.</b></p>	

## EXTERIOR VEHICLE FORM

**NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM**

1. Primary Sampling Unit Number	<u>74</u>	3. Vehicle Number	<u>01</u>
2. Case Number - Stratum	<u>1955</u>		

## VEHICLE IDENTIFICATION

VIN 2P4GH25 [REDACTED] Model Year 95  
Vehicle Make (specify): Plymouth Vehicle Model (specify): Voyager

## LOCATOR

Locate the end of the damage with respect to the vehicle's damaged center point or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	Whole front bumper	Whole front bumper	C1

### CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts. 452

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

[illegible]

# ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	<u>112.3</u>	inches	x 2.54	=	<u>285</u> cm
Overall Length	<u>178.1</u>	inches	x 2.54	=	<u>452</u> cm
Maximum Width	<u>22.</u>	inches	x 2.54	=	<u>183</u> cm
Curb Weight	<u>3333</u> <sup>100</sup>	pounds	x .4536	=	<u>          </u> kg
Average Track	<u>156</u>	inches	x 2.54	=	<u>          </u> cm
Front Overhang	<u>          </u>	inches	x 2.54	=	<u>          </u> cm
Rear Overhang	<u>          </u>	inches	x 2.54	=	<u>          </u> cm
Undeformed End Width	<u>          </u>	inches	x 2.54	=	<u>          </u> cm
Engine Size: cyl./displ.	<u>V6</u>	cc	x .001	=	<u>3.0</u> L
	<u>          </u>	CID	x .0164	=	<u>          </u> L

<b>TIRE—WHEEL DAMAGE</b> a. Rotation physically restricted      b. Tire deflated  RF <u>2</u> RF <u>2</u> LF <u>2</u> LF <u>2</u> RR <u>2</u> RR <u>2</u> LR <u>2</u> LR <u>2</u>		<b>ORIGINAL SPECIFICATIONS</b>  Wheelbase <u>285</u> cm Overall Length <u>452</u> cm Maximum Width <u>183</u> cm Curb Weight <u>1557</u> kg Average Track <u>61.4</u> cm Front Overhang <u>85</u> cm Rear Overhang <u>82</u> cm Undeformed End Width <u>177</u> cm Engine Size: cyl./displ. <u>v6 3.0</u> L		<b>WHEEL STEER ANGLES</b> (For locked front wheels or displaced rear axles only) RF $\pm$ <u>7</u> ° LF $\pm$ <u>7</u> ° RR $\pm$ <u>7</u> ° LR $\pm$ <u>7</u> ° Within $\pm$ 5 degrees	
(1) Yes (2) No (8) NA (9) Unk.				<b>DRIVE WHEELS</b> <input checked="" type="checkbox"/> FWD <input type="checkbox"/> RWD <input type="checkbox"/> 4WD	
<b>TYPE OF TRANSMISSION</b> <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Automatic <b>END SHIFT <math>\geq</math> 10 CM</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Approximate Cargo Weight <u>0</u> kg	

Hand-drawn sketches of a vehicle from four perspectives: front, rear, top, and side. The sketches include various measurements and labels.

**Front View:** Shows a width of 153. The bumper height is labeled as 38, with the text "Original Bumper height" next to it.

**Rear View:** Shows a width of 160. The bumper height is labeled as 38.

**Top View:** Shows the vehicle's footprint from above.

**Side View (Left):** Shows a length of 283. The bumper corner to stringline distance is labeled as 87. The text "POST-CRASH" is written above the length dimension.

**Side View (Right):** Shows a length of 288. The bumper corner to stringline distance is labeled as 82. The text "POST-CRASH" is written above the length dimension. Other labels include "mirrors missing" and "scuffs".

HS Form 435B (2n) (1/96)

**CODES FOR OBJECT CONTACTED**

(99) Unknown event or object

[illegible]



## COLLISION DEFORMATION CLASSIFICATION

## HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. <u>01</u>	5. <u>02</u>	6. <u>01</u> <del>12</del>	7. <u>F</u>	8. <u>D</u>	9. <u>E</u>	10. <u>W</u>	11. <u>01</u>

## Second Highest Delta "V"

12. \_\_\_\_\_ 13. \_\_\_\_\_ 14. \_\_\_\_\_ 15. \_\_\_\_\_ 16. \_\_\_\_\_ 17. \_\_\_\_\_ 18. \_\_\_\_\_ 19. \_\_\_\_\_

## CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

## HIGHEST DELTA "V"

20. L	21. C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	22. ± D
<u>177</u>	<u>019</u> <del>016</del>	<u>016</u> <del>015</del>	<u>014</u>	<u>012</u>	<u>009</u> <del>008</del>	<u>009</u> <del>006</del>	<u>+ 000</u>

## Second Highest Delta "V"

23. L	24. C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	25. ± D
_____	_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____	_____

## 26. Undeformed End Width

(Coded when highest severity impact is an end plane impact.)

Code to the nearest centimeter

(250) 250 centimeters or more

(998) No highest severity end plane impact

(999) Unknown

## 27. Direct Damage Width

(For highest severity impact)

Code to the nearest centimeter

(250) 250 centimeters or more

(999) Unknown

## 28. Original Wheelbase

Code to the nearest centimeter

(650) 650 centimeters or more

(999) Unknown

172.3 inches X 2.54 = 283 centimeters

## 29. Original Average Track Width

Code to the nearest centimeter

(185) 185 centimeters or more

(999) Unknown

61 inches X 2.54 = 156 centimeters

**FUEL SYSTEM**

30. Are CDCs Documented but Not Coded on The Automated File? 0  
 (0) No  
 (1) Yes
31. Researcher's Assessment of Vehicle Disposition 1  
 (0) Not towed due to vehicle damage  
 (1) Towed due to vehicle damage  
 (9) Unknown
32. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? 0  
 (0) No post manufacturer modifications  
 (1) Yes - post manufacturer modifications (specify): \_\_\_\_\_  
 \_\_\_\_\_  
 (Include photograph of CERTIFICATION PLACARD in case report)  
 (9) Unknown if vehicle is modified

**FIRE OCCURRENCE**

33. Fire Occurrence 0  
 (0) No fire  
 Yes, fire occurred  
 (1) Minor  
 (2) Major  
 (9) Unknown
34. Origin of Fire 0  
 (0) No fire  
 (1) Vehicle exterior (front, side, back, top)  
 (2) Exhaust system  
 (3) Fuel tank (and other fuel retention system parts)  
 (4) Engine compartment  
 (5) Cargo/trunk compartment  
 (6) Instrument panel  
 (7) Passenger compartment area  
 (8) Other location (specify): \_\_\_\_\_  
 (9) Unknown

35. Location of Fuel Tank-1 Filler Cap 4
36. Location of Fuel Tank-2 Filler Cap 0  
 (0) No fuel tank  
 (1) On back plane  
 (2) Aft of center of the rear wheels (rear axle) on left side plane  
 (3) Aft of center of the rear wheels (rear axle) on right side plane  
 (4) Forward of center of the rear wheels (rear axle) on left side plane  
 (5) Forward of center of the rear wheels (rear axle) on right side plane  
 (6) Over the center of the rear wheels (rear axle) on left side plane  
 (7) Over the center of the rear wheels (rear axle) on right side plane  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown

37. Type of Fuel Tank-1 1
38. Type of Fuel Tank-2 0  
 (0) No fuel tank (electrical vehicle)  
 (1) Metallic  
 (2) Non-metallic  
 (9) Unknown

39. Location of Fuel Tank-1 4
40. Location of Fuel Tank-2 0  
 (0) No fuel tank  
 (1) Aft of center of the rear wheels (rear axle) centered  
 (2) Aft of center of the rear wheels (rear axle) left side  
 (3) Aft of center of the rear wheels (rear axle) right side  
 (4) Forward of center of the rear wheels (rear axle) centered  
 (5) Forward of center of the rear wheels (rear axle) left side  
 (6) Forward of center of the rear wheels (rear axle) right side  
 (7) Over center of the rear wheels (rear axle)  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown

41. Damage to Fuel Tank-1 1
42. Damage to Fuel Tank-2 0  
 (0) No fuel tank  
 (1) No damage to fuel tank  
 (2) Deformed, no seam failure  
 (3) Deformed, with a seam failure  
 (4) Punctured  
 (5) Lacerated (ripped)  
 (6) Abraded (scraped)  
 (7) Filler neck separation from the fuel tank  
 (8) Other damage (specify): \_\_\_\_\_  
 (9) Unknown

43. Leakage Location of Fuel System-1

1

44. Leakage Location of Fuel System-2

0

(0) No fuel tank

(1) No fuel leakage

*Primary Area Of Leakage*

(2) Tank

(3) Filler neck

(4) Cap

(5) Lines/pump/filter

(6) Vent/emission recovery

(8) Other (specify): \_\_\_\_\_

(9) Unknown

45. Fuel Type-1

01

46. Fuel Type-2

00*Single Fuel Type*

(00) No fuel tank

(01) Gasoline

(02) Diesel

(03) CNG (Compressed Natural Gas)

(04) LPG (Liquid Petroleum Gas) also known as Propane

(05) LNG (Liquid Natural Gas)

(06) Methanol (M100 or M85)

(07) Ethanol (E100 or E85)

(08) Other (Hydrogen or others) (specify): \_\_\_\_\_

*Electric Powered or Electric/Solar Powered Vehicles*

(10) Lead Acid Battery

(11) Nickel-Iron Battery

(12) Nickel-Cadmium Battery

(13) Sodium Metal Chloride Battery

(14) Sodium Sulfur Battery

(18) Other (Specify): \_\_\_\_\_

(98) Other Hybrid (specify): \_\_\_\_\_

(99) Unknown fuel type

47. Is This Vehicle Equipped With More Than Two Fuel Tanks?

0

(0) No (one or two tanks only)

*Yes - More Than Two Tanks*(1) Yes -- no damage to any tank or filler cap and no fuel system leakage(2) Yes -- no damage to any tank or filler cap but there is fuel system leakage (specify leakage location): \_\_\_\_\_(3) Yes -- damage to an additional tank or filler cap and there is fuel system leakage (specify the following):

Type of tank \_\_\_\_\_

Tank location \_\_\_\_\_

Filler cap location \_\_\_\_\_

Tank damage \_\_\_\_\_

Location of leakage \_\_\_\_\_

Type of fuel \_\_\_\_\_

(9) Unknown if more than two tanks

**COMMENTS**

---

---

---

---

---

---

---

---

---

---

\*\*\* STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED \*\*\*

(GV10=0)

DO NOT COMPLETE THE INTERIOR VEHICLE FORM.



## INTERIOR VEHICLE FORM

1. Primary Sampling Unit Number

24

2. Case Number - Stratum

195 J

3. Vehicle Number

A 1

### INTEGRITY

4. Passenger Compartment Integrity

0 0

(00) No integrity loss

Yes, Integrity Was Lost Through

(01) Windshield

(02) Door (side)

(03) Door/hatch (back door)

(04) Roof

(05) Roof glass

(06) Side window

(07) Rear window (backlight)

(08) Roof and roof glass

(09) Windshield and door (side)

(10) Windshield and roof

(11) Side and rear window (side window and backlight)

(12) Windshield and side window

(13) Door and side window

(98) Other combination of above (specify):

(99) Unknown

Door, Tailgate or Hatch Opening

5. LF / 6. RF / 7. LR 0 8. RR / 9. TG/H /

(0) No door/gate/hatch

(1) Door/gate/hatch remained closed and operational

(2) Door/gate/hatch came open during collision

(3) Door/gate/hatch jammed shut

(8) Other (specify):

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision

(1) Door operational (no damage)

(2) Latch/striker failure due to damage

(3) Hinge failure due to damage

(4) Door structure failure due to damage

(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage

(6) Latch/striker and hinge failure due to damage

(8) Other failure (specify):

(9) Unknown

### GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 2 19. RR 2

20. BL 2 21. Roof 0 22. Other 2

(0) No glazing

(1) AS-1 — Laminated

(2) AS-2 — Tempered

(3) AS-3 — Tempered-tinted (original)

(4) AS-2 — Tempered-with after market tint

(5) AS-3 — Tempered-tinted (with additional after market tint)

(6) AS-14 — Glass/Plastic

(7) Glazing removed prior to accident

(8) Other (specify):

(9) Unknown

Window Precrash Glazing Status

23. WS / 24. LF 2 25. RF 3 26. LR 2 27. RR 2

28. BL / 29. Roof 0 30. Other /

(0) No glazing

(1) Fixed

(2) Closed

(3) Partially opened

(4) Fully opened

(7) Glazing removed prior to accident

(9) Unknown

Glazing Damage from Impact Forces

31. WS / 32. LF / 33. RF / 34. LR / 35. RR /

36. BL / 37. Roof 0 38. Other /

(0) No glazing

(1) No glazing damage from impact forces

(2) Glazing in place and cracked from impact forces

(3) Glazing in place and holed from impact forces

(4) Glazing out-of-place (cracked or not) and not holed from impact forces

(5) Glazing out-of-place and holed from impact forces

(6) Glazing disintegrated from impact forces

(7) Glazing removed prior to accident

(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 2 40. LF / 41. RF / 42. LR / 43. RR /

44. BL / 45. Roof 0 46. Other /

(0) No glazing

(1) No occupant contact to glazing

(2) Glazing contacted by occupant but no glazing damage

(3) Glazing in place and cracked by occupant contact

(4) Glazing in place and holed by occupant contact

(5) Glazing out-of-place (cracked or not) by occupant contact

(6) Glazing out-of-place by occupant contact and holed by occupant contact


(7) Glazing removed prior to accident

(8) Glazing disintegrated by occupant contact

(9) Unknown if contacted by occupant

# INTRUSION WORKSHEET

**NOTE: SKETCH INTRUDED AREAS**



LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters)			INTRUSION	DOMINANT CRUSH DIRECTION
		COMPARISON VALUE	—	INTRUDED VALUE	=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	
			—		=	

## OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

## INTRUDING COMPONENT

*Interior Components*

- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): \_\_\_\_\_

*Exterior Components*

- (30) Hood
- (31) Outside surface of this vehicle (specify): \_\_\_\_\_
- (32) Other exterior object in the environment (specify): \_\_\_\_\_
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): \_\_\_\_\_
- (99) Unknown

## LOCATION OF INTRUSION

## Front Seat

- (11) Left
- (12) Middle
- (13) Right

## Second Seat

- (21) Left
- (22) Middle
- (23) Right

## Third Seat

- (31) Left
- (32) Middle
- (33) Right

## Fourth Seat

- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) \_\_\_\_\_

(99) Unknown

## MAGNITUDE OF INTRUSION

- (1)  $\geq 3$  centimeters but  $< 8$  centimeters
- (2)  $\geq 8$  centimeters but  $< 15$  centimeters
- (3)  $\geq 15$  centimeters but  $< 30$  centimeters
- (4)  $\geq 30$  centimeters but  $< 46$  centimeters
- (5)  $\geq 46$  centimeters but  $< 61$  centimeters
- (6)  $\geq 61$  centimeters
- (7) Catastrophic
- (9) Unknown

## DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	—	DAMAGE VALUE	=	DEFORMATION
26	—	23	=	3
	—		=	
	—		=	
	—		=	

## STEERING COLUMN

## 87. Steering Column Type

- (1) Fixed column  
 (2) Tilt column  
 (3) Telescoping column  
 (4) Tilt and telescoping column  
 (8) Other column type (specify): \_\_\_\_\_

(9) Unknown

## 88. Tilt Steering Column Adjustment

- (0) No tilt steering column  
 (1) Full up  
 (2) Between full up and center  
 (3) Center  
 (4) Between center and full down  
 (5) Full down  
 (9) Unknown

## 89. Telescoping Steering Column Adjustment

- (0) No telescoping steering column  
 (1) Full back  
 (2) Between full back and midpoint  
 (3) Midpoint  
 (4) Between midpoint and full forward  
 (5) Full forward  
 (9) Unknown

## 90. Steering Rim/Spoke Deformation

Code actual measured

- deformation to the nearest centimeter  
 (00) No steering rim deformation  
 (01-14) Actual measured value in centimeters  
 (15) 15 centimeters or more  
 (98) Observed deformation cannot be measured  
 (99) Unknown

## 91. Location of Steering Rim/Spoke Deformation

- (00) No steering rim deformation


## Quarter Sections

- (01) Section A  
 (02) Section B  
 (03) Section C  
 (04) Section D



## Half Sections

- (05) Upper half of rim/spoke  
 (06) Lower half of rim/spoke  
 (07) Left half of rim/spoke  
 (08) Right half of rim/spoke



- (09) Complete steering wheel collapse  
 (10) Undetermined location  
 (99) Unknown

## INSTRUMENT PANEL

## 92. Odometer Reading

39.4 kilometers

Code to the nearest 1,000 kilometers

- (000) No odometer  
 (001) Less than 1,500 kilometers  
 (500) 499,500 kilometers or more  
 (999) Unknown

24.740 miles X 1.6093 = 39.8 kilometers

Source: \_\_\_\_\_

## 93. Instrument Panel Damage from Occupant Contact?

- (0) No  
 (1) Yes  
 (9) Unknown

## 94. Type of Knee Bolster Covering

- (0) No knee bolster  
 (1) Padded  
 (2) Rigid plastic  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown

## 95. Knee Bolsters Deformed from Occupant Contact?

- (0) No knee bolster  
 (1) No deformation  
 (2) Yes - deformation  
 (9) Unknown

## 96. Did Glove Compartment Door Open During Collision(s)?


- (0) No glove compartment door  
 (1) No - door did not open  
 (2) Yes - door opened  
 (9) Unknown

## 97. Adaptive (Assistive) Driving Equipment

- (0) No adaptive driving equipment  
 (1) Adaptive driving equipment installed (Check all that apply.)  
☐ Hand controls for braking/acceleration  
☐ Steering control devices (attached to OEM steering wheel)  
☐ Steering knob attached to steering wheel  
☐ Low effort power steering (unit or device)  
☐ Replacement steering wheel (i.e., reduced diameter)  
☐ Joy-stick steering controls  
☐ Wheelchair tie-downs  
☐ Modification to seat belts (specify): \_\_\_\_\_  
☐ Additional or relocated switches (specify): \_\_\_\_\_  
☐ Raised roof  
☐ Wall-mounted head rest (used behind wheelchair)  
☐ Other adaptive device (specify): \_\_\_\_\_

(9) Unknown






Fibers  
on belt  
NO stretching

## VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure).  
 Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.  
 Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

## POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	151	2	FACE ?	BLOOD deposit / 22cm x 15	1
B	170	2 ?	FACE ?	BLOOD STAIN	3
C	001	2	FACE/HAND	Smudge 64cm from Right A Pillar 21cm from Headset	1
D	001	2	FACE/HAND	Smudge 54cm from Right A Pillar 25cm from Headset	1
E	001	2	FACE/HAND	Smudge 34cm from Right A Pillar 11cm from Headset	1
F	001	2	FACE	NOSE mucus 40cm from Right A Pillar 5cm from Headset	1
G	001	2	UNK	UNK MATTER 39cm from Right A Pillar 1cm from Headset	3
H	103	2	UNK	Smudge 12cm long	3
I	185	2	BODY	Red Smudge 4cm long 27 from edge	1
J	185	2	UNK	Small TUE m flap 1cm long 21 from edge	3
K	003	2	UNK	BROWN fiber	3
L	201	2	FACE	NOSE mucus	1
M	205	2	UNK	BLUE fiber 40 from side rail 75 from Headset	3
N	205	UNK	UNK	fluid TRANSFER 75 from Headset	3

- FRONT 175
- (001) Windshield  
 (002) Mirror  
 (003) Sunvisor  
 (004) Steering wheel rim  
 (005) Steering wheel hub/spoke  
 (006) Steering wheel (combination of codes 004 and 005)  
 (007) Steering column, transmission selector lever, other attachment  
 (008) Cellular telephone or CB radio  
 (009) Add on equipment (e.g., tapedeck, air conditioner)  
 (010) Left instrument panel and below  
 (011) Center instrument panel and below  
 (012) Right instrument panel and below  
 (013) Glove compartment door  
 (014) Knee bolster  
 (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)  
 (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)  
 (017) Windshield reinforced by exterior object, (specify):  
 (019) Other front object (specify):

## 2 CODES FOR INTERIOR COMPONENTS

## LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests  
 (052) Left side hardware or armrest  
 (053) Left A (A1/A2)-pillar  
 (054) Left B-pillar  
 (055) Other left pillar (specify):  
 (056) Left side window glass  
 (057) Left side window frame  
 (058) Left side window sill  
 (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.  
 (060) Other left side object (specify):

## RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests  
 (102) Right side hardware or armrest  
 (103) Right A (A1/A2)-pillar  
 (104) Right B-pillar  
 (105) Other right pillar (specify):  
 (106) Right side window glass  
 (107) Right side window frame  
 (108) Right side window sill  
 (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.  
 (110) Other right side object (specify):

## INTERIOR

- (151) Seat, back support  
 (152) Belt restraint webbing/buckle  
 (153) Belt restraint B-pillar or door frame attachment point  
 (154) Other restraint system component (specify):  
 (155) Head restraint system  
 (160) Other occupants (specify):  
 (161) Interior loose objects  
 (162) Child safety seat (specify):  
 (163) Other interior object (specify):

## AIR BAG

- (170) Air bag-driver side  
 (175) Air bag compartment cover-driver side  
 (180) Air bag-passenger side  
 (185) Air bag compartment cover-passenger side  
 (190) Other air bag (specify):  
 (195) Other air bag compartment cover (specify):

## ROOF

- (201) Front header  
 (202) Rear header  
 (203) Roof left side rail  
 (204) Roof right side rail  
 (205) Roof or convertible top

## FLOOR

- (251) Floor (including toe pan)  
 (252) Floor or console mounted transmission lever, including console  
 (253) Parking brake handle  
 (254) Foot controls including parking brake

## REAR

- (301) Backlight (rear window)  
 (302) Backlight storage rack, door, etc.  
 (303) Other rear object (specify):

## ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration  
 (402) Steering control devices (attached to OEM steering wheel)  
 (403) Steering knob attached to steering wheel  
 (405) Replacement steering wheel (i.e., reduced diameter)  
 (406) Joy stick steering controls  
 (407) Wheelchair tie-downs  
 (408) Modification to seat belts, (specify):  
 (409) Additional or relocated switches, (specify):  
 (410) Raised roof  
 (411) Wall mounted head rest (used behind wheel chair)  
 (412) Other adaptive device (specify):

## CONFIDENCE LEVEL OF CONTACT POINT

- (1) Certain  
 (2) Probable  
 (3) Possible  
 (9) Unknown

# MANUAL RESTRAINTS

**NOTES:** Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a child safety seat is present, encode the data on the back of this page 11.

If the vehicle has automatic restraints available, encode the appropriate data on page 6.

		Left	Center	Right
FIRST	A-Availability	4		4
	B-Evidence of usage	4		4
	C-Used in this crash?	0		0
	D-Proper Use	0		0
	E-Failure Modes	0		0
	F-Anchorage Adjustment	2		4
SECOND	A-Availability	4		4
	B-Evidence of usage	4		0
	C-Used in this crash?	0		0
	D-Proper Use	0		0
	E-Failure Modes	0		0
	F-Anchorage Adjustment	1		1
OTHER	A-Availability	4	3	4
	B-Evidence of usage	0	0	0
	C-Used in this crash?	0	0	0
	D-Proper Use	0	0	0
	E-Failure Modes	0	0	0
	F-Anchorage Adjustment	1	0	1

## A-Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

### Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify): \_\_\_\_\_
- (9) Unknown

## B/C-Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify): \_\_\_\_\_

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify): \_\_\_\_\_
- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify): \_\_\_\_\_
- (99) Unknown if belt used

## D-Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

### Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): \_\_\_\_\_
- (8) Other improper use of manual belt system (specify): \_\_\_\_\_
- (9) Unknown

## E-Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): \_\_\_\_\_
- (6) Broken retractor
- (7) Combination of above (specify): \_\_\_\_\_
- (8) Other manual belt failure (specify): \_\_\_\_\_
- (9) Unknown

## F-Shoulder Belt Upper Anchorage Adjustment

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

### Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

**AUTOMATIC RESTRAINTS**

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

**AIR BAGS**

		Frontal Air Bags--Left Front	Frontal Air Bags--Right Front	Other Air Bag
F I R S T	Availability/Function	/	/	
	Deployment	/	/	
	Failure	/	/	

**Air Bag System Availability/Function**

- (0) Not equipped/not available  
(1) Air bag

*Non-functional*

- (2) Air bag disconnected (specify):  
\_\_\_\_\_  
(3) Air bag not reinstalled  
(9) Unknown

**Air Bag System Deployment  
(This Occupant Position)**

- (0) Not equipped/not available  
(1) Deployed during accident (as a result of impact)  
(2) Deployed inadvertently just prior to accident  
(3) Deployed, accident sequence undetermined  
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
(5) Unknown if deployed  
(7) Nondeployed  
(9) Unknown

**Are There Indications of Air Bag System Failure? (This Occupant Position)**

- (0) Not equipped/not available  
(1) No  
(2) Yes (specify):  
\_\_\_\_\_  
(9) Unknown

**AUTOMATIC BELTS**

		Left	Right
F I R S T	A-Availability/Function		
	B-Use		
	C-Type		
	D-Proper Use		
	E-Failure Modes		

**A-Automatic (Passive) Belt System Availability/Function**

- (0) Not equipped/not available  
(1) 2 point automatic belts  
(2) 3 point automatic belts  
(3) Automatic belts - type unknown

*Non-functional*

- (4) Automatic belts destroyed or rendered inoperative  
(9) Unknown

**B-Automatic (Passive) Belt System Use**

- (0) Not equipped/not available/destroyed or rendered inoperative  
(1) Automatic belt in use  
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)  
(3) Automatic belt use unknown  
(9) Unknown

**C-Automatic (Passive) Belt System Type**

- (0) Not equipped/not available  
(1) Non-motorized system  
(2) Motorized system  
(9) Unknown

**D-Proper Use of Automatic (Passive) Belt System**

- (0) Not equipped/not available/not used  
(1) Automatic belt used properly  
(2) Automatic belt used properly with child safety seat

*Automatic Belt Used Improperly*

- (3) Automatic shoulder belt worn under arm  
(4) Automatic shoulder belt worn behind back  
(5) Automatic belt worn around more than one person  
(6) Lap portion of automatic belt worn on abdomen  
(7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):  
\_\_\_\_\_

- (8) Other improper use of automatic belt system (specify):  
\_\_\_\_\_  
(9) Unknown

**E-Automatic (Passive) Belt Failure Modes During Accident**

- (0) Not equipped/not available/not in use  
(1) No automatic belt failure(s)  
(2) Torn webbing (stretched webbing not included)  
(3) Broken buckle or latchplate  
(4) Upper anchorage separated  
(5) Other anchorage separated (specify):  
\_\_\_\_\_  
(6) Broken retractor  
(7) Combination of above (specify):  
(8) Other automatic belt failure (specify):  
\_\_\_\_\_  
(9) Unknown

## FIRST SEAT FRONTAL AIR BAGS

**NOTES:** Encode the applicable data *for the driver and first seat passenger* in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
A-Type of air bag?	1	1
B-Flaps open at tear points?	2	2
C-Flaps damaged?	1	1
D-Air bag damaged?	1	1
E-Source of air bag damage	01	01
F-Air bag tethered?	1	2
G-Air bag have vent ports?	2	1
H-Other occupant contact air bag?	1	1
I-Occupant wearing eyewear?	1	1

### A-Type of Air Bag

- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

### B-Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?

- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### C-Were Air Bag Module Cover Flap(s) Damaged?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### D-Was There Damage To The Air Bag?

- (00) Not equipped/not available
- (01) Not damaged

#### Yes - Air Bag Damage

- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify):

- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

### E-Source of Air Bag Damage

- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify):
- (03) Object carried by occupant, (specify):
- (04) Adaptive/assistive controls, (specify):

- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify):

- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

### F-Was The Air Bag Tethered?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps): 2
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### G-Did The Air Bag Have Vent Ports?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports):
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### H-Was the Air Bag in this Occupant's Position Contacted by Another Occupant?


- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### I-Was This Occupant Wearing Eye-wear?


- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

## DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

## 1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)



## 2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)




## DRIVER AIR BAG SKETCHES (Cont'd)

### 3. DRIVER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width ( $W_U$ ) \_\_\_\_\_ width ( $W_L$ ) \_\_\_\_\_

height ( $H$ ) \_\_\_\_\_




### 4. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap

b. Lower Flap

width ( $W_U$ ) 18 width ( $W_L$ ) 18


height ( $H_U$ ) 7 height ( $H_L$ ) 7



### 5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

### 6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS


### 7. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS






## PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES

## 1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)




## 2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)



## PASSENGER AIR BAG SKETCHES (Cont'd)

### 3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W) 15  
height (H) 32



### 4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap


b. Lower Flap

width ( $W_U$ ) \_\_\_\_\_

width ( $W_L$ ) \_\_\_\_\_

height ( $H_U$ ) \_\_\_\_\_


height ( $H_L$ ) \_\_\_\_\_



### 5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

### 6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

### 7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



**"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES**

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON "OTHER" AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON "OTHER" AIR BAG (Back)

**"OTHER" AIR BAG SKETCHES (Cont'd)**

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS

**HEAD RESTRAINTS/SEAT EVALUATION**

**NOTES:** Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found on the next page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
<b>FIRST</b>	A-Head Restraint Type/Damage	1		1
	B-Seat Type	01		01
	C-Seat Orientation	1		1
	D-Seat Track Position	2		3
	E-Seat Back Incline Pre/Post Impact	14		23
	F-Seat Performance	1		1
<b>SECOND</b>	A-Head Restraint Type/Damage	0	0	
	B-Seat Type	03	03	
	C-Seat Orientation	1	1	
	D-Seat Track Position	01	01	
	E-Seat Back Incline Pre/Post Impact	1	1	
	F-Seat Performance	1	1	
<b>THIRD</b>	A-Head Restraint Type/Damage	0	0	0
	B-Seat Type	03	03	03
	C-Seat Orientation	1	1	1
	D-Seat Track Position	1	1	1
	E-Seat Back Incline Pre/Post Impact	1	1	1
	F-Seat Performance	1	1	1
<b>OTHER</b>	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			

**DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE  
(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)**

**HEAD RESTRAINTS/SEAT EVALUATION****A-Head Restraint Type/Damage by Occupant at This Occupant Position**

- (0) No head restraints
- (1) Integral — no damage
- (2) Integral — damaged during accident
- (3) Adjustable — no damage
- (4) Adjustable — damaged during accident
- (5) Add-on — no damage
- (6) Add-on — damaged during accident
- (8) Other
- Specify): \_\_\_\_\_
- (9) Unknown

**B-Seat Type (this Occupant Position)**

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Box mounted seat (i.e., van type)
- (10) Other seat type (specify): \_\_\_\_\_
- (99) Unknown

**C-Seat Orientation (this Occupant Position)**

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

**D-Seat Track Adjusted Position Prior To Impact**

- (0) Occupant not seated or no seat
- (1) Non-adjustable seat track

**Adjustable Seat Track**

- (2) Seat at forward most track position
- (3) Seat between forward most and middle track positions
- (4) Seat at middle track position
- (5) Seat between middle and rear most track positions
- (6) Seat at rear most track position
- (9) Unknown

**E-Seat Back Incline Prior and Post Impact**

- (00) Occupant not seated or no seat
- (01) Not adjustable

**Upright prior to impact**

- (11) Moved to completely rearward position
- (12) Moved to rearward midrange position
- (13) Moved to slightly rearward position
- (14) Retained pre-impact position
- (15) Moved to slightly forward position
- (16) Moved to forward midrange position
- (17) Moved to completely forward position

**Slightly reclined prior to impact**

- (21) Moved to completely rearward position
- (22) Moved to rearward midrange position
- (23) Retained pre-impact position
- (24) Moved to upright position
- (25) Moved to slightly forward position
- (26) Moved to forward midrange position
- (27) Moved to completely forward position




**Completely reclined prior to impact**

- (31) Retained pre-impact position
- (32) Moved to rearward midrange position
- (33) Moved to slightly rearward position
- (34) Moved to upright position
- (35) Moved to slightly forward position
- (36) Moved to forward midrange position
- (37) Moved to completely forward position

- (99) Unknown

**F-Seat Performance (this Occupant Position)**

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): \_\_\_\_\_
- (4) Seat tracks/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): \_\_\_\_\_
- (7) Combination of above (specify): \_\_\_\_\_
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

DESCRIBE ANY INDICATION OF

ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT

CONTACT PATTERN)

## CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

### 1. Type of Child Safety Seat

- (0) No child safety seat
- (1) Infant seat
- (2) Toddler seat
- (3) Convertible seat
- (4) Booster seat
- (7) Other type child safety seat (specify):  
\_\_\_\_\_
- (8) Unknown child safety seat type
- (9) Unknown if child safety seat used

### 2. Child Safety Seat Orientation

- (00) No child safety seat
- Designed for Rear Facing for This Age/Weight
- (01) Rear facing
- (02) Forward facing
- (08) Other orientation (specify):  
\_\_\_\_\_

- (09) Unknown orientation

Designed for Forward Facing for This Age/Weight

- (11) Rear facing
- (12) Forward facing
- (18) Other orientation (specify):  
\_\_\_\_\_

- (19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

- (21) Rear facing
- (22) Forward facing
- (28) Other orientation (specify):  
\_\_\_\_\_

- (29) Unknown orientation

- (99) Unknown if child safety seat used

### 3. Child Safety Seat Harness Usage

### 4. Child Safety Seat Shield Usage

- 5. Child Safety Seat Tether Usage
- Note: Options Below Are Used for Variables 3-5.
- (00) No child safety seat

Not Designed with Harness/Shield/Tether

- (01) After market harness/shield/tether added, not used
- (02) After market harness/shield/tether used
- (03) Child safety seat used, but no after market harness/shield/tether added
- (09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether

- (11) Harness/shield/tether not used
- (12) Harness/shield/tether used
- (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

- (21) Harness/shield/tether not used
- (22) Harness/shield/tether used
- (29) Unknown if harness/shield/tether used

- (99) Unknown if child safety seat used

- 6. Child Safety Seat Make/Model
- (Specify make/model and occupant number)

---



---



---



---

**EJECTION/ENTRAPMENT DATA**

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

**EJECTION** No [ ☒ ] Yes [ ☐ ]

Describe indications of ejection and body parts involved in partial ejection(s):

---



---



---



---



---

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

**Ejection**

- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, Unknown degree
- (9) Unknown

**Ejection Area**

- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear

**(7) Roof**

- (8) Other area (e.g., back of pickup, etc.) (specify):

(9) Unknown

**Ejection Medium**

- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify):

**(5) Integral structure**

- (8) Other medium (specify):

(9) Unknown

**Medium Status (Immediately Prior to Impact)**

- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

**ENTRAPMENT** No [ ☒ ] Yes [ ☐ ]

Describe entrapment mechanism: \_\_\_\_\_

---



---



---



---

Component(s): \_\_\_\_\_

(Note on vehicle interior sketch)





# OCCUPANT ASSESSMENT FORM

1. Primary Sampling Unit Number	<u>24</u>
2. Case Number - Stratum	<u>195J</u>
3. Vehicle Number	<u>01</u>
4. Occupant Number	<u>01</u>

## OCCUPANT'S CHARACTERISTICS

5. Occupant's Age	<u>49</u>
Code actual age at time of accident.	
(00) Less than one year old (specify by month):	
(97) 97 years and older	
(99) Unknown	
6. Occupant's Sex	<u>2</u>
(1) Male	
(2) Female-not reported pregnant	
(3) Female-pregnant-1st trimester(1st-3rd month)	
(4) Female-pregnant-2nd trimester(4th-6th month)	
(5) Female-pregnant-3rd trimester(7th-9th month)	
(6) Female-pregnant-term unknown	
(9) Unknown	
7. Occupant's Height	<u>999</u>
Code actual height to the nearest centimeter.	
(999) Unknown	
___ inches X 2.54 = <u>999</u> centimeters	
8. Occupant's Weight	<u>999</u>
Code actual weight to the nearest kilogram.	
(999) Unknown	
___ pounds X .4536 = <u>999</u> kilograms	
9. Occupant's Role	<u>1</u>
(1) Driver	
(2) Passenger	
(9) Unknown	

## OCCUPANT'S SEATING

10. Occupant's Seat Position	<u>11</u>
<i>Front Seat</i>	
(11) Left side	
(12) Middle	
(13) Right side	
(14) Other (specify):	
(15) On or in the lap of another occupant	
<i>Second Seat</i>	
(21) Left side	
(22) Middle	
(23) Right side	
(24) Other (specify):	
(25) On or in the lap of another occupant	
<i>Third Seat</i>	
(31) Left side	
(32) Middle	
(33) Right side	
(34) Other (specify):	
(35) On or in the lap of another occupant	
<i>Fourth Seat</i>	
(41) Left side	
(42) Middle	
(43) Right side	
(44) Other (specify):	
(45) On or in the lap of another occupant	
(97) In or on unenclosed area	
(98) Other seat (specify):	
(99) Unknown	
11. Occupant's Posture	<u>0</u>
(0) Normal posture	
<i>Abnormal posture</i>	
(1) Kneeling or standing on seat	
(2) Lying on or across seat	
(3) Kneeling, standing or sitting in front of seat	
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window	
(5) Sitting on a console	
(6) Lying back in a reclined seat position	
(7) Bracing with feet or hands on a surface in front of seat	
(8) Other abnormal posture (specify):	
(9) Unknown	

## EJECTION/ENTRAPMENT

12. Ejection 0

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area 0

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)  
(specify): \_\_\_\_\_
- (9) Unknown

14. Ejection Medium 0

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): \_\_\_\_\_
- (5) Integral structure
- (8) Other medium (specify): \_\_\_\_\_
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 0

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.  
(specify): \_\_\_\_\_
- (9) Unknown

17. Occupant Mobility 4

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or not oriented to time or place
- (2) Removed from vehicle due to perceived serious injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (8) Removed from vehicle for other reasons  
(specify): \_\_\_\_\_
- (9) Unknown

## BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

*Integral Belt Partially Destroyed*

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 00

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify):

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 0

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

*Belt Used Improperly*

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 0

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Manual Shoulder Belt Upper Anchorage Adjustment 2

- (0) No manual shoulder belt
- (1) No upper anchorage adjustment for manual shoulder belt

*Adjustable shoulder Belt Upper Anchorage*

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function 0

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

*Non-functional*

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use 0

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type 0

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

*Automatic Belt Used Improperly*

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):

(9) Unknown

## POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 0

- (0) None used  
 (1) Police did not indicate belt use  
 (2) Shoulder belt  
 (3) Lap belt  
 (4) Lap and shoulder belt  
 (5) Belt used, type not specified  
 (6) Child safety seat  
 (7) Automatic belt  
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 2

- (0) No air bag available  
 (1) Police did not indicate air bag availability/function  
 (2) Deployed  
 (3) Not deployed  
 (4) Unknown if deployed  
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☒ Vehicle inspection  
☐ Official injury data  
☐ Driver/occupant interview  
☐ Other (specify):

☐ Unknown if belt used

## AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System 1

- Availability/Function  
 (This Occupant Position)  
 (0) Not equipped/not available  
 (1) Air bag  
*Non-functional*  
 (2) Air bag disconnected (specify):  
 (3) Air bag not reinstalled  
 (9) Unknown

31. Frontal Air Bag System Deployment (This Occupant Position) 1

- (0) Not equipped/not available  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

32. Other Than First Seat Frontal Air Bag Availability/Function (This Occupant Position) 0

- (0) Not equipped/not available  
 (1) Air bag  
*Non-functional*  
 (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled  
 (9) Unknown

Specify type of "other" air bag present:

33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position) 0

- (0) Not equipped with an "other" air bag  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

34. Are There Indications of Air Bag System Failure? (This Occupant Position) 1

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify):  
 (9) Unknown

## FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 1

(0) Not equipped/not available

(1) No previous accidents

Yes

(2) Previous accident(s) without deployment(s)

(3) One previous accident with deployment

(4) More than one previous accident with at least one deployment

(8) Previous accidents, unknown deployment status

(9) Unknown

36. Type of Air Bag 1

(0) Not equipped/not available

(1) Original manufacturer installed system

(2) Retrofitted air bag

(3) Replacement air bag

(8) Unknown type of air bag

(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 1

(0) Not equipped/not available

(1) No prior maintenance

(2) Yes, prior maintenance (specify): \_\_\_\_\_

(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 01

(00) Not equipped/not available

Code the accident event sequence number that initiated the air bag deployment

(96) Deployed, unknown event

(97) Not deployed

(98) Unknown if deployed

(99) Unknown

39. CDC For Air Bag Deployment Impact 1

(0) Not equipped/not available

(1) Highest delta V

(2) Second highest delta V

(3) Other non-coded delta V (specify): \_\_\_\_\_

(6) Deployed, unknown event

(7) Not deployed

(8) Unknown if deployed

(9) Unknown

40. Longitudinal Component of Delta V For Air Bag + 996Deployment Impact - 014

(\_000) Not equipped/not available

Code the value of the delta V for the impact that initiated the air bag deployment

(\_996) Deployment, unknown longitudinal Delta V

(\_997) Not deployed

(\_998) Unknown if deployed

(\_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 2

(0) Not equipped/not available

(1) No

(2) Yes

(3) Deployed, unknown if flap(s) opened at designated tear points

(7) Not deployed

(8) Unknown if deployed

(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 1

(0) Not equipped/not available

(1) No

(2) Yes (specify): \_\_\_\_\_

(3) Deployed, unknown if air bag module cover flap(s) damaged

(7) Not deployed

(8) Unknown if deployed

(9) Unknown

43. Was There Damage To The Air Bag? 01

(00) Not equipped/not available

(01) Not damaged

Yes - Air Bag Damage

(02) Ruptured

(03) Cut

(04) Torn

(05) Holed

(06) Burned

(07) Abraded

(88) Other damage (specify): \_\_\_\_\_

(95) Damaged, details unknown

(96) Deployed, unknown if damaged

(97) Not deployed

(98) Unknown if deployed

(99) Unknown

**FIRST SEAT FRONTAL AIR BAG SYSTEM  
EVALUATION** *continued*44. Source of Air Bag Damage 01

- (00) Not equipped/not available  
 (01) Not damaged  
 (02) Object worn by occupant, (specify):

(03) Object carried by occupant, (specify):

(04) Adaptive/assistive controls, (specify):

- (05) Fire in vehicle  
 (06) Thermal burns  
 (07) Rescue or emergency efforts  
 (88) Other damage source (specify):

- (95) Damaged, unknown source  
 (96) Deployed, unknown if damaged  
 (97) Not deployed  
 (98) Unknown if deployed  
 (99) Unknown

45. Was The Air Bag Tethered? 1

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify number of tether straps):

- (3) Deployed, unknown if tethered  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

46. Did The Air Bag Have Vent Ports? 2

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify number of vent ports):

- (3) Deployed, unknown if vent ports present  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 1

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify):  
 (3) Deployed, unknown if other occupant contact to air bag  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

48. Was This Occupant Wearing Eye-wear? 4

- (0) Not air bag equipped/air bag not available  
 (1) No  
 (2) Eyeglasses/sunglasses  
 (3) Contact lenses  
 (4) Deployed, unknown if eyewear worn  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

**HEAD RESTRAINT AND SEAT EVALUATION**49. Head Restraint Type/Damage by Occupant at This Occupant Position 1

- (0) No head restraints  
 (1) Integral—no damage  
 (2) Integral—damaged during accident  
 (3) Adjustable—no damage  
 (4) Adjustable—damaged during accident  
 (5) Add-on—no damage  
 (6) Add-on—damaged during accident  
 (8) Other (specify):

(9) Unknown 09

50. Seat Type (this Occupant Position) 01

- (00) Occupant not seated or no seat  
 (01) Bucket  
 (02) Bucket with folding back  
 (03) Bench  
 (04) Bench with separate back cushions  
 (05) Bench with folding back(s)  
 (06) Split bench with separate back cushions  
 (07) Split bench with folding back(s)  
 (08) Pedestal (i.e., column supported)  
 (09) Box mounted seat (i.e., van type)  
 (10) Other seat type (specify):

(99) Unknown

51. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat  
 (1) Forward facing seat  
 (2) Rear facing seat  
 (3) Side facing seat (inward)  
 (4) Side facing seat (outward)  
 (8) Other (specify):

(9) Unknown 3

52. Seat Track Adjusted Position Prior To Impact 2

- (0) Occupant not seated or no seat  
 (1) Non-adjustable seat track

*Adjustable Seat Track*

- (2) Seat at forward most track position  
 (3) Seat between forward most and middle track positions  
 (4) Seat at middle track position  
 (5) Seat between middle and rear most track positions  
 (6) Seat at rear most track position  
 (9) Unknown

**HEAD RESTRAINT AND SEAT EVALUATION** *continued*53. Seat Back Incline Prior and Post Impact 14

(00) Occupant not seated or no seat

(01) Not adjustable

***Upright prior to impact***

(11) Moved to completely rearward position

(12) Moved to rearward midrange position


(13) Moved to slightly rearward position

(14) Retained pre-impact position

(15) Moved to slightly forward position

(16) Moved to forward midrange position

(17) Moved to completely forward position

***Slightly reclined prior to impact***

(21) Moved to completely rearward position

(22) Moved to rearward midrange position


(23) Retained pre-impact position

(24) Moved to upright position

(25) Moved to slightly forward position

(26) Moved to forward midrange position

(27) Moved to completely forward position

***Completely reclined prior to impact***

(31) Retained pre-impact position

(32) Moved to rearward midrange position


(33) Moved to slightly rearward position

(34) Moved to upright position

(35) Moved to slightly forward position

(36) Moved to forward midrange position

(37) Moved to completely forward position



(99) Unknown

54. Seat Performance (this Occupant Position) 1

(0) Occupant not seated or no seat

(1) No seat performance failure(s)

(2) Seat adjusters failed

(3) Seat back folding locks or "seat back" failed  
(specify): \_\_\_\_\_

(4) Seat track/anchors failed

(5) Deformed by impact of occupant

(6) Deformed by passenger compartment  
intrusion, (specify): \_\_\_\_\_

(7) Combination of above (specify): \_\_\_\_\_

(8) Other (specify): \_\_\_\_\_

(9) Unknown

## CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

000

(000) No child safety seat

Applicable codes are found in your NASS CDS  
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

0

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

00

(00) No child safety seat

*Designed for Rear Facing for This Age/Weight*

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

*Designed For Forward Facing for This Age/Weight*

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This  
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

00

59. Child Safety Seat Shield Usage

00

60. Child Safety Seat Tether Usage

00Note: Options below applicable to  
Variables OA58-OA60.

(00) No child safety seat

*Not Designed With Harness/Shield/Tether*(01) After market harness/shield/tether  
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market  
harness/shield/tether added(09) Unknown if harness/shield/tether  
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

*Unknown If Designed With Harness/Shield/Tether*

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used



**INJURY CONSEQUENCES**61. Injury Severity (Police Rating) 0

- (0) O - No injury  
 (1) C - Possible injury  
 (2) B - Nonincapacitating injury  
 (3) A - Incapacitating injury  
 (4) K - Killed  
 (5) U - Injury, severity unknown  
 (6) Died prior to accident  
 (9) Unknown

62. Treatment - Mortality 6

- (0) No treatment  
 (1) Fatal  
 (2) Fatal - ruled disease (specify):  
 \_\_\_\_\_

*Nonfatal*

- (3) Hospitalization  
 (4) Transported and released  
 (5) Treatment at scene - nontransported  
 (6) Treatment later  
 (7) Treatment - other (specify):  
 \_\_\_\_\_  
 (8) Transported to a medical facility-unknown if treated  
 (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 5

- (0) Not treated at a medical facility  
 (1) Trauma center  
 (2) Hospital  
 (3) Medical clinic  
 (4) Physician's office  
 (5) Treatment later at medical facility  
 (8) Other (specify):  
 \_\_\_\_\_

(9) Unknown

64. Hospital Stay 00

- (00) Not Hospitalized  
 \_\_\_\_\_ Code the number of days (up through 60) that the occupant stayed in hospital.  
 (61) 61 days or more  
 (99) Unknown

65. Working Days Lost 00

- \_\_\_\_\_ Code the number of days (up through 60) that the occupant lost from work due to the accident  
 (00) No working days lost  
 (61) 61 days or more  
 (62) Fatally injured  
 (97) Not working prior to accident  
 (99) Unknown

**EMERGENCY RESPONSE INFORMATION**

## EMS Notification

- (1) Not notified  
 (2) Notified  
 (9) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Notification Time (first unit)

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Arrival Time (first unit)

(9998) EMS cancelled or did not arrive

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Departure Time To

Treatment Facility (transporting unit)

(9997) EMS arrived, provided treatment, but did not transport

(9998) EMS arrived, but was not used

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Arrival Time At

Treatment Facility

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Type

- (01) Fire department  
 (02) Rescue squad  
 (03) Police department  
 (04) Trauma unit  
 (05) Disaster unit  
 (06) Ambulance service unit  
 (07) Hospital  
 (08) Mortuaries/funeral homes  
 (98) Other, specify: \_\_\_\_\_  
 (99) Unknown

FIRST UNIT

TRANSPORTING UNIT

ROAD VEHICLE

AIR VEHICLE

## EMS Care

- (01) No care administered  
 (02) First aid  
 (03) Resuscitation  
 (04) CPR  
 (05) Emergency cardiac care  
 (06) Life support system monitoring (blood pressure, pulse rate, respiration, EKG)  
 (07) Emergency burn care  
 (08) Combination of above, specify: \_\_\_\_\_  
 (98) Other, specify: \_\_\_\_\_  
 (99) Unknown

ON-SCENE

DURING TRANSPORT

ROAD VEHICLE

AIR VEHICLE

**STOP WORK HERE VARIABLES 66-74 TO BE CODED BY THE ZONE CENTER**

**TO BE CODED BY THE ZONE CENTER****INJURY CONSEQUENCES****66. Time to Death**

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)  
 (00) Not fatal  
 (96) Fatal - ruled disease  
 (99) Unknown

00**67. 1st Medically Reported Cause of Death**00**68. 2nd Medically Reported Cause of Death**00**69. 3rd Medically Reported Cause of Death**00

Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death  
 (00) Not fatal or no additional causes  
 (96) Mode of death given but specific injuries are not linked to cause of death. (specify):  
 (97) Other result (includes fatal ruled disease) (specify):  
 (99) Unknown

**70. Number of Recorded Injuries for This Occupant**01

Code the actual number of injuries recorded for this occupant.  
 (00) No recorded injuries  
 (97) Injured, details unknown  
 (99) Unknown if injured

**TRAUMA DATA****71. Glasgow Coma Scale (GCS) Score (at Medical Facility)**02

- (00) Not injured
- (01) Injured - not treated at medical facility
- (02) No GCS Score at medical facility
- (03-15) Code the actual value of the initial GCS Score recorded at medical facility.
- (97) Injured, details unknown
- (99) Unknown if injured

**72. Was the Occupant Given Blood?**1

- (1) No - blood not given
- (2) Yes - blood given (specify units):
- (9) Unknown if blood given

**73. Arterial Blood Gases (ABG) - HCO<sub>3</sub>**01

- (00) Not injured
- (01) Injured, ABGs not measured or reported
- (02-50) Code the actual value of the HCO<sub>3</sub>
- (96) ABGs reported, HCO<sub>3</sub> unknown
- (97) Injured, details unknown
- (99) Unknown if injured

**BELT USE DETERMINATION****74. Primary Source of Belt Use Determination**1

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Vehicle inspection
- (2) Official injury data
- (3) Driver/occupant interview
- (8) Other (specify):
- (9) Unknown if belt used



## OCCUPANT INJURY FORM

1. Primary Sampling Unit Number	<u>74</u>	3. Vehicle Number	<u>01</u>
2. Case Number - Stratum	<u>1957</u>	4. Occupant Number	<u>01</u>

### INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. <u>3</u>	6. <u>7</u>	7. <u>5</u>	8. <u>28</u>	9. <u>02</u>	10. <u>2</u>	11. <u>2</u>	12. <u>053</u>	13. <u>2</u>	14. <u>1</u>	15. <u>00</u>
2nd	16. ____	17. ____	18. ____	19. ____	20. ____	21. ____	22. ____	23. ____	24. ____	25. ____	26. ____
3rd	27. ____	28. ____	29. ____	30. ____	31. ____	32. ____	33. ____	34. ____	35. ____	36. ____	37. ____
4th	38. ____	39. ____	40. ____	41. ____	42. ____	43. ____	44. ____	45. ____	46. ____	47. ____	48. ____
5th	49. ____	50. ____	51. ____	52. ____	53. ____	54. ____	55. ____	56. ____	57. ____	58. ____	59. ____
6th	60. ____	61. ____	62. ____	63. ____	64. ____	65. ____	66. ____	67. ____	68. ____	69. ____	70. ____
7th	71. ____	72. ____	73. ____	74. ____	75. ____	76. ____	77. ____	78. ____	79. ____	80. ____	81. ____
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____
10th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____

# OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90					Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
		Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity					
11th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
12th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
13th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
14th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
15th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
16th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
17th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
18th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
19th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
20th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
21st	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
22nd	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
23rd	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
24th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
25th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —

Body Region	Specific Anatomic Structure	Level of Injury	Aspect
(1) Head		Specific injuries are assigned consecutive two-digit numbers beginning with 02.	(1) Right
(2) Face			(2) Left
(3) Neck	<u>Vessels, Nerves, Organs, Bones, Joints</u> are assigned consecutive two digit numbers beginning with 02.		(3) Bilateral
(4) Thorax			(4) Central
(5) Abdomen			(5) Anterior
(6) Spine			(6) Posterior
(7) Upper Extremity			(7) Superior
(8) Lower Extremity			(8) Inferior
(9) Unspecified			(9) Unknown
	The exceptions to this rule apply to:		(0) Whole region
<b>Type of Anatomic Structure</b>	<b><u>Whole Area</u></b>		
	(02) Skin - Abrasion		
	(04) Skin - Contusion		
	(06) Skin - Laceration		
	(08) Skin - Avulsion		
(1) Whole Area	(10) Amputation		
(2) Vessels	(20) Burn		
(3) Nerves	(30) Crush		
(4) Organs (includes Muscles/ligaments)	(40) Degloving		
(5) Skeletal (includes joints)	(50) Injury - NFS		
(6) Head - LOC	(90) Trauma, other than mechanical		
(9) Skin			
	<b><u>Head - LOC</u></b>		
	(02) Length of LOC		
	(04) Level		
	(06) of		
	(08) Consciousness		
	(10) Concussion		
	<b><u>Spine</u></b>		
	(02) Cervical		
	(04) Thoracic		
	(06) Lumbar		
		<b>Abbreviated Injury Scale</b>	
		(1) Minor Injury	
		(2) Moderate Injury	
		(3) Serious Injury	
		(4) Severe Injury	
		(5) Critical Injury	
		(6) Maximum (untreatable)	
		(7) Injured, unknown severity	

## INJURY SOURCE

### CONFIDENCE LEVEL

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

(5) Lay coroner report  
(6) E.M.S. personnel  
(7) Interviewee  
(8) Other source (specify):  
(9) Police

- (1) Certain  
(2) Probable  
(3) Possible  
(9) Unknown

- (1) Direct contact injury  
(2) Indirect contact injury  
(3) Noncontact injury  
(7) Injured, unknown source

## INJURY SOURCES

### FRONT

- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column, transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment (e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object (specify): \_\_\_\_\_

- (019) Other front object (specify): \_\_\_\_\_

### LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): \_\_\_\_\_
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): \_\_\_\_\_

### RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests

- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): \_\_\_\_\_
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): \_\_\_\_\_

### INTERIOR

- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): \_\_\_\_\_
- (155) Head restraint system
- (160) Other occupants (specify): \_\_\_\_\_
- (161) Interior loose objects
- (162) Child safety seat (specify): \_\_\_\_\_
- (163) Other interior object (specify): \_\_\_\_\_

### AIR BAG

- (170) Air bag-driver side
- (171) Air bag-driver side and eyewear
- (172) Air bag-driver side and jewelry
- (173) Air bag-driver side and object held
- (174) Air bag-driver side and object in mouth
- (175) Air bag compartment cover-driver side
- (176) Air bag compartment cover-driver side and eyewear
- (177) Air bag compartment cover-driver side and jewelry
- (178) Air bag compartment cover-driver side and object held
- (179) Air bag compartment cover-driver side and object in mouth
- (180) Air bag-passenger side
- (181) Air bag-passenger side and eyewear
- (182) Air bag-passenger side and jewelry

- (183) Air bag-passenger side and object held
- (184) Air bag-passenger side and object in mouth
- (185) Air bag compartment cover-passenger side
- (186) Air bag compartment cover-passenger side and eyewear
- (187) Air bag compartment cover-passenger side and jewelry
- (188) Air bag compartment cover-passenger side and object held
- (189) Air bag compartment cover-passenger side and object in mouth
- (190) Other air bag (specify) \_\_\_\_\_
- (195) Other air bag compartment cover (specify) \_\_\_\_\_

### ROOF

- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top
- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

### REAR

- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): \_\_\_\_\_

### ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): \_\_\_\_\_
- (409) Additional or relocated switches, (specify): \_\_\_\_\_
- (410) Raised roof

- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): \_\_\_\_\_

### EXTERIOR of OCCUPANT'S VEHICLE

- (451) Hood
- (452) Outside hardware (e.g., outside mirror, antenna)
- (453) Other exterior surface or tires (specify): \_\_\_\_\_
- (454) Unknown exterior objects

### EXTERIOR OF OTHER MOTOR VEHICLE

- (501) Front bumper
- (502) Hood edge
- (503) Other front of vehicle (specify): \_\_\_\_\_
- (504) Hood
- (505) Hood ornament
- (506) Windshield, roof rail, A-pillar
- (507) Side surface
- (508) Side mirrors
- (509) Other side protrusions (specify): \_\_\_\_\_
- (510) Rear surface
- (511) Undercarriage
- (512) Tires and wheels
- (513) Other exterior of other motor vehicle (specify): \_\_\_\_\_
- (514) Unknown exterior of other motor vehicle

### OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (551) Ground
- (598) Other vehicle or object (specify): \_\_\_\_\_
- (599) Unknown vehicle or object

### NONCONTACT INJURY

- (601) Fire in vehicle
- (602) Flying glass
- (603) Other noncontact injury source (specify): \_\_\_\_\_
- (604) Air bag exhaust gases
- (697) Injured, unknown source

# OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Restrained?

☐ No

☐ Yes

Blood Alcohol Level  
(mg/dl)

BAL = ?

Glasgow Coma  
Scale Score

GCSS = 02

Units of Blood  
Given

Units = 0



Arterial Blood Gases

pH =     

PO<sub>2</sub> =     


PCO<sub>2</sub> =     

HCO<sub>3</sub> =     



## OFFICIAL INJURY DATA — SKELETAL INJURIES



Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





## OFFICIAL INJURY DATA – INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





# OCCUPANT ASSESSMENT FORM

1. Primary Sampling Unit Number 24

2. Case Number - Stratum 195J

3. Vehicle Number 01

4. Occupant Number 02

## OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 06

Code actual age at time of accident.

(00) Less than one year old (specify by month):

(97) 97 years and older

(99) Unknown

6. Occupant's Sex 1

(1) Male

(2) Female-not reported pregnant

(3) Female-pregnant-1st trimester(1st-3rd month)

(4) Female-pregnant-2nd trimester(4th-6th month)

(5) Female-pregnant-3rd trimester(7th-9th month)

(6) Female-pregnant-term unknown

(9) Unknown

7. Occupant's Height 132

Code actual height to the nearest  
centimeter.

(999) Unknown

52 inches X 2.54 = 132 centimeters

8. Occupant's Weight 025

Code actual weight to the nearest  
kilogram.

(999) Unknown

55 pounds X .4536 = 025 kilograms

9. Occupant's Role 2

(1) Driver

(2) Passenger

(9) Unknown

## OCCUPANT'S SEATING

10. Occupant's Seat Position 13

*Front Seat*

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify):

(15) On or in the lap of another occupant

*Second Seat*

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify):

(25) On or in the lap of another occupant

*Third Seat*

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify):

(35) On or in the lap of another occupant

*Fourth Seat*

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify):

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify):

(99) Unknown

11. Occupant's Posture 0

(0) Normal posture

*Abnormal posture*

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with

another occupant or to look out a rear  
window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in  
front of seat

(8) Other abnormal posture (specify):

(9) Unknown

## EJECTION/ENTRAPMENT

12. Ejection 0

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area 0

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)  
(specify): \_\_\_\_\_
- (9) Unknown

14. Ejection Medium 0

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): \_\_\_\_\_
- (5) Integral structure
- (8) Other medium (specify): \_\_\_\_\_
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 0

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.  
(specify): \_\_\_\_\_
- (9) Unknown

17. Occupant Mobility 1

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or not oriented to time or place
- (2) Removed from vehicle due to perceived serious injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (8) Removed from vehicle for other reasons  
(specify): \_\_\_\_\_
- (9) Unknown

## BELT SYSTEM FUNCTION

18. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

*Integral Belt Partially Destroyed*

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify):

(9) Unknown

19. Manual (Active) Belt System Use 00

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify):

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used—type unknown
- (08) Other belt used (specify):

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat—type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

20. Proper Use of Manual (Active) Belts 0

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

*Belt Used Improperly*

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

21. Manual (Active) Belt Failure Modes During Accident 0

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

(6) Broken retractor

(7) Combination of above (specify):

(8) Other manual belt failure (specify):

(9) Unknown

22. Manual Shoulder Belt Upper Anchorage Adjustment 4

- (0) No manual shoulder belt
- (1) No upper anchorage adjustment for manual shoulder belt

*Adjustable shoulder Belt Upper Anchorage*

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

23. Automatic (Passive) Belt System Availability/Function 0

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

*Non-functional*

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

24. Automatic (Passive) Belt System Use 0

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):
- (3) Automatic belt use unknown
- (9) Unknown

25. Automatic (Passive) Belt System Type 0

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

26. Proper Use of Automatic (Passive) Belt System 0

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

*Automatic Belt Used Improperly*

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):

(9) Unknown

27. Automatic (Passive) Belt Failure Modes During Accident 0

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

(6) Broken retractor

(7) Combination of above (specify):

(8) Other automatic belt failure (specify):

(9) Unknown

## POLICE REPORTED RESTRAINT USE

28. Police Reported Belt Use 0

- (0) None used  
 (1) Police did not indicate belt use  
 (2) Shoulder belt  
 (3) Lap belt  
 (4) Lap and shoulder belt  
 (5) Belt used, type not specified  
 (6) Child safety seat  
 (7) Automatic belt  
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

29. Police Reported Air Bag Availability/Function 2

- (0) No air bag available  
 (1) Police did not indicate air bag availability/function  
 (2) Deployed  
 (3) Not deployed  
 (4) Unknown if deployed  
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- ☒ Vehicle inspection  
☐ Official injury data  
☐ Driver/occupant interview  
☐ Other (specify):

☐ Unknown if belt used

## AIR BAG SYSTEM FUNCTION

30. Frontal Air Bag System 1

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available  
 (1) Air bag

*Non-functional*

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled  
 (9) Unknown

31. Frontal Air Bag System Deployment 1

(This Occupant Position)

- (0) Not equipped/not available  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

32. Other Than First Seat Frontal Air Bag 0

Availability/Function

(This Occupant Position)

- (0) Not equipped/not available  
 (1) Air bag

*Non-functional*

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled  
 (9) Unknown

*Specify type of "other" air bag present:*

33. Air Bag(s) Deployment, Other Than First 0

Seat Frontal (This Occupant Position)

- (0) Not equipped with an "other" air bag  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

34. Are There Indications of Air Bag System 1

Failure?

- (This Occupant Position)  
 (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify):

(9) Unknown

## FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 1

- (0) Not equipped/not available  
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)  
(3) One previous accident with deployment  
(4) More than one previous accident with at least one deployment  
(8) Previous accidents, unknown deployment status  
(9) Unknown

36. Type of Air Bag 1

- (0) Not equipped/not available  
(1) Original manufacturer installed system  
(2) Retrofitted air bag  
(3) Replacement air bag  
(8) Unknown type of air bag  
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 1

- (0) Not equipped/not available  
(1) No prior maintenance  
(2) Yes, prior maintenance (specify):

(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 01

- (00) Not equipped/not available

Code the accident event sequence number that initiated the air bag deployment

- (96) Deployed, unknown event  
(97) Not deployed  
(98) Unknown if deployed  
(99) Unknown

39. CDC For Air Bag Deployment Impact 1

- (0) Not equipped/not available  
(1) Highest delta V  
(2) Second highest delta V  
(3) Other non-coded delta V (specify):

- (6) Deployed, unknown event  
(7) Not deployed  
(8) Unknown if deployed  
(9) Unknown

40. Longitudinal Component of + 996

Delta V For Air Bag

Deployment Impact

(\_000) Not equipped/not available -014

Code the value of the delta V for the impact that initiated the air bag deployment

- (\_996) Deployment, unknown longitudinal Delta V  
(\_997) Not deployed  
(\_998) Unknown if deployed  
(\_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 2

- (0) Not equipped/not available  
(1) No  
(2) Yes  
(3) Deployed, unknown if flap(s) opened at designated tear points  
(7) Not deployed  
(8) Unknown if deployed  
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 2

- (0) Not equipped/not available  
(1) No  
(2) Yes (specify): Scraped by occupant  
(3) Deployed, unknown if air bag module cover flap(s) damaged  
(7) Not deployed  
(8) Unknown if deployed  
(9) Unknown

43. Was There Damage To The Air Bag? 01

- (00) Not equipped/not available  
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured  
(03) Cut  
(04) Torn  
(05) Holed  
(06) Burned  
(07) Abraded  
(88) Other damage (specify):

- (95) Damaged, details unknown  
(96) Deployed, unknown if damaged  
(97) Not deployed  
(98) Unknown if deployed  
(99) Unknown

**FIRST SEAT FRONTAL AIR BAG SYSTEM  
EVALUATION** *continued*44. Source of Air Bag Damage 01

- (00) Not equipped/not available  
 (01) Not damaged  
 (02) Object worn by occupant, (specify):

(03) Object carried by occupant, (specify):

(04) Adaptive/assistive controls, (specify):

- (05) Fire in vehicle  
 (06) Thermal burns  
 (07) Rescue or emergency efforts  
 (08) Other damage source (specify):

- (95) Damaged, unknown source  
 (96) Deployed, unknown if damaged  
 (97) Not deployed  
 (98) Unknown if deployed  
 (99) Unknown

45. Was The Air Bag Tethered? 2

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify number of tether straps):

- (3) 2  
 Deployed, unknown if tethered  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

46. Did The Air Bag Have Vent Ports? 1

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify number of vent ports):

- (3) 1  
 Deployed, unknown if vent ports present  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 1

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify):

- (3) 1  
 Deployed, unknown if other occupant contact to air bag  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

48. Was This Occupant Wearing Eye-wear? 4

- (0) Not air bag equipped/air bag not available  
 (1) No  
 (2) Eyeglasses/sunglasses  
 (3) Contact lenses  
 (4) Deployed, unknown if eyewear worn  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

**HEAD RESTRAINT AND SEAT EVALUATION**49. Head Restraint Type/Damage by Occupant at This Occupant Position 1

- (0) No head restraints  
 (1) Integral—no damage  
 (2) Integral—damaged during accident  
 (3) Adjustable—no damage  
 (4) Adjustable—damaged during accident  
 (5) Add-on—no damage  
 (6) Add-on—damaged during accident  
 (8) Other (specify):

(9) 1  
 Unknown

50. Seat Type (this Occupant Position) 01

- (00) Occupant not seated or no seat  
 (01) Bucket  
 (02) Bucket with folding back  
 (03) Bench  
 (04) Bench with separate back cushions  
 (05) Bench with folding back(s)  
 (06) Split bench with separate back cushions  
 (07) Split bench with folding back(s)  
 (08) Pedestal (i.e., column supported)  
 (09) Box mounted seat (i.e., van type)  
 (10) Other seat type (specify):

(99) 1  
 Unknown

51. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat  
 (1) Forward facing seat  
 (2) Rear facing seat  
 (3) Side facing seat (inward)  
 (4) Side facing seat (outward)  
 (8) Other (specify):

(9) 1  
 Unknown

52. Seat Track Adjusted Position Prior To Impact 3

- (0) Occupant not seated or no seat  
 (1) Non-adjustable seat track

*Adjustable Seat Track*


- (2) Seat at forward most track position  
 (3) Seat between forward most and middle track positions  
 (4) Seat at middle track position  
 (5) Seat between middle and rear most track positions  
 (6) Seat at rear most track position  
 (9) Unknown

**HEAD RESTRAINT AND SEAT EVALUATION** *continued***53. Seat Back Incline Prior and Post Impact** 23


- (00) Occupant not seated or no seat  
 (01) Not adjustable

***Upright prior to impact***


- (11) Moved to completely rearward position  
 (12) Moved to rearward midrange position  
 (13) Moved to slightly rearward position  
 (14) Retained pre-impact position  
 (15) Moved to slightly forward position  
 (16) Moved to forward midrange position  
 (17) Moved to completely forward position

***Slightly reclined prior to impact***

- (21) Moved to completely rearward position  
 (22) Moved to rearward midrange position  
 (23) Retained pre-impact position  
 (24) Moved to upright position  
 (25) Moved to slightly forward position  
 (26) Moved to forward midrange position  
 (27) Moved to completely forward position

***Completely reclined prior to impact***

- (31) Retained pre-impact position  
 (32) Moved to rearward midrange position  
 (33) Moved to slightly rearward position  
 (34) Moved to upright position  
 (35) Moved to slightly forward position  
 (36) Moved to forward midrange position  
 (37) Moved to completely forward position



(99) Unknown

**54. Seat Performance (this Occupant Position)** 1

- (0) Occupant not seated or no seat  
 (1) No seat performance failure(s)  
 (2) Seat adjusters failed  
 (3) Seat back folding locks or "seat back" failed (specify): \_\_\_\_\_  
 (4) Seat track/anchors failed  
 (5) Deformed by impact of occupant  
 (6) Deformed by passenger compartment intrusion, (specify): \_\_\_\_\_  
 (7) Combination of above (specify): \_\_\_\_\_  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown



## CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS  
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

*Designed for Rear Facing for This Age/Weight*

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

*Designed For Forward Facing for This Age/Weight*

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This  
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to  
Variables OA58-OA60.

(00) No child safety seat

*Not Designed With Harness/Shield/Tether*(01) After market harness/shield/tether  
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market  
harness/shield/tether added(09) Unknown if harness/shield/tether  
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

*Unknown If Designed With Harness/Shield/Tether*

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

**INJURY CONSEQUENCES**61. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

62. Treatment - Mortality 3

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):  
\_\_\_\_\_

*Nonfatal*

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (7) Treatment - other (specify):  
\_\_\_\_\_
- (8) Transported to a medical facility-unknown if treated
- (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 1

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):  
\_\_\_\_\_

(9) Unknown

64. Hospital Stay 61

- (00) Not Hospitalized
- \_\_\_\_\_ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

65. Working Days Lost 97

- \_\_\_\_\_ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

**EMERGENCY RESPONSE INFORMATION**

## EMS Notification

- (1) Not notified
- (2) Notified
- (9) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Notification Time (first unit)

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Arrival Time (first unit)

(9998) EMS cancelled or did not arrive

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Departure Time To

Treatment Facility (transporting unit)

(9997) EMS arrived, provided treatment, but did not transport

(9998) EMS arrived, but was not used

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Arrival Time At

Treatment Facility

(9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Type

- (01) Fire department
- (02) Rescue squad
- (03) Police department
- (04) Trauma unit
- (05) Disaster unit
- (06) Ambulance service unit
- (07) Hospital
- (08) Mortuaries/funeral homes
- (98) Other, specify: \_\_\_\_\_
- (99) Unknown

FIRST  
UNITTRANSPORTING  
UNIT

ROAD VEHICLE

AIR VEHICLE

## EMS Care

- (01) No care administered
- (02) First aid
- (03) Resuscitation
- (04) CPR
- (05) Emergency cardiac care
- (06) Life support system monitoring (blood pressure, pulse rate, respiration, EKG)
- (07) Emergency burn care
- (08) Combination of above, specify: \_\_\_\_\_
- (98) Other, specify: \_\_\_\_\_
- (99) Unknown

ON-SCENE

DURING  
TRANSPORT

ROAD VEHICLE

AIR VEHICLE

**STOP WORK HERE VARIABLES 66-74 TO BE CODED BY THE ZONE CENTER**

**TO BE CODED BY THE ZONE CENTER****INJURY CONSEQUENCES**

## 66. Time to Death

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)  
 (00) Not fatal  
 (96) Fatal - ruled disease  
 (99) Unknown

00

## 67. 1st Medically Reported Cause of Death

00

## 68. 2nd Medically Reported Cause of Death

00

## 69. 3rd Medically Reported Cause of Death

00

Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death  
 (00) Not fatal or no additional causes  
 (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

## 70. Number of Recorded Injuries for This Occupant

Code the actual number of injuries recorded for this occupant.  
 (00) No recorded injuries  
 (97) Injured, details unknown  
 (99) Unknown if injured

04**TRAUMA DATA**

## 71. Glasgow Coma Scale (GCS) Score (at Medical Facility)

- (00) Not injured  
 (01) Injured - not treated at medical facility  
 (02) No GCS Score at medical facility  
 (03-15) Code the actual value of the initial GCS Score recorded at medical facility.  
 (97) Injured, details unknown  
 (99) Unknown if injured

02

## 72. Was the Occupant Given Blood?

- (1) No - blood not given  
 (2) Yes - blood given (specify units):  
 (9) Unknown if blood given

173. Arterial Blood Gases (ABG) - HCO<sub>3</sub>

- (00) Not injured  
 (01) Injured, ABGs not measured or reported  
 (02-50) Code the actual value of the HCO<sub>3</sub>  
 (96) ABGs reported, HCO<sub>3</sub> unknown  
 (97) Injured, details unknown  
 (99) Unknown if injured

14**BELT USE DETERMINATION**

## 74. Primary Source of Belt Use Determination

- (0) Not equipped/not available/destroyed or rendered inoperative  
 (1) Vehicle inspection  
 (2) Official injury data  
 (3) Driver/occupant interview  
 (8) Other (specify):  
 (9) Unknown if belt used

1

## OCCUPANT INJURY FORM

1. Primary Sampling Unit Number	<u>74</u>	3. Vehicle Number	<u>01</u>
2. Case Number - Stratum	<u>195J</u>	4. Occupant Number	<u>02</u>

### INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. <u>2</u>	6. <u>6</u>	7. <u>4</u>	8. <u>02</u>	9. <u>34</u>	10. <u>6</u>	11. <u>6</u>	12. <u>180</u>	13. <u>1</u>	14. <u>1</u>	15. <u>00</u>
2nd	16. <u>2</u>	17. <u>3</u>	18. <u>9</u>	19. <u>20</u>	20. <u>06</u>	21. <u>1</u>	22. <u>5</u>	23. <u>180</u>	24. <u>1</u>	25. <u>1</u>	26. <u>00</u>
3rd	27. <u>2</u>	28. <u>3</u>	29. <u>9</u>	30. <u>02</u>	31. <u>02</u>	32. <u>1</u>	33. <u>5</u>	34. <u>180</u>	35. <u>1</u>	36. <u>1</u>	37. <u>00</u>
4th	38. <u>2</u>	39. <u>2</u>	40. <u>9</u>	41. <u>02</u>	42. <u>02</u>	43. <u>1</u>	44. <u>8</u>	45. <u>180</u>	46. <u>1</u>	47. <u>1</u>	48. <u>00</u>
5th	49. <u>  </u>	50. <u>  </u>	51. <u>  </u>	52. <u>  </u>	53. <u>  </u>	54. <u>  </u>	55. <u>  </u>	56. <u>  </u>	57. <u>  </u>	58. <u>  </u>	59. <u>  </u>
6th	60. <u>  </u>	61. <u>  </u>	62. <u>  </u>	63. <u>  </u>	64. <u>  </u>	65. <u>  </u>	66. <u>  </u>	67. <u>  </u>	68. <u>  </u>	69. <u>  </u>	70. <u>  </u>
7th	71. <u>  </u>	72. <u>  </u>	73. <u>  </u>	74. <u>  </u>	75. <u>  </u>	76. <u>  </u>	77. <u>  </u>	78. <u>  </u>	79. <u>  </u>	80. <u>  </u>	81. <u>  </u>
8th	82. <u>  </u>	83. <u>  </u>	84. <u>  </u>	85. <u>  </u>	86. <u>  </u>	87. <u>  </u>	88. <u>  </u>	89. <u>  </u>	90. <u>  </u>	91. <u>  </u>	92. <u>  </u>
9th	93. <u>  </u>	94. <u>  </u>	95. <u>  </u>	96. <u>  </u>	97. <u>  </u>	98. <u>  </u>	99. <u>  </u>	100. <u>  </u>	101. <u>  </u>	102. <u>  </u>	103. <u>  </u>
10th	104. <u>  </u>	105. <u>  </u>	106. <u>  </u>	107. <u>  </u>	108. <u>  </u>	109. <u>  </u>	110. <u>  </u>	111. <u>  </u>	112. <u>  </u>	113. <u>  </u>	114. <u>  </u>

# OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90					Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
		Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity					
11th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
12th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
13th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
14th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
15th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
16th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
17th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
18th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
19th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
20th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
21st	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
22nd	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
23rd	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
24th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —
25th	—	—	—	— — —	— — —	—	—	— — — —	—	—	— — —

**OCCUPANT INJURY CLASSIFICATION**

Body Region	Specific Anatomic Structure	Level of Injury	Aspect
(1) Head		Specific injuries are assigned consecutive two-digit numbers beginning with 02.	(1) Right
(2) Face			(2) Left
(3) Neck	<u>Vessels, Nerves, Organs.</u>	To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.	(3) Bilateral
(4) Thorax	<u>Bones, Joints</u> are assigned consecutive two digit numbers beginning with 02.		(4) Central
(5) Abdomen		The exceptions to this rule apply to:	(5) Anterior
(6) Spine			(6) Posterior
(7) Upper Extremity			(7) Superior
(8) Lower Extremity			(8) Inferior
(9) Unspecified			(9) Unknown
			(0) Whole region
<b>Type of Anatomic Structure</b>	<u>Whole Area</u>		
(1) Whole Area	(02) Skin - Abrasion		
(2) Vessels	(04) Skin - Contusion		
(3) Nerves	(06) Skin - Laceration		
(4) Organs (includes Muscles/ligaments)	(08) Skin - Avulsion		
(5) Skeletal (includes joints)	(10) Amputation		
(6) Head - LOC	(20) Burn		
(9) Skin	(30) Crush		
	(40) Degloving		
	(50) Injury - NFS		
	(90) Trauma, other than mechanical		
	<u>Head - LOC</u>		
	(02) Length of LOC		
	(04) Level		
	(06) of		
	(08) Consciousness		
	(10) Concussion		
	<u>Spine</u>		
	(02) Cervical		
	(04) Thoracic		
	(06) Lumbar		

**Abbreviated Injury Scale**

- (1) Minor Injury
- (2) Moderate Injury
- (3) Serious Injury
- (4) Severe Injury
- (5) Critical Injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

**SOURCE OF INJURY DATA****INJURY SOURCE****DIRECT/INDIRECT INJURY****CONFIDENCE LEVEL****OFFICIAL RECORDS**

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

**UNOFFICIAL RECORDS**

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify):
- (9) Police

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

## INJURY SOURCES

### FRONT

- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column, transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment (e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object (specify): \_\_\_\_\_
- (019) Other front object (specify): \_\_\_\_\_

### LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): \_\_\_\_\_
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): \_\_\_\_\_

### RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests

- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): \_\_\_\_\_
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): \_\_\_\_\_

### INTERIOR

- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): \_\_\_\_\_
- (155) Head restraint system
- (160) Other occupants (specify): \_\_\_\_\_
- (161) Interior loose objects
- (162) Child safety seat (specify): \_\_\_\_\_
- (163) Other interior object (specify): \_\_\_\_\_

### AIR BAG

- (170) Air bag-driver side
- (171) Air bag-driver side and eyewear
- (172) Air bag-driver side and jewelry
- (173) Air bag-driver side and object held
- (174) Air bag-driver side and object in mouth
- (175) Air bag compartment cover-driver side
- (176) Air bag compartment cover-driver side and eyewear
- (177) Air bag compartment cover-driver side and jewelry
- (178) Air bag compartment cover-driver side and object held
- (179) Air bag compartment cover-driver side and object in mouth
- (180) Air bag-passenger side
- (181) Air bag-passenger side and eyewear
- (182) Air bag-passenger side and jewelry

- (183) Air bag-passenger side and object held
- (184) Air bag-passenger side and object in mouth
- (185) Air bag compartment cover-passenger side
- (186) Air bag compartment cover-passenger side and eyewear
- (187) Air bag compartment cover-passenger side and jewelry
- (188) Air bag compartment cover-passenger side and object held
- (189) Air bag compartment cover-passenger side and object in mouth
- (190) Other air bag (specify) \_\_\_\_\_
- (195) Other air bag compartment cover (specify) \_\_\_\_\_

### ROOF

- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top

### FLOOR

- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

### REAR

- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): \_\_\_\_\_

### ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): \_\_\_\_\_
- (409) Additional or relocated switches, (specify): \_\_\_\_\_
- (410) Raised roof

- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): \_\_\_\_\_

### EXTERIOR of OCCUPANT'S VEHICLE

- (451) Hood
- (452) Outside hardware (e.g., outside mirror, antenna)
- (453) Other exterior surface or tires (specify): \_\_\_\_\_
- (454) Unknown exterior objects

### EXTERIOR OF OTHER MOTOR VEHICLE

- (501) Front bumper
- (502) Hood edge
- (503) Other front of vehicle (specify): \_\_\_\_\_
- (504) Hood
- (505) Hood ornament
- (506) Windshield, roof rail, A-pillar
- (507) Side surface
- (508) Side mirrors
- (509) Other side protrusions (specify): \_\_\_\_\_
- (510) Rear surface
- (511) Undercarriage
- (512) Tires and wheels
- (513) Other exterior of other motor vehicle (specify): \_\_\_\_\_
- (514) Unknown exterior of other motor vehicle

### OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (551) Ground
- (598) Other vehicle or object (specify): \_\_\_\_\_
- (599) Unknown vehicle or object

### NONCONTACT INJURY

- (601) Fire in vehicle
- (602) Flying glass
- (603) Other noncontact injury source (specify): \_\_\_\_\_
- (604) Air bag exhaust gases
- (697) Injured, unknown source

# OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Restrained?

☐ No

☐ Yes

Blood Alcohol Level  
(mg/dl)

BAL = 0

Glasgow Coma  
Scale Score

GCSS = 02

Units of Blood  
Given

Units = 0

Arterial Blood Gases

pH = 7.35

PO<sub>2</sub> = 407



PCO<sub>2</sub> = 26

HCO<sub>3</sub> = 14

scattered facial abrasions

burn type abrasions  
chin


2° abrasions +  
burn anterior neck







## OFFICIAL INJURY DATA — SKELETAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



## OFFICIAL INJURY DATA — INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





## GENERAL VEHICLE FORM

1. Primary Sampling Unit Number 24

2. Case Number - Stratum 1953

3. Vehicle Number 02

### VEHICLE IDENTIFICATION

4. Vehicle Model Year 90  
Code the last two digits of the model year  
(99) Unknown

5. Vehicle Make (specify): 10  
Eagle

Applicable codes are found in your  
NASS Data Collection, Coding and  
Editing Manual.  
(99) Unknown

6. Vehicle Model (specify): 037  
Talon

Applicable codes are found in your  
NASS Data Collection, Coding and  
Editing Manual.  
(99) Unknown

7. Body Type 03  
Note: Applicable codes may be found on  
the back of this page.

8. Vehicle Identification Number ✓

4E3CT64 [REDACTED]  
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17

Left justify; Slash zeros and letter Z (0 and Z)  
No VIN—Code all zeros  
Unknown—Code all nines

9. Vehicle Special Use (This Trip) 0

- (0) No special use  
(1) Taxi  
(2) Vehicle used as school bus  
(3) Vehicle used as other bus  
(4) Military  
(5) Police  
(6) Ambulance  
(7) Fire truck or car  
(8) Other (specify): \_\_\_\_\_  
(9) Unknown

### OFFICIAL RECORDS

10. Police Reported Vehicle Disposition 1  
(0) Not towed due to vehicle damage  
(1) Towed due to vehicle damage  
(9) Unknown

11. Police Reported Travel Speed 999  
Code to the nearest kmph (NOTE: 000 means  
less than 0.5 kmph)  
(160) 159.5 kmph and above  
(999) Unknown

99 mph X 1.6093 = 999 kmph

12. Speed Limit 040  
(000) No statutory limit  
Code posted or statutory speed limit in kmph  
(999) Unknown

40 mph X 1.6093 = 040 kmph

13. Police Reported Alcohol Presence For Driver 0  
(0) No alcohol present  
(1) Yes alcohol present  
(7) Not reported  
(8) No driver present  
(9) Unknown

14. Alcohol Test Result For Driver 96  
Code actual value (decimal implied  
before first digit—0.xx)  
(95) Test refused  
(96) None given  
(97) AC test performed, results unknown  
(98) No driver present  
(99) Unknown

Source: [REDACTED]

15. Police Reported Other Drug Presence For Driver 0  
(0) No other drug(s) present  
(1) Yes other drug(s) present  
(7) Not reported  
(8) No driver present  
(9) Unknown

16. Other Drug Specimen Test Result For Driver 0  
(0) No specimen test given  
(1) Drug(s) not found in specimen  
(2) Drug(s) found in specimen, (specify): \_\_\_\_\_  
(3) Specimen test given, results unknown or not  
obtained  
(8) No driver present  
(9) Unknown if specimen test given

17. Driver's Zip Code [REDACTED]  
(00001) Driver not a resident of U.S. or territories  
Code actual 5-digit zip code  
(99998) No driver present  
(99999) Unknown

18. Driver's Race/Ethnic Origin 1  
(1) White (non-Hispanic)  
(2) Black (non-Hispanic)  
(3) White (Hispanic)  
(4) Black (Hispanic)  
(5) American Indian, Eskimo or Aleut  
(6) Asian or Pacific Islander  
(7) Other (specify): \_\_\_\_\_  
(8) No driver present  
(9) Unknown

# CODES FOR BODY TYPE

## CDS APPLICABLE VEHICLES

### Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): \_\_\_\_\_
- (09) Unknown automobile type

### Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

### Utility Vehicles ( $\leq 4,536$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Passport, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Hummer, Landcruiser, Rover, Scout, Yukon)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

### Van Based Light Trucks ( $\leq 4,536$ kgs GVWR)

- (20) Minivan (Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Vista, Aerostar, Windstar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Expo Wagon, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ( $\leq 4,536$  kgs GVWR)
- (23) Van based motorhome ( $\leq 4,536$  kgs GVWR)
- (24) Van based school bus ( $\leq 4,536$  kgs GVWR)
- (25) Van based other bus ( $\leq 4,536$  kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): \_\_\_\_\_
- (29) Unknown van type

### Light Conventional Trucks (Pickup style cab, $\leq 4,536$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500, T100)
- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

### Other Light Trucks ( $\leq 4,536$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

## OTHER VEHICLES

### Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): \_\_\_\_\_
- (59) Unknown bus type

### Medium/Heavy Trucks ( $> 4,536$ kgs GVWR)

- (60) Step van ( $> 4,536$  kgs GVWR)
- (61) Single unit straight truck ( $4,536$  kgs  $<$  GVWR  $\leq 8,845$  kgs)
- (62) Single unit straight truck ( $8,845$  kgs  $<$  GVWR  $\leq 11,793$  kgs)
- (63) Single unit straight truck ( $> 11,793$  kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

### Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): \_\_\_\_\_
- (89) Unknown motored cycle type

### Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

**PRECRASH ENVIRONMENTAL DATA**19. Relation To Interchange Or Junction 2

- (0) Non-interchange area and non-junction
- (1) Interchange area related

*Non-Interchange junctions*

- (2) Intersection related
- (3) Driveway, alley access related
- (4) Other junction (specify) \_\_\_\_\_

- (5) Unknown type of junction

- (9) Unknown

20. Trafficway Flow 0

- (0) Not physically divided (two way traffic)
- (1) Divided trafficway-median strip without positive barrier
- (2) Divided trafficway-median strip with positive barrier
- (3) One way traffic
- (9) Unknown

21. Number Of Travel Lanes 2

- (1) One
- (2) Two
- (3) Three
- (4) Four
- (5) Five
- (6) Six
- (7) Seven or more
- (9) Unknown

22. Roadway Alignment 1

- (1) Straight
- (2) Curve right
- (3) Curve left
- (9) Unknown

23. Roadway Profile 4

- (1) Level
- (2) Uphill grade (> 2%)
- (3) Hill crest
- (4) Downhill grade (> 2%)
- (5) Sag
- (9) Unknown

24. Roadway Surface Type 1

- (1) Concrete
- (2) Bituminous (asphalt)
- (3) Brick or block
- (4) Slag, gravel, or stone
- (5) Dirt
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

25. Roadway Surface Condition 3 2

- (1) Dry
- (2) Wet
- (3) Snow or slush
- (4) Ice
- (5) Sand, dirt, or oil
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

26. Light Conditions 1

- (1) Daylight
- (2) Dark
- (3) Dark, but lighted
- (4) Dawn
- (5) Dusk
- (9) Unknown

27. Atmospheric Conditions 0

- (0) No adverse atmospheric-related driving conditions
- (1) Rain
- (2) Sleet/hail
- (3) Snow
- (4) Fog
- (5) Rain and fog
- (6) Sleet and fog
- (7) Other (e.g., smog, smoke, blowing sand or dust, etc.) (specify): \_\_\_\_\_
- (9) Unknown

28. Traffic Control Device 1

- (0) No traffic control(s)
- (1) Traffic control signal (not RR crossing)

*Regulatory*

- (2) Stop sign
- (3) Yield sign
- (4) School zone sign
- (5) Other regulatory sign (specify): \_\_\_\_\_

- (6) Warning sign (not RR crossing)
- (7) Unknown sign
- (8) Miscellaneous/other controls including RR controls (specify): \_\_\_\_\_

- (9) Unknown

29. Traffic Control Device Functioning 2

- (0) No traffic control device
- (1) Traffic control device not functioning (specify): \_\_\_\_\_
- (2) Traffic control device functioning properly
- (9) Unknown

**PRECRASH DRIVER RELATED DATA**

30. Driver's Distraction/Inattention To Driving (Prior To Recognition Of Critical Event) **01**
- (00) No driver present
- (01) Attentive or not distracted
- (02) Looked but did not see
- Distractions*
- (03) By other occupant(s), (specify): \_\_\_\_\_
- (04) By moving object in vehicle (specify): \_\_\_\_\_
- (05) While talking or listening to cellular phone (specify location and type of phone): \_\_\_\_\_
- (06) While dialing cellular phone (specify location and type of phone): \_\_\_\_\_
- (07) While adjusting climate controls
- (08) While adjusting radio, cassette, CD (specify): \_\_\_\_\_
- (09) While using other device/controls integral to vehicle (specify): \_\_\_\_\_
- (10) While using or reaching for device/object brought into vehicle (specify): \_\_\_\_\_
- (11) Sleepy or fell asleep
- (12) Distracted by outside person, object, or event (specify): \_\_\_\_\_
- (13) Eating or drinking
- (14) Smoking related
- (97) Distracted/inattentive, details unknown
- (98) Other, distraction (specify): \_\_\_\_\_
- (99) Unknown
31. Pre-Event Movement (Prior to Recognition of Critical Event) **01**
- (00) No driver present
- (01) Going straight
- (02) Decelerating in traffic lane
- (03) Accelerating in traffic lane
- (04) Starting in traffic lane
- (05) Stopped in traffic lane
- (06) Passing or overtaking another vehicle
- (07) Disabled or parked in travel lane
- (08) Leaving a parking position
- (09) Entering a parking position
- (10) Turning right
- (11) Turning left
- (12) Making a U-turn
- (13) Backing up (other than for parking position)
- (14) Negotiating a curve
- (15) Changing lanes
- (16) Merging
- (17) Successful avoidance maneuver to a previous critical event
- (97) Other (specify): \_\_\_\_\_
- (99) Unknown
32. Critical Precrash Event **17**
- THIS VEHICLE LOSS OF CONTROL DUE TO:**
- (01) Blow out or flat tire
- (02) Stalled engine
- (03) Disabling vehicle failure (e.g., wheel fell off) (specify): \_\_\_\_\_
- (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): \_\_\_\_\_
- (05) Poor road conditions (puddle, pot hole, ice, etc.) (specify): \_\_\_\_\_
- (06) Traveling too fast for conditions
- (08) Other cause of control loss (specify): \_\_\_\_\_
- (09) Unknown cause of control loss

**THIS VEHICLE TRAVELLING**

- (10) Over the lane line on left side of travel lane
- (11) Over the lane line on right side of travel lane
- (12) Off the edge of the road on the left side
- (13) Off the edge of the road on the right side
- (14) End departure
- (15) Turning left at intersection
- (16) Turning right at intersection
- (17) Crossing over (passing through) intersection
- (18) This vehicle decelerating
- (19) Unknown travel direction

**OTHER MOTOR VEHICLE IN LANE**

- (50) Other vehicle stopped
- (51) Traveling in same direction with lower steady speed
- (52) Traveling in same direction while decelerating
- (53) Traveling in same direction with higher speed
- (54) Traveling in opposite direction
- (55) In crossover
- (56) Backing
- (59) Unknown travel direction of other motor vehicle in lane

**OTHER MOTOR VEHICLE ENCROACHING INTO LANE**

- (60) From adjacent lane (same direction)—over left lane line
- (61) From adjacent lane (same direction)—over right lane line
- (62) From opposite direction—over left lane line
- (63) From opposite direction—over right lane line
- (64) From parking lane
- (65) From crossing street, turning into same direction
- (66) From crossing street, across path
- (67) From crossing street, turning into opposite direction
- (68) From crossing street, intended path not known
- (70) From driveway, turning into same direction
- (71) From driveway, across path
- (72) From driveway, turning into opposite direction
- (73) From driveway, intended path not known
- (74) From entrance to limited access highway
- (78) Encroachment by other vehicle—details unknown

**PEDESTRIAN, PEDALCYCLIST, OR OTHER NONMOTORIST**

- (80) Pedestrian in roadway
- (81) Pedestrian approaching roadway
- (82) Pedestrian—unknown location
- (83) Pedalcyclist or other nonmotorist in roadway (specify): \_\_\_\_\_
- (84) Pedalcyclist or other nonmotorist approaching roadway, (specify): \_\_\_\_\_
- (85) Pedalcyclist or other nonmotorist—unknown location (specify): \_\_\_\_\_

**OBJECT OR ANIMAL**

- (87) Animal in roadway
- (88) Animal approaching roadway
- (89) Animal—unknown location
- (90) Object in roadway
- (91) Object approaching roadway
- (92) Object—unknown location
- (98) Other critical precrash event (specify): \_\_\_\_\_
- (99) Unknown

## 33. Attempted Avoidance Maneuver

09

- (00) No driver present
- (01) No avoidance maneuver
- (02) Braking (no lockup)
- (03) Braking (lockup)
- (04) Braking (lockup unknown)
- (05) Releasing brakes
- (06) Steering left
- (07) Steering right
- (08) Braking and steering left
- (09) Braking and steering right
- (10) Accelerating
- (11) Accelerating and steering left
- (12) Accelerating and steering right
- (98) Other action (specify):

(99) Unknown

## 34. Pre-Impact Stability

1

- (0) No driver present
- (1) Tracking
- (2) Skidding longitudinally—rotation less than 30 degrees
- (3) Skidding laterally—clockwise rotation
- (4) Skidding laterally—counterclockwise rotation
- (7) Other vehicle loss-of-control (specify):

(9) Precrash stability unknown

## 35. Pre-Impact Location

1

- (0) No driver present
- (1) Stayed in original travel lane
- (2) Stayed on roadway but left original travel lane
- (3) Stayed on roadway, not known if left original travel lane
- (4) Departed roadway
- (5) Remained off roadway
- (6) Returned to roadway
- (7) Entered roadway
- (9) Unknown

## 36. Accident Type



















































89

(Note: Applicable codes on back of this page)

- (00) No impact  
Code the number of the diagram that best describes the accident circumstance
- (98) Other accident type (specify):

(99) Unknown

**STOP HERE IF GV07 DOES NOT EQUAL 01 - 49**

Category	Configuration	ACCIDENT TYPES (Includes Intent)				
I Single Driver	A Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN
	B Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN
	C Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER 16 SPECIFICS UNKNOWN
II Same Trafficway Same Direction	D Rear-End	 20 STOPPED 21, 22, 23	 22 SLOWER 24, 25, 27	 24 DECEL. 26, 28, 31	 26 AVOID COLLISION WITH VEH.	(EACH • 32) SPECIFICS OTHER (EACH • 33) SPECIFICS UNKNOWN
	E Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	(EACH • 42) SPECIFICS OTHER (EACH • 43) SPECIFICS UNKNOWN
	F Sideswipe Angle	 44 SIDESWIPE	 46 SIDESWIPE	 48 SIDESWIPE	 50 SIDESWIPE	(EACH • 48) SPECIFICS OTHER (EACH • 49) SPECIFICS UNKNOWN
III Same Trafficway Opposite Direction	G Head-On	 50 LATERAL MOVE	 52 HEAD-ON	 54 HEAD-ON	 56 HEAD-ON	(EACH • 52) SPECIFICS OTHER (EACH • 53) SPECIFICS UNKNOWN
	H Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	(EACH • 52) SPECIFICS OTHER (EACH • 53) SPECIFICS UNKNOWN
	I Sideswipe Angle	 64 LATERAL MOVE	 66 SIDESWIPE	 68 SIDESWIPE	 70 SIDESWIPE	(EACH • 66) SPECIFICS OTHER (EACH • 67) SPECIFICS UNKNOWN
IV Change Trafficway Vehicle Turning	J Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 70 INITIAL SAME DIRECTIONS	 72 TURN ACROSS PATH	 74 TURN ACROSS PATH	(EACH • 74) SPECIFICS OTHER (EACH • 75) SPECIFICS UNKNOWN
	K Turn Into Path	 76 TURN INTO SAME DIRECTION	 78 TURN INTO OPPOSITE DIRECTIONS	 80 TURN INTO OPPOSITE DIRECTIONS	 82 TURN INTO OPPOSITE DIRECTIONS	(EACH • 76) SPECIFICS OTHER (EACH • 77) SPECIFICS UNKNOWN
V Intersecting Paths (Vehicle Damage)	L Straight Paths	 86 STRAIGHT PATHS	 88 STRAIGHT PATHS	 90 STRAIGHT PATHS	 92 STRAIGHT PATHS	(EACH • 86) SPECIFICS OTHER (EACH • 87) SPECIFICS UNKNOWN
VI Miscellaneous	M Backing Etc.	 92 BACKING VEH.	 94 OTHER VEH. OR OBJECT	 96 OTHER ACCIDENT TYPE	 98 UNKNOWN ACCIDENT TYPE	00 No Impact



**OCCUPANT RELATED**

37. Driver Presence in Vehicle 1  
 (0) Driver not present  
 (1) Driver present  
 (9) Unknown
38. Number of Occupants This Vehicle 01  
 (00-96) Code actual number of occupants for this vehicle  
 (97) 97 or more  
 (99) Unknown
39. Number of Occupant Forms Submitted 01

**AIR BAG RELATED**

40. Is this an AOPS Vehicle? 1  
 (0) No (includes unknown)  
 (1) Yes - researcher determined  
 (2) VIN determined air bag system  
 (3) VIN determined automatic (passive) belts  
 (4) VIN determined air bag and automatic (passive) belts
41. Air Bag(s) Deployment, First Seat Frontal 0  
 (0) Not equipped or not available  
 (1) No air bags deployed  
*Single Air Bag Vehicle*  
 (2) Driver air bag deployed  
 (3) Driver air bag, unknown if deployed  
*Multiple Air Bag Vehicle*  
 (4) Driver side only deployed  
 (5) Passenger side only deployed  
 (6) Driver and passenger side deployed  
 (7) Driver and passenger side unknown if deployed  
 (8) Air bag(s) deployed, details unknown  
 (9) Unknown
42. Air Bag(s) Deployment, Other Than First Seat Frontal 0  
 (0) Not equipped with an "other" air bag  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

Specify type of "other" air bag present: \_\_\_\_\_

**VEHICLE WEIGHT ITEMS**

43. Vehicle Curb Weight 1.200  
 Code weight to nearest 10 kilograms.  
 (045) Less than 454 kilograms  
 (612) 6,124 kilograms or more  
 (999) Unknown  
2651 lbs X .4536 = 1202 kgs  
 Source: 1990

44. Vehicle Cargo Weight 0.000  
 Code weight to nearest 10 kilograms.  
 (000) Less than 5 kilograms  
 (454) 4,536 kilograms or more  
 (999) Unknown  
 \_\_\_\_\_ lbs X .4536 = 000 kgs  
 Source: \_\_\_\_\_

**ROLLOVER DATA**

45. Rollover 00  
 (00) No rollover (no overturning)  
*Rollover (primarily about the longitudinal axis)*  
 (01-16) Code the number of quarter turns  
 (17) Rollover, 17 or more quarter turns (specify): \_\_\_\_\_  
 (98) Rollover--end-over-end (i.e., primarily about the lateral axis)  
 (99) Rollover (overturn), details unknown
46. Rollover Initiation Type 00  
 (00) No rollover  
 (01) Trip-over  
 (02) Flip-over  
 (03) Turn-over  
 (04) Climb-over  
 (05) Fall-over  
 (06) Bounce-over  
 (07) Collision with another vehicle  
 (08) Other rollover initiation type specify): \_\_\_\_\_  
 (98) Rollover--end-over-end  
 (99) Unknown rollover initiation type
47. Location of Rollover Initiation 0  
 (0) No rollover  
 (1) On roadway  
 (2) On shoulder—paved  
 (3) On shoulder—unpaved  
 (4) On roadside or divided trafficway median  
 (8) Rollover--end-over-end  
 (9) Unknown
48. Rollover Initiation Object Contacted 00  
 (Note: Applicable codes on back of page)
49. Location on Vehicle Where Initial Principal Tripping Force Is Applied 0  
 (0) No rollover  
 (1) Wheels/tires  
 (2) Side plane  
 (3) End plane  
 (4) Undercarriage  
 (5) Other location on vehicle (specify): \_\_\_\_\_  
 (6) Non-contact rollover forces (specify): \_\_\_\_\_  
 (8) Rollover--end-over-end  
 (9) Unknown
50. Direction of Initial Roll 0  
 (0) No rollover  
 (1) Roll right - primarily about the longitudinal axis  
 (2) Roll left - primarily about the longitudinal axis  
 (8) Rollover--end-over-end  
 (9) Unknown roll direction

## CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

### Noncollision

- (31) Turn-over — fall-over
- (32) No rollover impact initiation (end-over-end)
- (34) Jackknife

### Collision With Fixed Object

- (41) Tree ( $\leq 10$  cm in diameter)
- (42) Tree ( $> 10$  cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

- (45) Breakaway pole or post (any diameter)

### Nonbreakaway Pole or Post

- (50) Pole or post ( $\leq 10$  cm in diameter)
- (51) Pole or post ( $> 10$  cm but  $\leq 30$  cm in diameter)
- (52) Pole or post ( $> 30$  cm in diameter)
- (53) Pole or post (diameter unknown)

- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)  
(specify): \_\_\_\_\_

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): \_\_\_\_\_

- (69) Unknown fixed object \_\_\_\_\_

### Collision with Nonfixed Object

- (70) Passenger car, light truck, van, or other vehicle not in-transport
- (71) Medium/heavy truck or bus not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): \_\_\_\_\_

- (89) Unknown nonfixed object \_\_\_\_\_

- (98) Other event (specify): \_\_\_\_\_

- (99) Unknown event or object \_\_\_\_\_

**VERRIDE/UNDERRIDE (THIS VEHICLE)**51. Front Override/Underride (this Vehicle) 052. Rear Override/Underride (this Vehicle) 0

- (0) No override/underride, or not an end-to-end impact between two CDS applicable vehicles, and no medium/heavy truck or bus underride

*Override (see specific CDC)**[Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)]*

- (1) 1st CDC  
(2) 2nd CDC  
(3) Other not automated CDC (specify):  
\_\_\_\_\_

*Underride (see specific CDC)**[Between 2 CDS applicable vehicles (Bodytype, GV07 = 1-49)]*

- (4) 1st CDC  
(5) 2nd CDC  
(6) Other not automated CDC (specify):  
\_\_\_\_\_

- (7) Medium/heavy truck or bus override (of any configuration)  
(9) Unknown

**HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V**

Values: (000)-(359) Code actual value  
(996) Non-horizontal impact  
(997) Noncollision  
(998) Impact with object  
(999) Unknown

53. Heading Angle For This Vehicle 01054. Heading Angle For Other Vehicle 090**RECONSTRUCTION DATA**55. Towed Trailing Unit 0

- (0) No towed unit  
(1) Yes—towed trailing unit  
(9) Unknown

56. Documentation of Trajectory Data for This Vehicle 1

- (0) No  
(1) Yes

57. Post Collision Condition of Tree or Pole (For Highest Delta V) 0

- (0) Not collision (for highest delta V) with tree or pole  
(1) Not damaged  
(2) Cracked/sheared  
(3) Tilted <45 degrees  
(4) Tilted ≥45 degrees  
(5) Uprooted tree  
(6) Separated pole from base  
(7) Pole replaced  
(8) Other (specify):  
\_\_\_\_\_

(9) Unknown

**ACCIDENT RECONSTRUCTION PROGRAMS HIGHEST DELTA V**58. Basis for Total (Resultant) Delta V (highest) 03

(00) No vehicle inspection

*Delta V Calculated*

- (01) Reconstruction program-damage only routine  
(02) Reconstruction program-damage and trajectory routine  
(03) Missing vehicle algorithm

*Delta V Not Calculated*

- (04) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.

*All vehicles within scope (CDC applicable) of reconstruction program but one of the collision conditions is beyond the scope of the reconstruction program or other acceptable reconstruction technique, regardless of adequacy of damage data.*

- (05) Rollover  
(06) Other non-horizontal forces  
(07) Sideswipe type damage  
(08) Severe override  
(09) Yielding object  
(10) Overlapping damage  
(11) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available, (specify):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

(98) Other, (specify): \_\_\_\_\_

## COMPUTER GENERATED CRASH SEVERITY

59. Total Delta V

Highest

24 Nearest kmph (highest)

Nearest kmph (secondary)

(NOTE: 000 means less than 0.5 kmph)  
 (160) 159.5 kmph and above  
 (999) Unknown

60. Longitudinal Component of Delta V

Highest

-15 Nearest kmph (highest)

Nearest kmph (secondary)

(NOTE: 000 means greater than  
 -0.5 kmph and less than +0.5 kmph)  
 (±160) ±159.5 kmph and above  
 (999) Unknown

61. Lateral Component of Delta V

Highest

18 Nearest kmph (highest)

Nearest kmph (secondary)

(NOTE: 000 means greater than -0.5 kmph and  
 less than +0.5 kmph)  
 (±160) ±159.5 kmph and above  
 (999) Unknown

62. Energy Absorption

Highest

42950 Nearest 100 joules (highest)

Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)  
 (9997) 999,650 joules or more  
 (9999) Unknown

63. Impact Speed

Highest

998 Nearest kmph (highest)

Nearest kmph (secondary)

(NOTE: 000 means  
 less than 0.5 kmph)  
 (160) 159.5 kmph and above  
 (998) Trajectory algorithm not run  
 (999) Unknown

## DELTA V CONFIDENCE LEVEL

64. Confidence In Reconstruction Program Results (For Highest Delta V)

- (0) No reconstruction  
 (1) Collision fits model — results appear reasonable  
 (2) Collision fits model — results appear high  
 (3) Collision fits model — results appear low  
 (4) Borderline reconstruction — results appear reasonable

## OTHER SPEED ESTIMATE

65. Barrier Equivalent Speed

Highest

28.6 Nearest kmph (highest)

Nearest kmph (secondary)

(NOTE: 000 means  
 less than 0.5 kmph)  
 (160) 159.5 kmph and above  
 (999) Unknown

✓ 2. damage - on LF  
 wheel CDC only

ESTIMATED DELTA V	INSPECTION TYPE
<p>66. Estimated Highest Delta V (Researcher Determined) <span style="float: right;">0 <del>6</del></span></p> <p>(0) Reconstruction Delta V coded</p> <p><i>Estimated Delta V</i></p> <p>(1) Less than 10 kmph (2) <math>\geq 10</math> kmph but <math>&lt; 25</math> kmph (3) <math>\geq 25</math> kmph but <math>&lt; 40</math> kmph (4) <math>\geq 40</math> kmph but <math>&lt; 55</math> kmph (5) <math>\geq 55</math> kmph</p> <p><i>Other estimates of damage severity</i></p> <p>(6) Minor (7) Moderate (8) Severe (9) Unknown</p>	<p>67. Type of Vehicle Inspection <span style="float: right;">3</span></p> <p>(0) No inspection (1) Vehicle fully repaired-no damage evident (2) Partial inspection (specify): _____ (3) Complete inspection</p> <p><b>DELTA V EVENT NUMBER</b></p> <p>68. Delta V Event Number <span style="float: right;">01</span></p> <p>_____ Code the accident event sequence number that resulted in the Delta V that has been coded above for this vehicle (99) Unknown</p>

\*\*\* IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV67 = 0), \*\*\*

DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS

\*\*\* IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE \*\*\*

THE EXTERIOR VEHICLE, INTERIOR VEHICLE,  
OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.

## EXTERIOR VEHICLE FORM

**NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM**

Administration	
1. Primary Sampling Unit Number	74
2. Case Number - Stratum	195J
3. Vehicle Number	02

## VEHICLE IDENTIFICATION

VIN 4E3GT64UXLE [REDACTED] Model Year 90  
Vehicle Make (specify): Eagle Vehicle Model (specify): Talon

## LOCATOR

Locate the end of the damage with respect to the vehicle's damaged center point or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L	Location of Max Crush
1	20cm behind rear axle in front of LF axle	20cm behind rear axle	CU

### CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

**Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.**


**Use as many lines/columns as necessary to describe each damage profile.**

[illegible]

# ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	<u>97.2</u>	inches	x 2.54	=	<u>247</u>	cm
Overall Length	<u>172.4</u>	inches	x 2.54	=	<u>438</u>	cm
Maximum Width	<u>66.9</u>	inches	x 2.54	=	<u>170</u>	cm
Curb Weight	<u>21651</u>	pounds	x .4536	=	<u>1202</u>	kg
Average Track	<u>52</u>	inches	x 2.54	=	_____	cm
Front Overhang	_____	inches	x 2.54	=	_____	cm
Rear Overhang	_____	inches	x 2.54	=	_____	cm
Undeformed End Width	_____	inches	x 2.54	=	_____	cm
Engine Size: cyl./displ.	<u>14</u>	cc	x .001	=	<u>20</u>	L
	_____	CID	x .0164	=	_____	L

<b>TIRE — WHEEL DAMAGE</b> a. Rotation physically restricted RF <u>2</u> LF <u>2</u> RR <u>2</u> LR <u>2</u> (1) Yes (2) No (8) NA (9) Unk.		<b>ORIGINAL SPECIFICATIONS</b> Wheelbase <u>247</u> cm Overall Length <u>438</u> cm Maximum Width <u>170</u> cm Curb Weight <u>1202</u> kg Average Track <u>145</u> cm Front Overhang <u>96</u> cm Rear Overhang <u>91</u> cm Undeformed End Width <u>145</u> cm Engine Size: cyl./displ. <u>I4 2.0</u> L		<b>WHEEL STEER ANGLES</b> (For locked front wheels or displaced rear axles only) RF $\pm$ <u>X</u> ° LF $\pm$ <u>X</u> ° RR $\pm$ <u>X</u> ° LR $\pm$ <u>X</u> ° Within $\pm$ 5 degrees	
<b>TYPE OF TRANSMISSION</b> <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Automatic END SHIFT $\geq$ 10 CM <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				<b>DRIVE WHEELS</b> <input checked="" type="checkbox"/> FWD <input type="checkbox"/> RWD <input type="checkbox"/> 4WD Approximate Cargo Weight <u>0</u> kg	



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.



### CODES FOR OBJECT CONTACTED

(specify): \_\_\_\_\_

[illegible]

## COLLISION DEFORMATION CLASSIFICATION

## HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. <u>01</u>	5. <u>01</u>	6. <u>09</u> <u>10</u>	7. <u>L</u>	8. <u>D</u>	9. <u>E</u>	10. <u>W</u>	11. <u>02</u>

## Second Highest Delta "V"

12. \_\_\_\_\_ 13. \_\_\_\_\_ 14. \_\_\_\_\_ 15. \_\_\_\_\_ 16. \_\_\_\_\_ 17. \_\_\_\_\_ 18. \_\_\_\_\_ 19. \_\_\_\_\_

## CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

## HIGHEST DELTA "V"

20. L 21. C<sub>1</sub> take out C<sub>2</sub> C<sub>3</sub> C<sub>4</sub> C<sub>5</sub> C<sub>6</sub> 22. ±D

320 000 000 005 007 004 000 000 017

## Second Highest Delta "V"

23. L 24. C<sub>1</sub> C<sub>2</sub> C<sub>3</sub> C<sub>4</sub> C<sub>5</sub> C<sub>6</sub> 25. ±D

\_\_\_\_\_ + \_\_\_\_\_

\_\_\_\_\_ - \_\_\_\_\_

26. Undeformed End Width  
(Coded when highest severity  
impact is an end plane impact.) 998  
\_\_\_\_\_ Code to the nearest centimeter  
(250) 250 centimeters or more  
(998) No highest severity end plane impact  
(999) Unknown

27. Direct Damage Width  
(For highest severity impact) 250  
\_\_\_\_\_ Code to the nearest centimeter  
(250) 250 centimeters or more  
(999) Unknown

28. Original Wheelbase 247  
\_\_\_\_\_ Code to the nearest  
centimeter  
(650) 650 centimeters or more  
(999) Unknown  
97.2 inches X 2.54 = 247 centimeters

29. Original Average Track Width 145  
\_\_\_\_\_ Code to the  
nearest centimeter  
(185) 185 centimeters or more  
(999) Unknown  
57.1 inches X 2.54 = 145 centimeters

## FUEL SYSTEM

30. Are CDCs Documented  
but Not Coded on The  
Automated File?

- (0) No  
(1) Yes

31. Researcher's Assessment of Vehicle  
Disposition

- (0) Not towed due to vehicle damage  
(1) Towed due to vehicle damage  
(9) Unknown

32. Is This A Multi-Stage Manufactured Vehicle  
And/Or A Certified Altered Vehicle?

- (0) No post manufacturer modifications  
(1) Yes - post manufacturer modifications  
(specify): \_\_\_\_\_

(Include photograph of CERTIFICATION  
PLACARD in case report)

- (9) Unknown if vehicle is modified

## FIRE OCCURRENCE

33. Fire Occurrence

- (0) No fire

Yes, fire occurred

- (1) Minor  
(2) Major  
(9) Unknown

34. Origin of Fire

- (0) No fire  
(1) Vehicle exterior (front, side, back, top)  
(2) Exhaust system  
(3) Fuel tank (and other fuel retention  
system parts)  
(4) Engine compartment  
(5) Cargo/trunk compartment  
(6) Instrument panel  
(7) Passenger compartment area  
(8) Other location (specify): \_\_\_\_\_

- (9) Unknown

35. Location of Fuel Tank-1 Filler Cap

36. Location of Fuel Tank-2 Filler Cap

- (0) No fuel tank  
(1) On back plane  
(2) Aft of center of the rear wheels (rear axle)  
on left side plane  
(3) Aft of center of the rear wheels (rear axle)  
on right side plane  
(4) Forward of center of the rear wheels (rear  
axle) on left side plane  
(5) Forward of center of the rear wheels (rear  
axle) on right side plane  
(6) Over the center of the rear wheels (rear  
axle) on left side plane  
(7) Over the center of the rear wheels (rear  
axle) on right side plane  
(8) Other (specify): \_\_\_\_\_  
(9) Unknown

37. Type of Fuel Tank-1

38. Type of Fuel Tank-2

- (0) No fuel tank (electrical vehicle)  
(1) Metallic  
(2) Non-metallic  
(9) Unknown

39. Location of Fuel Tank-1

40. Location of Fuel Tank-2

- (0) No fuel tank  
(1) Aft of center of the rear wheels (rear axle)  
centered  
(2) Aft of center of the rear wheels (rear axle)  
left side  
(3) Aft of center of the rear wheels (rear axle)  
right side  
(4) Forward of center of the rear wheels (rear  
axle) centered  
(5) Forward of center of the rear wheels (rear  
axle) left side  
(6) Forward of center of the rear wheels (rear  
axle) right side  
(7) Over center of the rear wheels (rear axle)  
(8) Other (specify): \_\_\_\_\_  
(9) Unknown

41. Damage to Fuel Tank-1

42. Damage to Fuel Tank-2

- (0) No fuel tank  
(1) No damage to fuel tank  
(2) Deformed, no seam failure  
(3) Deformed, with a seam failure  
(4) Punctured  
(5) Lacerated (ripped)  
(6) Abraded (scraped)  
(7) Filler neck separation from the fuel tank  
(8) Other damage (specify): \_\_\_\_\_  
(9) Unknown

**DO NOT COMPLETE THE INTERIOR VEHICLE FORM.**



## INTERIOR VEHICLE FORM

1. Primary Sampling Unit Number 24

2. Case Number - Stratum 1955

3. Vehicle Number 02

### INTEGRITY

4. Passenger Compartment Integrity 06

(00) No integrity loss

Yes, Integrity Was Lost Through

(01) Windshield

(02) Door (side)

(03) Door/hatch (back door)

(04) Roof

(05) Roof glass

(06) Side window

(07) Rear window (backlight)

(08) Roof and roof glass

(09) Windshield and door (side)

(10) Windshield and roof

(11) Side and rear window (side window and backlight)

(12) Windshield and side window

(13) Door and side window

(98) Other combination of above (specify):

(99) Unknown

Door, Tailgate or Hatch Opening

5. LF / 6. RF / 7. LR 0 8. RR 0 9. TG/H 1

(0) No door/gate/hatch

(1) Door/gate/hatch remained closed and operational

(2) Door/gate/hatch came open during collision

(3) Door/gate/hatch jammed shut

(8) Other (specify):

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch Opening in Collision. If IV05-IV09 ≠ 2, Then code Ø

10. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

(0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision

(1) Door operational (no damage)

(2) Latch/striker failure due to damage

(3) Hinge failure due to damage

(4) Door structure failure due to damage

(5) Door support (i.e., pillar, sill, roof side rail, etc.) failure due to damage

(6) Latch/striker and hinge failure due to damage

(8) Other failure (specify):

(9) Unknown

### GLAZING

Type of Window/Windshield Glazing

15. WS 1 16. LF 2 17. RF 2 18. LR 2 19. RR 2

20. BL 2 21. Roof 3 22. Other 0

(0) No glazing

(1) AS-1 — Laminated

(2) AS-2 — Tempered

(3) AS-3 — Tempered-tinted (original)

(4) AS-2 — Tempered-with after market tint

(5) AS-3 — Tempered-tinted (with additional after market tint)

(6) AS-14 — Glass/Plastic

(7) Glazing removed prior to accident

(8) Other (specify):

(9) Unknown

Window Precrash Glazing Status

23. WS 1 24. LF 2 25. RF 2 26. LR / 27. RR /

28. BL 1 29. Roof 2 30. Other 0

(0) No glazing

(1) Fixed

(2) Closed

(3) Partially opened

(4) Fully opened

(7) Glazing removed prior to accident

(9) Unknown

Glazing Damage from Impact Forces

31. WS 2 32. LF 6 33. RF / 34. LR / 35. RR /

36. BL / 37. Roof / 38. Other 0

(0) No glazing

(1) No glazing damage from impact forces

(2) Glazing in place and cracked from impact forces

(3) Glazing in place and holed from impact forces

(4) Glazing out-of-place (cracked or not) and not holed from impact forces

(5) Glazing out-of-place and holed from impact forces

(6) Glazing disintegrated from impact forces

(7) Glazing removed prior to accident

(9) Unknown if damaged

Glazing Damage from Occupant Contact

39. WS 2 40. LF 1 41. RF 1 42. LR / 43. RR /

44. BL / 45. Roof / 46. Other 0

(0) No glazing

(1) No occupant contact to glazing

(2) Glazing contacted by occupant but no glazing damage

(3) Glazing in place and cracked by occupant contact

(4) Glazing in place and holed by occupant contact

(5) Glazing out-of-place (cracked or not) by occupant contact and not holed by occupant contact

(6) Glazing out-of-place by occupant contact and holed by occupant contact

(7) Glazing removed prior to accident

(8) Glazing disintegrated by occupant contact

(9) Unknown if contacted by occupant

**NOTE: SKETCH INTRUDED AREAS**

**NOTE: SKETCH INTRUDED AREAS**



## OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

## INTRUDING COMPONENT

*Interior Components*

- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Side panel - forward of the A1/A2-pillar
- (11) Door panel (side)
- (12) Side panel - rear of the B-pillar
- (13) Roof (or convertible top)
- (14) Roof side rail
- (15) Windshield
- (16) Windshield header
- (17) Window frame
- (18) Floor pan (includes sill)
- (19) Backlight header
- (20) Front seat back
- (21) Second seat back
- (22) Third seat back
- (23) Fourth seat back
- (24) Fifth seat back
- (25) Seat cushion
- (26) Back door/panel (e.g., tailgate)
- (27) Other interior component (specify): \_\_\_\_\_

*Exterior Components*

- (30) Hood
- (31) Outside surface of this vehicle (specify): \_\_\_\_\_
- (32) Other exterior object in the environment (specify): \_\_\_\_\_
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): \_\_\_\_\_
- (99) Unknown

## LOCATION OF INTRUSION

## Front Seat

- (11) Left
- (12) Middle
- (13) Right

## Second Seat

- (21) Left
- (22) Middle
- (23) Right

## Third Seat

- (31) Left
- (32) Middle
- (33) Right

## Fourth Seat

- (41) Left
- (42) Middle
- (43) Right

- (97) Catastrophic
- (98) Other enclosed area (specify) \_\_\_\_\_

(99) Unknown

## MAGNITUDE OF INTRUSION

- (1)  $\geq 3$  centimeters but  $< 8$  centimeters
- (2)  $\geq 8$  centimeters but  $< 15$  centimeters
- (3)  $\geq 15$  centimeters but  $< 30$  centimeters
- (4)  $\geq 30$  centimeters but  $< 46$  centimeters
- (5)  $\geq 46$  centimeters but  $< 61$  centimeters
- (6)  $\geq 61$  centimeters
- (7) Catastrophic
- (9) Unknown

## DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

1st 47. 11 48. 18 49. 2 50. 32nd 51. 11 52. 11 53. 1 54. 33rd 55. 11 56. 06 57. + 58. 3

4th 59. \_\_\_\_\_ 60. \_\_\_\_\_ 61. \_\_\_\_\_ 62. \_\_\_\_\_

5th 63. \_\_\_\_\_ 64. \_\_\_\_\_ 65. \_\_\_\_\_ 66. \_\_\_\_\_

6th 67. \_\_\_\_\_ 68. \_\_\_\_\_ 69. \_\_\_\_\_ 70. \_\_\_\_\_

7th 71. \_\_\_\_\_ 72. \_\_\_\_\_ 73. \_\_\_\_\_ 74. \_\_\_\_\_

8th 75. \_\_\_\_\_ 76. \_\_\_\_\_ 77. \_\_\_\_\_ 78. \_\_\_\_\_

9th 79. \_\_\_\_\_ 80. \_\_\_\_\_ 81. \_\_\_\_\_ 82. \_\_\_\_\_

10th 83. \_\_\_\_\_ 84. \_\_\_\_\_ 85. \_\_\_\_\_ 86. \_\_\_\_\_

# STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE

—

DAMAGE VALUE

=

DEFORMATION

20

—

20

=

0

—

=

—

=

—

=



## STEERING COLUMN

## INSTRUMENT PANEL

87. Steering Column Type 2

- (1) Fixed column  
 (2) Tilt column  
 (3) Telescoping column  
 (4) Tilt and telescoping column  
 (8) Other column type (specify): \_\_\_\_\_

(9) Unknown

88. Tilt Steering Column Adjustment 3

- (0) No tilt steering column  
 (1) Full up  
 (2) Between full up and center  
 (3) Center  
 (4) Between center and full down  
 (5) Full down  
 (9) Unknown

89. Telescoping Steering Column Adjustment 0

- (0) No telescoping steering column  
 (1) Full back  
 (2) Between full back and midpoint  
 (3) Midpoint  
 (4) Between midpoint and full forward  
 (5) Full forward  
 (9) Unknown

90. Steering Rim/Spoke Deformation 00

- Code actual measured  
 deformation to the nearest centimeter  
 (00) No steering rim deformation  
 (01-14) Actual measured value in centimeters  
 (15) 15 centimeters or more  
 (98) Observed deformation cannot be measured  
 (99) Unknown

91. Location of Steering Rim/Spoke Deformation 00

(00) No steering rim deformation



## Quarter Sections

- (01) Section A  
 (02) Section B  
 (03) Section C  
 (04) Section D



## Half Sections

- (05) Upper half of rim/spoke  
 (06) Lower half of rim/spoke  
 (07) Left half of rim/spoke  
 (08) Right half of rim/spoke



- (09) Complete steering wheel collapse  
 (10) Undetermined location  
 (99) Unknown

92. Odometer Reading 093,000

\_\_\_\_\_ kilometers  
 Code to the nearest 1,000 kilometers

- (000) No odometer  
 (001) Less than 1,500 kilometers  
 (500) 499,500 kilometers or more  
 (999) Unknown

57.593 miles X 1.6093 = 92.684 kilometers

Source: [REDACTED]93. Instrument Panel Damage from Occupant Contact? 0

- (0) No  
 (1) Yes  
 (9) Unknown

94. Type of Knee Bolster Covering 1

- (0) No knee bolster  
 (1) Padded  
 (2) Rigid plastic  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown

95. Knee Bolsters Deformed from Occupant Contact? 1

- (0) No knee bolster  
 (1) No deformation  
 (2) Yes - deformation  
 (9) Unknown

96. Did Glove Compartment Door Open During Collision(s)? 1

- (0) No glove compartment door  
 (1) No - door did not open  
 (2) Yes - door opened  
 (9) Unknown





97. Adaptive (Assistive) Driving Equipment 0

- (0) No adaptive driving equipment  
 (1) Adaptive driving equipment installed  
 (Check all that apply.)  
☐ Hand controls for braking/acceleration  
☐ Steering control devices (attached to OEM steering wheel)  
☐ Steering knob attached to steering wheel  
☐ Low effort power steering (unit or device)  
☐ Replacement steering wheel (i.e., reduced diameter)  
☐ Joy-stick steering controls  
☐ Wheelchair tie-downs  
☐ Modification to seat belts (specify): \_\_\_\_\_  
☐ Additional or relocated switches (specify): \_\_\_\_\_  
☐ Raised roof  
☐ Wall-mounted head rest (used behind wheelchair)  
☐ Other adaptive device (specify): \_\_\_\_\_

(9) Unknown

## VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure).

Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.

Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

## POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	051	1	Side	Smudge	3
B	052	1	Side	Smudge	3
C	001	1	Hand	Smudge	3
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

## FRONT

- (001) Windshield  
 (002) Mirror  
 (003) Sunvisor  
 (004) Steering wheel rim  
 (005) Steering wheel hub/spoke  
 (006) Steering wheel (combination of codes 004 and 005)  
 (007) Steering column, transmission selector lever, other attachment  
 (008) Cellular telephone or CB radio  
 (009) Add on equipment (e.g., tape deck, air conditioner)  
 (010) Left instrument panel and below  
 (011) Center instrument panel and below  
 (012) Right instrument panel and below  
 (013) Glove compartment door  
 (014) Knee bolster  
 (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)  
 (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)  
 (017) Windshield reinforced by exterior object, (specify):  
 (019) Other front object (specify):

## CODES FOR INTERIOR COMPONENTS

## LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests  
 (052) Left side hardware or armrest  
 (053) Left A (A1/A2)-pillar  
 (054) Left B-pillar  
 (055) Other left pillar (specify):  
 (056) Left side window glass  
 (057) Left side window frame  
 (058) Left side window sill  
 (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.  
 (060) Other left side object (specify):

## RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests  
 (102) Right side hardware or armrest  
 (103) Right A (A1/A2)-pillar  
 (104) Right B-pillar  
 (105) Other right pillar (specify):  
 (106) Right side window glass  
 (107) Right side window frame  
 (108) Right side window sill  
 (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.  
 (110) Other right side object (specify):

## INTERIOR

- (151) Seat, back support  
 (152) Belt restraint webbing/buckle  
 (153) Belt restraint B-pillar or door frame attachment point  
 (154) Other restraint system component (specify):  
 (155) Head restraint system  
 (160) Other occupants (specify):  
 (161) Interior loose objects  
 (162) Child safety seat (specify):  
 (163) Other interior object (specify):

## AIR BAG

- (170) Air bag-driver side  
 (175) Air bag compartment cover-driver side  
 (180) Air bag-passenger side  
 (185) Air bag compartment cover-passenger side  
 (190) Other air bag (specify):  
 (195) Other air bag compartment cover (specify):

## ROOF

- (201) Front header  
 (202) Rear header  
 (203) Roof left side rail  
 (204) Roof right side rail  
 (205) Roof or convertible top

## FLOOR

- (251) Floor (including toe pan)  
 (252) Floor or console mounted transmission lever, including console  
 (253) Parking brake handle  
 (254) Foot controls including parking brake

## REAR

- (301) Backlight (rear window)  
 (302) Backlight storage rack, door, etc.  
 (303) Other rear object (specify):

## ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration  
 (402) Steering control devices (attached to OEM steering wheel)  
 (403) Steering knob attached to steering wheel  
 (405) Replacement steering wheel (i.e., reduced diameter)  
 (406) Joy stick steering controls  
 (407) Wheelchair tie-downs  
 (408) Modification to seat belts, (specify):  
 (409) Additional or relocated switches, (specify):  
 (410) Raised roof  
 (411) Wall mounted head rest (used behind wheel chair)  
 (412) Other adaptive device (specify):

## CONFIDENCE LEVEL OF CONTACT POINT

- (1) Certain  
 (2) Probable  
 (3) Possible  
 (9) Unknown

## MANUAL RESTRAINTS

**NOTES:** Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a child safety seat is present, encode the data on the back of this page 11.

If the vehicle has automatic restraints available, encode the appropriate data on page 6.

		Left	Center	Right
FIRST	A-Availability	3	X	3
	B-Evidence of usage	3		3
	C-Used in this crash?	0		0
	D-Proper Use	9		0
	E-Failure Modes	0		0
	F-Anchorage Adjustment	0		0
SECOND	A-Availability	4	X	4
	B-Evidence of usage	0		0
	C-Used in this crash?	0		0
	D-Proper Use	0		0
	E-Failure Modes	0		0
	F-Anchorage Adjustment	0		0
OTHER	A-Availability	X	X	X
	B-Evidence of usage			
	C-Used in this crash?			
	D-Proper Use			
	E-Failure Modes			
	F-Anchorage Adjustment			

### A-Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

#### Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)
- (8) Other belt (specify): \_\_\_\_\_

- (9) Unknown

### B/C-Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify): \_\_\_\_\_

- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify): \_\_\_\_\_

- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify): \_\_\_\_\_
- (99) Unknown if belt used

### D-Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

#### Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): \_\_\_\_\_
- (8) Other improper use of manual belt system (specify): \_\_\_\_\_
- (9) Unknown

### E-Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): \_\_\_\_\_
- (6) Broken retractor
- (7) Combination of above (specify): \_\_\_\_\_
- (8) Other manual belt failure (specify): \_\_\_\_\_
- (9) Unknown

### F-Shoulder Belt Upper Anchorage Adjustment

- (0) No shoulder belt
- (1) No upper anchorage adjustment for shoulder belt

#### Adjustable shoulder Belt Upper Anchorage

- (2) In full up position
- (3) In mid position
- (4) In full down position
- (5) Position unknown
- (9) Unknown if position has adjustable upper anchorage adjustment

**AUTOMATIC RESTRAINTS**

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

**AIR BAGS**

		Frontal Air Bags--Left Front	Frontal Air Bags--Right Front	Other Air Bag
F I R S T	Availability/Function			
	Deployment			
	Failure			

**Air Bag System Availability/Function**

- (0) Not equipped/not available  
(1) Air bag

*Non-functional*

- (2) Air bag disconnected (specify):  
\_\_\_\_\_  
(3) Air bag not reinstalled  
(9) Unknown

**Air Bag System Deployment  
(This Occupant Position)**

- (0) Not equipped/not available  
(1) Deployed during accident (as a result of impact)  
(2) Deployed inadvertently just prior to accident  
(3) Deployed, accident sequence undetermined  
(4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
(5) Unknown if deployed  
(7) Nondeployed  
(9) Unknown

**Are There Indications of Air Bag System Failure? (This Occupant Position)**

- (0) Not equipped/not available  
(1) No  
(2) Yes (specify):  
\_\_\_\_\_  
(9) Unknown

**AUTOMATIC BELTS**

		Left	Right
F I R S T	A-Availability/Function	/	/
	B-Use	/	/
	C-Type	2	2
	D-Proper Use	/	/
	E-Failure Modes	/	/

**A-Automatic (Passive) Belt System Availability/Function**

- (0) Not equipped/not available  
(1) 2 point automatic belts  
(2) 3 point automatic belts  
(3) Automatic belts - type unknown

*Non-functional*

- (4) Automatic belts destroyed or rendered inoperative  
(9) Unknown

**B-Automatic (Passive) Belt System Use**

- (0) Not equipped/not available/destroyed or rendered inoperative  
(1) Automatic belt in use  
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)  
(3) Automatic belt use unknown  
(9) Unknown

**C-Automatic (Passive) Belt System Type**

- (0) Not equipped/not available  
(1) Non-motorized system  
(2) Motorized system  
(9) Unknown

**D-Proper Use of Automatic (Passive) Belt System**

- (0) Not equipped/not available/not used  
(1) Automatic belt used properly  
(2) Automatic belt used properly with child safety seat

*Automatic Belt Used Improperly*

- (3) Automatic shoulder belt worn under arm  
(4) Automatic shoulder belt worn behind back  
(5) Automatic belt worn around more than one person  
(6) Lap portion of automatic belt worn on abdomen  
(7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):  
\_\_\_\_\_  
(9) Unknown

**E-Automatic (Passive) Belt Failure Modes During Accident**

- (0) Not equipped/not available/not in use  
(1) No automatic belt failure(s)  
(2) Torn webbing (stretched webbing not included)  
(3) Broken buckle or latchplate  
(4) Upper anchorage separated  
(5) Other anchorage separated (specify):  
\_\_\_\_\_  
(6) Broken retractor  
(7) Combination of above (specify):  
(8) Other automatic belt failure (specify):  
\_\_\_\_\_  
(9) Unknown

## FIRST SEAT FRONTAL AIR BAGS

**NOTES:** Encode the applicable data *for the driver and first seat passenger* in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

	Driver	Passenger
A-Type of air bag?		
B-Flaps open at tear points?		
C-Flaps damaged?		
D-Air bag damaged?		
E-Source of air bag damage		
F-Air bag tethered?		
G-Air bag have vent ports?		
H-Other occupant contact air bag?		
I-Occupant wearing eyewear?		

### A-Type of Air Bag

- (0) Not equipped/not available
- (1) Original manufacturer installed system
- (2) Retrofitted air bag
- (3) Replacement air bag
- (8) Unknown type of air bag
- (9) Unknown

### B-Did Air Bag Module Cover Flap(s) Open At Designated Tear Points?

- (0) Not equipped/not available
- (1) No
- (2) Yes
- (3) Deployed, unknown if flap(s) opened at designated tear points
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### C-Were Air Bag Module Cover Flap(s) Damaged?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if air bag module cover flap(s) damaged
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### D-Was There Damage To The Air Bag?

- (00) Not equipped/not available
- (01) Not damaged

#### Yes - Air Bag Damage

- (02) Ruptured
- (03) Cut
- (04) Torn
- (05) Holed
- (06) Burned
- (07) Abraded
- (88) Other damage (specify):

- (95) Damaged, details unknown
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

### E-Source of Air Bag Damage

- (00) Not equipped/not available
- (01) Not damaged
- (02) Object worn by occupant, (specify):
- (03) Object carried by occupant, (specify):
- (04) Adaptive/assistive controls, (specify):
- (05) Fire in vehicle
- (06) Thermal burns
- (07) Rescue or emergency efforts
- (88) Other damage source (specify):
- (95) Damaged, unknown source
- (96) Deployed, unknown if damaged
- (97) Not deployed
- (98) Unknown if deployed
- (99) Unknown

### F-Was The Air Bag Tethered?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of tether straps):
- (3) Deployed, unknown if tethered
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### G-Did The Air Bag Have Vent Ports?

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify number of vent ports):
- (3) Deployed, unknown if vent ports present
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### H-Was the Air Bag in this Occupant's Position Contacted by Another Occupant?


- (0) Not equipped/not available
- (1) No
- (2) Yes (specify):
- (3) Deployed, unknown if other occupant contact to air bag
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

### I-Was This Occupant Wearing Eye-wear?


- (0) Not equipped/not available
- (1) No
- (2) Eyeglasses/sunglasses
- (3) Contact lenses
- (4) Deployed, unknown if eyewear worn
- (7) Not deployed
- (8) Unknown if deployed
- (9) Unknown

DRIVER AIR BAG DAMAGE AND CONTACT SKETCHES

1. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Front)




2. SKETCH DAMAGE AND CONTACT EVIDENCE ON DRIVER AIR BAG (Back)



## DRIVER AIR BAG SKETCHES (Cont'd)

### 3. DRIVER AIR BAG MODULE COVER FLAP SIZE (SINGLE)


width ( $W_U$ ) \_\_\_\_\_ width ( $W_L$ ) \_\_\_\_\_  
 height ( $H$ ) \_\_\_\_\_



### 4. DRIVER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap                      b. Lower Flap


width ( $W_U$ ) \_\_\_\_\_ width ( $W_L$ ) \_\_\_\_\_  
 height ( $H_U$ ) \_\_\_\_\_ height ( $H_L$ ) \_\_\_\_\_





### 5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

### 6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

### 7. SKETCH LOCATION OF CIRCULAR AIR BAG VENT PORTS






**PASSENGER AIR BAG DAMAGE AND CONTACT SKETCHES****1. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Front)****2. SKETCH DAMAGE AND CONTACT EVIDENCE ON PASSENGER AIR BAG (Back)**

## PASSENGER AIR BAG SKETCHES (Cont'd)

### 3. PASSENGER AIR BAG MODULE COVER FLAP SIZE (SINGLE)

width (W) \_\_\_\_\_

height (H) \_\_\_\_\_



### 4. PASSENGER AIR BAG MODULE COVER FLAP SIZE (DOUBLE)

a. Upper Flap


b. Lower Flap

width ( $W_u$ ) \_\_\_\_\_

width ( $W_l$ ) \_\_\_\_\_

height ( $H_u$ ) \_\_\_\_\_


height ( $H_l$ ) \_\_\_\_\_



### 5. SKETCH OF OTHER TYPE OF AIR BAG MODULE FLAP AND SIZE

### 6. SKETCH OF OTHER TYPE OF AIR BAG VENT PORTS

### 7. SKETCH LOCATION OF RECTANGULAR AIR BAG VENT PORTS



**"OTHER" AIR BAG DAMAGE AND CONTACT SKETCHES**


1. SKETCH DAMAGE AND CONTACT EVIDENCE ON "OTHER" AIR BAG (Front)

2. SKETCH DAMAGE AND CONTACT EVIDENCE ON "OTHER" AIR BAG (Back)

**"OTHER" AIR BAG SKETCHES (Cont'd)**

3. SKETCH AIR BAG MODULE FLAP AND SIZE OR OPENING FOR AIRBAG

4. SKETCH AIR BAG VENT PORTS



**HEAD RESTRAINTS/SEAT EVALUATION**

**NOTES:** Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found on the next page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
<b>FIRST</b>	A-Head Restraint Type/Damage	3		3
	B-Seat Type	2		2
	C-Seat Orientation	1		1
	D-Seat Track Position	6		4
	E-Seat Back Incline Pre/Post Impact	23		23
	F-Seat Performance	1		1
<b>SECOND</b>	A-Head Restraint Type/Damage	0		0
	B-Seat Type	07		07
	C-Seat Orientation	1		1
	D-Seat Track Position	0		0
	E-Seat Back Incline Pre/Post Impact	0		0
	F-Seat Performance	0		0
<b>THIRD</b>	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			
<b>OTHER</b>	A-Head Restraint Type/Damage			
	B-Seat Type			
	C-Seat Orientation			
	D-Seat Track Position			
	E-Seat Back Incline Pre/Post Impact			
	F-Seat Performance			

**DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE  
(I.E., UNUSUAL OCCUPANT CONTACT PATTERN)**

## HEAD RESTRAINTS/SEAT EVALUATION

**A-Head Restraint Type/Damage by Occupant at This Occupant Position**

- (0) No head restraints
- (1) Integral — no damage
- (2) Integral — damaged during accident
- (3) Adjustable — no damage
- (4) Adjustable — damaged during accident
- (5) Add-on — no damage
- (6) Add-on — damaged during accident
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

**B-Seat Type (this Occupant Position)**

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Box mounted seat (i.e., van type)
- (10) Other seat type (specify): \_\_\_\_\_
- (99) Unknown

**C-Seat Orientation (this Occupant Position)**

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

**D-Seat Track Adjusted Position Prior To Impact**

- (0) Occupant not seated or no seat
- (1) Non-adjustable seat track

**Adjustable Seat Track**

- (2) Seat at forward most track position
- (3) Seat between forward most and middle track positions
- (4) Seat at middle track position
- (5) Seat between middle and rear most track positions
- (6) Seat at rear most track position
- (9) Unknown

**E-Seat Back Incline Prior and Post Impact**

- (00) Occupant not seated or no seat
- (01) Not adjustable

**Upright prior to impact**

- (11) Moved to completely rearward position
- (12) Moved to rearward midrange position
- (13) Moved to slightly rearward position
- (14) Retained pre-impact position
- (15) Moved to slightly forward position
- (16) Moved to forward midrange position
- (17) Moved to completely forward position

**Slightly reclined prior to impact**

- (21) Moved to completely rearward position
- (22) Moved to rearward midrange position
- (23) Retained pre-impact position
- (24) Moved to upright position
- (25) Moved to slightly forward position
- (26) Moved to forward midrange position
- (27) Moved to completely forward position




**Completely reclined prior to impact**

- (31) Retained pre-impact position
- (32) Moved to rearward midrange position
- (33) Moved to slightly rearward position
- (34) Moved to upright position
- (35) Moved to slightly forward position
- (36) Moved to forward midrange position
- (37) Moved to completely forward position

- (99) Unknown

**F-Seat Performance (this Occupant Position)**

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): \_\_\_\_\_
- (4) Seat tracks/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): \_\_\_\_\_
- (7) Combination of above (specify): \_\_\_\_\_
- (8) Other (specify): \_\_\_\_\_
- (9) Unknown

Coding diagrams for *Seat Back Incline Position Prior and Post Impact*

DESCRIBE ANY INDICATION OF  
ABNORMAL OCCUPANT POSTURE

(I.E., UNUSUAL OCCUPANT

CONTACT PATTERN)

## CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage						
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model	Specify Below for Each Child Safety Seat					

### 1. Type of Child Safety Seat

- (0) No child safety seat
- (1) Infant seat
- (2) Toddler seat
- (3) Convertible seat
- (4) Booster seat
- (7) Other type child safety seat (specify): \_\_\_\_\_
- (8) Unknown child safety seat type
- (9) Unknown if child safety seat used

### 2. Child Safety Seat Orientation

- (00) No child safety seat
- Designed for Rear Facing for This Age/Weight
- (01) Rear facing
- (02) Forward facing
- (08) Other orientation (specify): \_\_\_\_\_
- (09) Unknown orientation
- Designed for Forward Facing for This Age/Weight
- (11) Rear facing
- (12) Forward facing
- (18) Other orientation (specify): \_\_\_\_\_
- (19) Unknown orientation
- Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
- (21) Rear facing
- (22) Forward facing
- (28) Other orientation (specify): \_\_\_\_\_
- (29) Unknown orientation
- (99) Unknown if child safety seat used

### 3. Child Safety Seat Harness Usage

### 4. Child Safety Seat Shield Usage

- 5. Child Safety Seat Tether Usage
- Note: Options Below Are Used for Variables 3-5.
- (00) No child safety seat

#### Not Designed with Harness/Shield/Tether

- (01) After market harness/shield/tether added, not used
- (02) After market harness/shield/tether used
- (03) Child safety seat used, but no after market harness/shield/tether added
- (09) Unknown if harness/shield/tether added or used

#### Designed With Harness/Shield/Tether

- (11) Harness/shield/tether not used
- (12) Harness/shield/tether used
- (19) Unknown if harness/shield/tether used

#### Unknown If Designed With Harness/Shield/Tether

- (21) Harness/shield/tether not used
- (22) Harness/shield/tether used
- (29) Unknown if harness/shield/tether used

#### (99) Unknown if child safety seat used

- 6. Child Safety Seat Make/Model
- (Specify make/model and occupant number)

---



---



---



---

**EJECTION/ENTRAPMENT DATA**

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

**EJECTION**      No ☒ Yes ☐

Describe indications of ejection and body parts involved in partial ejection(s):

---



---



---



---



---

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

**Ejection**

- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, Unknown degree
- (9) Unknown

**Ejection Area**

- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear

**(7) Roof**

- (8) Other area (e.g., back of pickup, etc.) (specify):

(9) Unknown

**Ejection Medium**

- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify):

**(5) Integral structure**

- (8) Other medium (specify):

(9) Unknown

**Medium Status (Immediately Prior to Impact)**

- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

**ENTRAPMENT**      No ☒ Yes ☐

Describe entrapment mechanism:

---



---



---



---

Component(s):

---

(Note on vehicle interior sketch)





# OCCUPANT ASSESSMENT FORM

1. Primary Sampling Unit Number	<u>24</u>
2. Case Number - Stratum	<u>195J</u>
3. Vehicle Number	<u>02</u>
4. Occupant Number	<u>01</u>

## OCCUPANT'S CHARACTERISTICS

5. Occupant's Age	<u>22</u>
Code actual age at time of accident.	
(00) Less than one year old (specify by month):	
(97) 97 years and older	
(99) Unknown	
6. Occupant's Sex	<u>2</u>
(1) Male	
(2) Female-not reported pregnant	
(3) Female-pregnant-1st trimester(1st-3rd month)	
(4) Female-pregnant-2nd trimester(4th-6th month)	
(5) Female-pregnant-3rd trimester(7th-9th month)	
(6) Female-pregnant-term unknown	
(9) Unknown	
7. Occupant's Height	<u>150</u>
Code actual height to the nearest centimeter.	
(999) Unknown	
<u>59</u> inches X 2.54 = <u>150</u> centimeters	
8. Occupant's Weight	<u>052</u>
Code actual weight to the nearest kilogram.	
(999) Unknown	
<u>115</u> pounds X .4536 = <u>052</u> kilograms	
9. Occupant's Role	<u>1</u>
(1) Driver	
(2) Passenger	
(9) Unknown	

## OCCUPANT'S SEATING

10. Occupant's Seat Position	<u>11</u>
<i>Front Seat</i>	
(11) Left side	
(12) Middle	
(13) Right side	
(14) Other (specify):	
(15) On or in the lap of another occupant	
<i>Second Seat</i>	
(21) Left side	
(22) Middle	
(23) Right side	
(24) Other (specify):	
(25) On or in the lap of another occupant	
<i>Third Seat</i>	
(31) Left side	
(32) Middle	
(33) Right side	
(34) Other (specify):	
(35) On or in the lap of another occupant	
<i>Fourth Seat</i>	
(41) Left side	
(42) Middle	
(43) Right side	
(44) Other (specify):	
(45) On or in the lap of another occupant	
(97) In or on unenclosed area	
(98) Other seat (specify):	
(99) Unknown	
11. Occupant's Posture	<u>0</u>
(0) Normal posture	
<i>Abnormal posture</i>	
(1) Kneeling or standing on seat	
(2) Lying on or across seat	
(3) Kneeling, standing or sitting in front of seat	
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window	
(5) Sitting on a console	
(6) Lying back in a reclined seat position	
(7) Bracing with feet or hands on a surface in front of seat	
(8) Other abnormal posture (specify):	
(9) Unknown	

## EJECTION/ENTRAPMENT

12. Ejection 0

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area 0

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)  
(specify): \_\_\_\_\_
- (9) Unknown

14. Ejection Medium 0

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): \_\_\_\_\_
- (5) Integral structure
- (8) Other medium (specify): \_\_\_\_\_
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) 0

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment 0

- (0) Not entrapped/exit not inhibited
- (1) Entrapped/pinned - mechanically restrained
- (2) Could not exit vehicle due to jammed doors, fire, etc.  
(specify): \_\_\_\_\_
- (9) Unknown

17. Occupant Mobility 4

- (0) Occupant fatal before removed from vehicle
- (1) Removed from vehicle while unconscious or not oriented to time or place
- (2) Removed from vehicle due to perceived serious injuries
- (3) Exited vehicle with some assistance
- (4) Exited vehicle under own power
- (5) Occupant fully ejected
- (8) Removed from vehicle for other reasons  
(specify): \_\_\_\_\_
- (9) Unknown

**BELT SYSTEM FUNCTION****18. Manual (Active) Belt System Availability**

- (0) None available  
 (1) Belt removed/destroyed  
 (2) Shoulder belt  
 (3) Lap belt  
 (4) Lap and shoulder belt  
 (5) Belt available—type unknown

*Integral Belt Partially Destroyed*

- (6) Shoulder belt (lap belt destroyed/removed)  
 (7) Lap belt (shoulder belt destroyed/removed)  
 (8) Other belt (specify): \_\_\_\_\_

(9) Unknown

**19. Manual (Active) Belt System Use**

- (00) None used, not available, or belt removed/destroyed  
 (01) Inoperative (specify): \_\_\_\_\_

- (02) Shoulder belt  
 (03) Lap belt  
 (04) Lap and shoulder belt  
 (05) Belt used—type unknown  
 (08) Other belt used (specify): \_\_\_\_\_

- (12) Shoulder belt used with child safety seat  
 (13) Lap belt used with child safety seat  
 (14) Lap and shoulder belt used with child safety seat  
 (15) Belt used with child safety seat—type unknown  
 (18) Other belt used with child safety seat (specify): \_\_\_\_\_  
 (99) Unknown if belt used

**20. Proper Use of Manual (Active) Belts**

- (0) None used or not available  
 (1) Belt used properly  
 (2) Belt used properly with child safety seat

*Belt Used Improperly*

- (3) Shoulder belt worn under arm  
 (4) Shoulder belt worn behind back or seat  
 (5) Belt worn around more than one person  
 (6) Lap belt worn on abdomen  
 (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): \_\_\_\_\_

(8) Other improper use of manual belt system (specify): \_\_\_\_\_

(9) Unknown

**21. Manual (Active) Belt Failure Modes During Accident**

- (0) No manual belt used or not available  
 (1) No manual belt failure(s)  
 (2) Torn webbing (stretched webbing not included)  
 (3) Broken buckle or latchplate  
 (4) Upper anchorage separated  
 (5) Other anchorage separated (specify): \_\_\_\_\_

(6) Broken retractor  
 (7) Combination of above (specify): \_\_\_\_\_

(8) Other manual belt failure (specify): \_\_\_\_\_

(9) Unknown

**22. Manual Shoulder Belt Upper Anchorage Adjustment**

- (0) No manual shoulder belt  
 (1) No upper anchorage adjustment for manual shoulder belt

*Adjustable shoulder Belt Upper Anchorage*

- (2) In full up position  
 (3) In mid position  
 (4) In full down position  
 (5) Position unknown  
 (9) Unknown if position has adjustable upper anchorage adjustment

**23. Automatic (Passive) Belt System Availability/Function**

- (0) Not equipped/not available  
 (1) 2 point automatic belts  
 (2) 3 point automatic belts  
 (3) Automatic belts - type unknown

*Non-functional*

- (4) Automatic belts destroyed or rendered inoperative  
 (9) Unknown

**24. Automatic (Passive) Belt System Use**

- (0) Not equipped/not available/destroyed or rendered inoperative  
 (1) Automatic belt in use  
 (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): \_\_\_\_\_  
 (3) Automatic belt use unknown  
 (9) Unknown

**25. Automatic (Passive) Belt System Type**

- (0) Not equipped/not available  
 (1) Non-motorized system  
 (2) Motorized system  
 (9) Unknown

**26. Proper Use of Automatic (Passive) Belt System**

- (0) Not equipped/not available/not used  
 (1) Automatic belt used properly  
 (2) Automatic belt used properly with child safety seat

*Automatic Belt Used Improperly*

- (3) Automatic shoulder belt worn under arm  
 (4) Automatic shoulder belt worn behind back  
 (5) Automatic belt worn around more than one person  
 (6) Lap portion of automatic belt worn on abdomen  
 (7) Automatic lap and shoulder belt or

automatic shoulder belt used improperly with child safety seat (specify): \_\_\_\_\_

(8) Other improper use of automatic belt system (specify): \_\_\_\_\_

(9) Unknown

**27. Automatic (Passive) Belt Failure Modes During Accident**

- (0) Not equipped/not available/not in use  
 (1) No automatic belt failure(s)  
 (2) Torn webbing (stretched webbing not included)  
 (3) Broken buckle or latchplate  
 (4) Upper anchorage separated  
 (5) Other anchorage separated (specify): \_\_\_\_\_

(6) Broken retractor  
 (7) Combination of above (specify): \_\_\_\_\_

(8) Other automatic belt failure (specify): \_\_\_\_\_

(9) Unknown

## POLICE REPORTED RESTRAINT USE

## 28. Police Reported Belt Use

- (0) None used  
 (1) Police did not indicate belt use  
 (2) Shoulder belt  
 (3) Lap belt  
 (4) Lap and shoulder belt  
 (5) Belt used, type not specified  
 (6) Child safety seat  
 (7) Automatic belt  
 (8) Other type belt, (specify):

(9) Police indicated "unknown"

## 29. Police Reported Air Bag Availability/Function

- (0) No air bag available  
 (1) Police did not indicate air bag availability/function  
 (2) Deployed  
 (3) Not deployed  
 (4) Unknown if deployed  
 (9) Police indicated "unknown"

Check the Primary Source Used In Determining Belt Use.

- [ ☒ ] Vehicle inspection  
 [ ☐ ] Official injury data  
 [ ☐ ] Driver/occupant interview  
 [ ☐ ] Other (specify):

[ ☐ ] Unknown if belt used

## AIR BAG SYSTEM FUNCTION

## 30. Frontal Air Bag System

Availability/Function  
 (This Occupant Position)

- (0) Not equipped/not available  
 (1) Air bag

*Non-functional*

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled  
 (9) Unknown

31. Frontal Air Bag System Deployment  
(This Occupant Position)

- (0) Not equipped/not available  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

32. Other Than First Seat Frontal Air Bag  
Availability/Function  
(This Occupant Position)

- (0) Not equipped/not available  
 (1) Air bag

*Non-functional*

- (2) Air bag disconnected (specify):

- (3) Air bag not reinstalled  
 (9) Unknown

*Specify type of "other" air bag present:*

## 33. Air Bag(s) Deployment, Other Than First Seat Frontal (This Occupant Position)

- (0) Not equipped with an "other" air bag  
 (1) Deployed during accident (as a result of impact)  
 (2) Deployed inadvertently just prior to accident  
 (3) Deployed, details unknown  
 (4) Deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)  
 (5) Unknown if deployed  
 (7) Nondeployed  
 (9) Unknown

34. Are There Indications of Air Bag System Failure?  
(This Occupant Position)

- (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify):

(9) Unknown

## FIRST SEAT FRONTAL AIR BAG SYSTEM EVALUATION

35. Had Vehicle Been in Previous Accident(s)? 0

- (0) Not equipped/not available  
(1) No previous accidents

Yes

- (2) Previous accident(s) without deployment(s)  
(3) One previous accident with deployment  
(4) More than one previous accident with at least one deployment  
(8) Previous accidents, unknown deployment status  
(9) Unknown

36. Type of Air Bag 0

- (0) Not equipped/not available  
(1) Original manufacturer installed system  
(2) Retrofitted air bag  
(3) Replacement air bag  
(8) Unknown type of air bag  
(9) Unknown

37. Had Any Prior Maintenance/Service Been Performed On This Air Bag System? 0

- (0) Not equipped/not available  
(1) No prior maintenance  
(2) Yes, prior maintenance (specify):  
\_\_\_\_\_  
(9) Unknown

38. Air Bag Deployment Accident Event Sequence Number 00

- (00) Not equipped/not available  
\_\_\_\_\_  
Code the accident event sequence number that initiated the air bag deployment  
(96) Deployed, unknown event  
(97) Not deployed  
(98) Unknown if deployed  
(99) Unknown

39. CDC For Air Bag Deployment Impact 0

- (0) Not equipped/not available  
(1) Highest delta V  
(2) Second highest delta V  
(3) Other non-coded delta V (specify):  
\_\_\_\_\_  
(6) Deployed, unknown event  
(7) Not deployed  
(8) Unknown if deployed  
(9) Unknown

40. Longitudinal Component of Delta V For Air Bag Deployment Impact + 000

- (\_000) Not equipped/not available  
Code the value of the delta V for the impact that initiated the air bag deployment  
(\_996) Deployment, unknown longitudinal Delta V  
(\_997) Not deployed  
(\_998) Unknown if deployed  
(\_999) Unknown

41. Did Air Bag Module Cover Flap(s) Open At Designated Tear Points? 0

- (0) Not equipped/not available  
(1) No  
(2) Yes  
(3) Deployed, unknown if flap(s) opened at designated tear points  
(7) Not deployed  
(8) Unknown if deployed  
(9) Unknown

42. Were Air Bag Module Cover Flap(s) Damaged? 0

- (0) Not equipped/not available  
(1) No  
(2) Yes (specify):  
(3) Deployed, unknown if air bag module cover flap(s) damaged  
(7) Not deployed  
(8) Unknown if deployed  
(9) Unknown

43. Was There Damage To The Air Bag? 00

- (00) Not equipped/not available  
(01) Not damaged

Yes - Air Bag Damage

- (02) Ruptured  
(03) Cut  
(04) Torn  
(05) Holed  
(06) Burned  
(07) Abraded  
(88) Other damage (specify):  
\_\_\_\_\_  
(95) Damaged, details unknown  
(96) Deployed, unknown if damaged  
(97) Not deployed  
(98) Unknown if deployed  
(99) Unknown

**FIRST SEAT FRONTAL AIR BAG SYSTEM  
EVALUATION** *continued*

44. Source of Air Bag Damage 00  
 (00) Not equipped/not available  
 (01) Not damaged  
 (02) Object worn by occupant, (specify):  
 (03) Object carried by occupant, (specify):  
 (04) Adaptive/assistive controls, (specify):  
 (05) Fire in vehicle  
 (06) Thermal burns  
 (07) Rescue or emergency efforts  
 (08) Other damage source (specify):  
 (95) Damaged, unknown source  
 (96) Deployed, unknown if damaged  
 (97) Not deployed  
 (98) Unknown if deployed  
 (99) Unknown
45. Was The Air Bag Tethered? 0  
 (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify number of tether straps):  
 (3) Deployed, unknown if tethered  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown
46. Did The Air Bag Have Vent Ports? 0  
 (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify number of vent ports):  
 (3) Deployed, unknown if vent ports present  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown
47. Was the Air Bag in this Occupant's Position Contacted by Another Occupant? 0  
 (0) Not equipped/not available  
 (1) No  
 (2) Yes (specify):  
 (3) Deployed, unknown if other occupant contact to air bag  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown
48. Was This Occupant Wearing Eye-wear? 2  
 (0) Not air bag equipped/air bag not available  
 (1) No  
 (2) Eyeglasses/sunglasses  
 (3) Contact lenses  
 (4) Deployed, unknown if eyewear worn  
 (7) Not deployed  
 (8) Unknown if deployed  
 (9) Unknown

**HEAD RESTRAINT AND SEAT EVALUATION**


49. Head Restraint Type/Damage by Occupant at This Occupant Position 3  
 (0) No head restraints  
 (1) Integral—no damage  
 (2) Integral—damaged during accident  
 (3) Adjustable—no damage  
 (4) Adjustable—damaged during accident  
 (5) Add-on—no damage  
 (6) Add-on—damaged during accident  
 (8) Other (specify):  
 (9) Unknown
50. Seat Type (this Occupant Position) 02  
 (00) Occupant not seated or no seat  
 (01) Bucket  
 (02) Bucket with folding back  
 (03) Bench  
 (04) Bench with separate back cushions  
 (05) Bench with folding back(s)  
 (06) Split bench with separate back cushions  
 (07) Split bench with folding back(s)  
 (08) Pedestal (i.e., column supported)  
 (09) Box mounted seat (i.e., van type)  
 (10) Other seat type (specify):  
 (99) Unknown
51. Seat Orientation (this Occupant Position) 1  
 (0) Occupant not seated or no seat  
 (1) Forward facing seat  
 (2) Rear facing seat  
 (3) Side facing seat (inward)  
 (4) Side facing seat (outward)  
 (8) Other (specify):  
 (9) Unknown
52. Seat Track Adjusted Position Prior To Impact 6  
 (0) Occupant not seated or no seat  
 (1) Non-adjustable seat track
- Adjustable Seat Track*  
 (2) Seat at forward most track position  
 (3) Seat between forward most and middle track positions  
 (4) Seat at middle track position  
 (5) Seat between middle and rear most track positions  
 (6) Seat at rear most track position  
 (9) Unknown

**HEAD RESTRAINT AND SEAT EVALUATION** *continued*53. Seat Back Incline Prior and Post Impact 23


- (00) Occupant not seated or no seat  
 (01) Not adjustable

***Upright prior to impact***


- (11) Moved to completely rearward position  
 (12) Moved to rearward midrange position  
 (13) Moved to slightly rearward position  
 (14) Retained pre-impact position  
 (15) Moved to slightly forward position  
 (16) Moved to forward midrange position  
 (17) Moved to completely forward position

***Slightly reclined prior to impact***

- (21) Moved to completely rearward position  
 (22) Moved to rearward midrange position  
 (23) Retained pre-impact position  
 (24) Moved to upright position  
 (25) Moved to slightly forward position  
 (26) Moved to forward midrange position  
 (27) Moved to completely forward position

***Completely reclined prior to impact***

- (31) Retained pre-impact position  
 (32) Moved to rearward midrange position  
 (33) Moved to slightly rearward position  
 (34) Moved to upright position  
 (35) Moved to slightly forward position  
 (36) Moved to forward midrange position  
 (37) Moved to completely forward position  
 (99) Unknown

54. Seat Performance (this Occupant Position) 1

- (0) Occupant not seated or no seat  
 (1) No seat performance failure(s)  
 (2) Seat adjusters failed  
 (3) Seat back folding locks or "seat back" failed (specify): \_\_\_\_\_  
 (4) Seat track/anchors failed  
 (5) Deformed by impact of occupant  
 (6) Deformed by passenger compartment intrusion, (specify): \_\_\_\_\_  
 (7) Combination of above (specify): \_\_\_\_\_  
 (8) Other (specify): \_\_\_\_\_  
 (9) Unknown

## CHILD SAFETY SEAT

55. Child Safety Seat Make/Model

(000) No child safety seat

Applicable codes are found in your NASS CDS  
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

56. Type of Child Safety Seat

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat - with shield

(5) Booster seat - without shield

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

57. Child Safety Seat Orientation

(00) No child safety seat

*Designed for Rear Facing for This Age/Weight*

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation

*Designed For Forward Facing for This Age/Weight*

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation

*Unknown Design or Orientation For This  
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

58. Child Safety Seat Harness Usage

59. Child Safety Seat Shield Usage

60. Child Safety Seat Tether Usage

Note: Options below applicable to  
Variables OA58-OA60.

(00) No child safety seat

*Not Designed With Harness/Shield/Tether*(01) After market harness/shield/tether  
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market  
harness/shield/tether added(09) Unknown if harness/shield/tether  
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

*Unknown If Designed With Harness/Shield/Tether*

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used



**INJURY CONSEQUENCES**

## 61. Injury Severity (Police Rating)

- (0) O - No injury  
 (1) C - Possible injury  
 (2) B - Nonincapacitating injury  
 (3) A - Incapacitating injury  
 (4) K - Killed  
 (5) U - Injury, severity unknown  
 (6) Died prior to accident  
 (9) Unknown

## 62. Treatment - Mortality

- (0) No treatment  
 (1) Fatal  
 (2) Fatal - ruled disease (specify):  
 \_\_\_\_\_

*Nonfatal*

- (3) Hospitalization  
 (4) Transported and released  
 (5) Treatment at scene - nontransported  
 (6) Treatment later  
 (7) Treatment - other (specify):  
 \_\_\_\_\_  
 (8) Transported to a medical facility-unknown if treated  
 (9) Unknown

63. Type Of Medical Facility (for Initial Treatment) 2

- (0) Not treated at a medical facility  
 (1) Trauma center  
 (2) Hospital  
 (3) Medical clinic  
 (4) Physician's office  
 (5) Treatment later at medical facility  
 (8) Other (specify):  
 \_\_\_\_\_

## (9) Unknown

## 64. Hospital Stay

- (00) Not Hospitalized  
 \_\_\_\_\_ Code the number of days (up through 60) that the occupant stayed in hospital.  
 (61) 61 days or more  
 (99) Unknown

## 65. Working Days Lost

- \_\_\_\_\_ Code the number of days (up through 60) that the occupant lost from work due to the accident  
 (00) No working days lost  
 (61) 61 days or more  
 (62) Fatally injured  
 (97) Not working prior to accident  
 (99) Unknown

**EMERGENCY RESPONSE INFORMATION**

## EMS Notification

- (1) Not notified  
 (2) Notified  
 (9) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS NotificationTime (first unit)

- (9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Arrival Time (first unit)

- (9998) EMS cancelled or did not arrive

- (9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Departure Time To

Treatment Facility (transporting unit)

- (9997) EMS arrived, provided treatment, but did not transport

- (9998) EMS arrived, but was not used

- (9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Arrival Time At

Treatment Facility

- (9999) Unknown

ROAD VEHICLE

AIR VEHICLE

## EMS Type

- (01) Fire department  
 (02) Rescue squad  
 (03) Police department  
 (04) Trauma unit  
 (05) Disaster unit  
 (06) Ambulance service unit  
 (07) Hospital  
 (08) Mortuaries/funeral homes  
 (98) Other, specify: \_\_\_\_\_  
 (99) Unknown

FIRST UNIT

TRANSPORTING UNIT

ROAD VEHICLE

AIR VEHICLE

## EMS Care

- (01) No care administered  
 (02) First aid  
 (03) Resuscitation  
 (04) CPR  
 (05) Emergency cardiac care  
 (06) Life support system monitoring (blood pressure, pulse rate, respiration, EKG)  
 (07) Emergency burn care  
 (08) Combination of above, specify: \_\_\_\_\_  
 (98) Other, specify: \_\_\_\_\_  
 (99) Unknown

ON-SCENE

DURING TRANSPORT

ROAD VEHICLE

AIR VEHICLE

**STOP WORK HERE VARIABLES 66-74 TO BE CODED BY THE ZONE CENTER**

**TO BE CODED BY THE ZONE CENTER****INJURY CONSEQUENCES****TRAUMA DATA**

66. Time to Death 00  
 Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)  
 (00) Not fatal  
 (96) Fatal - ruled disease  
 (99) Unknown

67. 1st Medically Reported Cause of Death 00

68. 2nd Medically Reported Cause of Death 00

69. 3rd Medically Reported Cause of Death 00  
 Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death  
 (00) Not fatal or no additional causes  
 (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

70. Number of Recorded Injuries for This Occupant 04  
 Code the actual number of injuries recorded for this occupant.  
 (00) No recorded injuries  
 (97) Injured, details unknown  
 (99) Unknown if injured

71. Glasgow Coma Scale (GCS) Score 15  
 (at Medical Facility)  
 (00) Not injured  
 (01) Injured - not treated at medical facility  
 (02) No GCS Score at medical facility  
 (03-15) Code the actual value of the initial GCS Score recorded at medical facility.  
 (97) Injured, details unknown  
 (99) Unknown if injured

72. Was the Occupant Given Blood? 1  
 (1) No - blood not given  
 (2) Yes - blood given  
 (specify units):  
 (9) Unknown if blood given

73. Arterial Blood Gases (ABG) - HCO<sub>3</sub> 01  
 (00) Not injured  
 (01) Injured, ABGs not measured or reported  
 (02-50) Code the actual value of the HCO<sub>3</sub>  
 (96) ABGs reported, HCO<sub>3</sub> unknown  
 (97) Injured, details unknown  
 (99) Unknown if injured

**BELT USE DETERMINATION**

74. Primary Source of Belt Use Determination 1  
 (0) Not equipped/not available/destroyed or rendered inoperative  
 (1) Vehicle inspection  
 (2) Official injury data  
 (3) Driver/occupant interview  
 (8) Other (specify):  
 (9) Unknown if belt used

## OCCUPANT INJURY FORM

1. Primary Sampling Unit Number

74

3. Vehicle Number

02

2. Case Number - Stratum

195I

4. Occupant Number

01

### INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. 3	6. 1	7. 9	8. 04	9. 02	10. 1	11. 2	12. 203	13. 2	14. 1	15. 00
2nd	16. 3	17. 6	18. 4	19. 06	20. 78	21. 1	22. 8	23. 603	24. 2	25. 3	26. 00
3rd	27. 7	28. 7	29. 9	30. 04	31. 02	32. 1	33. 2	34. 051	35. 1	36. 1	37. 02
4th	38. 7	39. 8	40. 9	41. 04	42. 02	43. 1	44. 2	45. 051	46. 1	47. 1	48. 02
5th	49. ____	50. ____	51. ____	52. ____	53. ____	54. ____	55. ____	56. ____	57. ____	58. ____	59. ____
6th	60. ____	61. ____	62. ____	63. ____	64. ____	65. ____	66. ____	67. ____	68. ____	69. ____	70. ____
7th	71. ____	72. ____	73. ____	74. ____	75. ____	76. ____	77. ____	78. ____	79. ____	80. ____	81. ____
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____
10th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____

# OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90					Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
		Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity					
11th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
12th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
13th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
14th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
15th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
16th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
17th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
18th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
19th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
20th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
21st	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
22nd	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
23rd	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
24th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —
25th	—	—	—	— — —	— — —	—	—	— — — — —	—	—	— — —

**OCCUPANT INJURY CLASSIFICATION**

Body Region	Specific Anatomic Structure	Level of Injury	Aspect
(1) Head		Specific injuries are assigned consecutive	(1) Right
(2) Face		two-digit numbers beginning with 02.	(2) Left
(3) Neck	<u>Vessels, Nerves, Organs.</u>		(3) Bilateral
(4) Thorax	<u>Bones, Joints</u> are assigned		(4) Central
(5) Abdomen	consecutive two digit		(5) Anterior
(6) Spine	numbers beginning with	To the extent possible,	(6) Posterior
(7) Upper Extremity	02.	within the organizational	(7) Superior
(8) Lower Extremity		framework of the AIS, 00	(8) Inferior
(9) Unspecified	The exceptions to this rule	is assigned to an injury	(9) Unknown
	apply to:	NFS as to severity or	(0) Whole region
		where only one injury is	
		given in the dictionary for	
		that anatomic structure.	
		99 is assigned to any	
		injury NFS as to lesion or	
		severity.	
<b>Type of Anatomic Structure</b>	<u>Whole Area</u>	<b>Abbreviated Injury Scale</b>	
(1) Whole Area	(02) Skin - Abrasion	(1) Minor Injury	
(2) Vessels	(04) Skin - Contusion	(2) Moderate Injury	
(3) Nerves	(06) Skin - Laceration	(3) Serious Injury	
(4) Organs (includes Muscles/ligaments)	(08) Skin - Avulsion	(4) Severe Injury	
(5) Skeletal (includes joints)	(10) Amputation	(5) Critical Injury	
(6) Head - LOC	(20) Burn	(6) Maximum	
(9) Skin	(30) Crush	(untreatable)	
	(40) Degloving	(7) Injured, unknown	
	(50) Injury - NFS	severity	
	(90) Trauma, other than mechanical		
	<u>Head - LOC</u>		
	(02) Length of LOC		
	(04) Level		
	(06) of		
	(08) Consciousness		
	(10) Concussion		
	<u>Spine</u>		
	(02) Cervical		
	(04) Thoracic		
	(06) Lumbar		

SOURCE OF INJURY DATA	INJURY SOURCE CONFIDENCE LEVEL	DIRECT/INDIRECT INJURY
<b><u>OFFICIAL RECORDS</u></b> (1) Autopsy records with or without hospital/medical records (2) Hospital/medical records other than emergency room (e.g., discharge summary) (3) Emergency room records only (including associated X-rays or other lab reports) (4) Private physician, walk-in or emergency clinic  <b><u>UNOFFICIAL RECORDS</u></b> (5) Lay coroner report (6) E.M.S. personnel (7) Interviewee (8) Other source (specify):  (9) Police	(1) Certain (2) Probable (3) Possible (9) Unknown	(1) Direct contact injury (2) Indirect contact injury (3) Noncontact injury (7) Injured, unknown source

## INJURY SOURCES

### FRONT

- (001) Windshield
- (002) Mirror
- (003) Sunvisor
- (004) Steering wheel rim
- (005) Steering wheel hub/spoke
- (006) Steering wheel (combination of codes 004 and 005)
- (007) Steering column, transmission selector lever, other attachment
- (008) Cellular telephone or CB radio
- (009) Add on equipment (e.g., tape deck, air conditioner)
- (010) Left instrument panel and below
- (011) Center instrument panel and below
- (012) Right instrument panel and below
- (013) Glove compartment door
- (014) Knee bolster
- (015) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (016) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (017) Windshield reinforced by exterior object (specify): \_\_\_\_\_
- (019) Other front object (specify): \_\_\_\_\_

### LEFT SIDE

- (051) Left side interior surface, excluding hardware or armrests
- (052) Left side hardware or armrest
- (053) Left A (A1/A2)-pillar
- (054) Left B-pillar
- (055) Other left pillar (specify): \_\_\_\_\_
- (056) Left side window glass
- (057) Left side window frame
- (058) Left side window sill
- (059) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (060) Other left side object (specify): \_\_\_\_\_

### RIGHT SIDE

- (101) Right side interior surface, excluding hardware or armrests

- (102) Right side hardware or armrest
- (103) Right A (A1/A2)-pillar
- (104) Right B-pillar
- (105) Other right pillar (specify): \_\_\_\_\_
- (106) Right side window glass
- (107) Right side window frame
- (108) Right side window sill
- (109) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (110) Other right side object (specify): \_\_\_\_\_

### INTERIOR

- (151) Seat, back support
- (152) Belt restraint webbing/buckle
- (153) Belt restraint B-pillar or door frame attachment point
- (154) Other restraint system component (specify): \_\_\_\_\_
- (155) Head restraint system
- (160) Other occupants (specify): \_\_\_\_\_
- (161) Interior loose objects
- (162) Child safety seat (specify): \_\_\_\_\_
- (163) Other interior object (specify): \_\_\_\_\_

### AIR BAG

- (170) Air bag-driver side
- (171) Air bag-driver side and eyewear
- (172) Air bag-driver side and jewelry
- (173) Air bag-driver side and object held
- (174) Air bag-driver side and object in mouth
- (175) Air bag compartment cover-driver side
- (176) Air bag compartment cover-driver side and eyewear
- (177) Air bag compartment cover-driver side and jewelry
- (178) Air bag compartment cover-driver side and object held
- (179) Air bag compartment cover-driver side and object in mouth
- (180) Air bag-passenger side
- (181) Air bag-passenger side and eyewear
- (182) Air bag-passenger side and jewelry

- (183) Air bag-passenger side and object held
- (184) Air bag-passenger side and object in mouth
- (185) Air bag compartment cover-passenger side
- (186) Air bag compartment cover-passenger side and eyewear
- (187) Air bag compartment cover-passenger side and jewelry
- (188) Air bag compartment cover-passenger side and object held
- (189) Air bag compartment cover-passenger side and object in mouth
- (190) Other air bag (specify) \_\_\_\_\_
- (195) Other air bag compartment cover (specify) \_\_\_\_\_

### ROOF

- (201) Front header
- (202) Rear header
- (203) Roof left side rail
- (204) Roof right side rail
- (205) Roof or convertible top
- (251) Floor (including toe pan)
- (252) Floor or console mounted transmission lever, including console
- (253) Parking brake handle
- (254) Foot controls including parking brake

### REAR

- (301) Backlight (rear window)
- (302) Backlight storage rack, door, etc.
- (303) Other rear object (specify): \_\_\_\_\_

### ADAPTIVE (ASSISTIVE) DRIVING EQUIPMENT

- (401) Hand controls for braking/acceleration
- (402) Steering control devices (attached to OEM steering wheel)
- (403) Steering knob attached to steering wheel
- (405) Replacement steering wheel (i.e., reduced diameter)
- (406) Joy stick steering controls
- (407) Wheelchair tie-downs
- (408) Modification to seat belts, (specify): \_\_\_\_\_
- (409) Additional or relocated switches, (specify): \_\_\_\_\_
- (410) Raised roof

- (411) Wall mounted head rest (used behind wheel chair)
- (412) Other adaptive device (specify): \_\_\_\_\_

### EXTERIOR of OCCUPANT'S VEHICLE

- (451) Hood
- (452) Outside hardware (e.g., outside mirror, antenna)
- (453) Other exterior surface or tires (specify): \_\_\_\_\_
- (454) Unknown exterior objects

### EXTERIOR OF OTHER MOTOR VEHICLE

- (501) Front bumper
- (502) Hood edge
- (503) Other front of vehicle (specify): \_\_\_\_\_
- (504) Hood
- (505) Hood ornament
- (506) Windshield, roof rail, A-pillar
- (507) Side surface
- (508) Side mirrors
- (509) Other side protrusions (specify): \_\_\_\_\_
- (510) Rear surface
- (511) Undercarriage
- (512) Tires and wheels
- (513) Other exterior of other motor vehicle (specify): \_\_\_\_\_
- (514) Unknown exterior of other motor vehicle

### OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (551) Ground
- (598) Other vehicle or object (specify): \_\_\_\_\_
- (599) Unknown vehicle or object

### NONCONTACT INJURY

- (601) Fire in vehicle
- (602) Flying glass
- (603) Other noncontact injury source (specify): \_\_\_\_\_
- (604) Air bag exhaust gases
- (697) Injured, unknown source

# OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)

Restrained?

☐ No  
☒ Yes

Blood Alcohol Level  
(mg/dl)

BAL = ?

Glasgow Coma  
Scale Score


GCSS = 15

Units of Blood  
Given

Units = 0



Arterial Blood Gases

pH =      
PO<sub>2</sub> =      
PCO<sub>2</sub> =      
HCO<sub>3</sub> =    



## OFFICIAL INJURY DATA — SKELETAL INJURIES



Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





## OFFICIAL INJURY DATA – INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





# SMASH PROGRAM SUMMARY

(All Measurements In Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM

## Identifying Title

74

Primary  
Sampling Unit

195J

Case No.-Stratum

01

Accident Event  
Sequence No.

01 01 96

Date (Month, day, year) of Run

## GENERAL INFORMATION

### VEHICLE 1

NASS Vehicle Number

Year

Make

Model

Body Style

CDC

Damaged Side

PDOF

Heading Angle

01  
1995  
Plymouth  
Voyager  
02 F D E W T  
01  
40 ± +50°  
± 90°

### VEHICLE 2

NASS Vehicle Number

Year

Make

Model

Body Style

CDC

Damaged Side

PDOF

Heading Angle

02  
1990  
Eagle  
Talon  
10 3H  
1 L L D E W 2  
-50 ± -40°  
± 0°

## VEHICLE SPECIFICATIONS

### VEHICLE 1

Wheelbase

Overall Length

Overall Width

Weight

1557 <sup>EST</sup> 88 + 88 = 1645 kg  
Curb Occupant(s) Cargo

Engine Displacement

Drive System

Size

Stiffness

285 cm  
452 cm  
183 cm  
3.0 L  
RWD  
4  
7

### VEHICLE 2

Wheelbase

Overall Length

Overall Width

Weight

1202 52 + 52 = 1254 kg  
Curb Occupant(s) Cargo

Engine Displacement

Drive System

Size

Stiffness

247 cm  
438 cm  
170 cm  
2.0 L  
FWD  
2  
2

## DAMAGE INFORMATION

### VEHICLE 1

Damage known?

Damage Length

Damage Offset

Crush Depth:

177 cm  
± 0 cm  
19 C1 76 cm  
16 C2 75 cm  
14 C3 74 cm  
12 C4 73 cm  
9 C5 7 cm  
9 C6 7 cm

### VEHICLE 2

Damage known?

Damage Length

Damage Offset

Crush Depth:

320 cm  
± +165 cm  
C1 0 cm  
C2 0 cm  
C3 0 cm  
C4 0 cm  
C5 0 cm  
C6 0 cm  
*used CDC Field Duplicate only*

## SCENE INFORMATION

		Rest and Impact Positions [ ] No [ ] Yes				Rest and Impact Positions [ ] No [ ] Yes	
	VEHICLE 1				VEHICLE 2		
Rest	X	8.5	m	Rest	X	8.6	m
Position	Y	10	m	Position	Y	6.1	m
	PSI	-146	°		PSI	-134	°
Impact	X	14.5	m	Impact	X	15.3	m
Position	Y	17.2	m	Position	Y	13.7	m
	PSI	-90	°		PSI	180	°
Slip Angle (-180 to +180)		°		Slip Angle (-180 to +180)		°	

## VEHICLE MOTION

Sustained Contact [X] No [ ] Yes		Sustained Contact [X] No [ ] Yes	
VEHICLE 1		VEHICLE 2	
Vehicle Rotation [ ] No [ ] Yes		Vehicle Rotation [ ] No [ ] Yes	
Rotation Stop Before Rest [ ] No [ ] Yes		Rotation Stop Before Rest [ ] No [ ] Yes	
End of Rotation X	_____ m	End of Rotation X	_____ m
Position Y	_____ m	Position Y	_____ m
PSI	_____ °	PSI	_____ °
Curved Path [ ] No [ ] Yes		Curved Path [ ] No [ ] Yes	
Point on Path X	_____ m	Point on Path X	_____ m
Y	_____ m	Y	_____ m
Rotation Direction [ ] None [ ] CW [ ] CCW		Rotation Direction [ ] None [ ] CW [ ] CCW	
Rotation >360° [ ] No [ ] Yes		Rotation >360° [ ] No [ ] Yes	

## FRICTION INFORMATION

Coefficient of Friction  
Rolling Resistance Option

Ice/snow .35  
1

Vehicle 1 Rolling Resistance

LF .8 RF .8  
LR .8 RR .8

Vehicle 2 Rolling Resistance

LF .50 RF .35  
LR .03 RR .03

IF THIS COMMON IMPACT WAS WITH A CDS VEHICLE NOT IN TRANSPORT, FILL IN THE INFORMATION BELOW.

Model Year: \_\_\_\_\_

Make: \_\_\_\_\_

Model: \_\_\_\_\_

VIN: \_\_\_\_\_

The Weight, CDC, Scene Data and Damage  
Information for this vehicle should be recorded above.

**Complete and ATTACH the appropriate  
damage sketch and dimensions to the form.**

Summary of Results Using Damage

74195j

Speed Change  
(Damage)

Vehicle #1

Total 18 km/h ( 11 mph)  
 Longitudinal -14 km/h ( -9 mph)  
 Latitudinal -12 km/h ( -7 mph)  
 PDOF Angle 40 °  
 Energy Dissipated = 40388 Joules ( 29785 Ft-Lb)  
 Barrier Equivalent Speed = 15.9 km/h ( 9.9 mph)  
 Calculated using size and stiffness categories.

Vehicle #2

Total 24 km/h ( 15 mph)  
 Longitudinal -15 km/h ( -10 mph)  
 Latitudinal 18 km/h ( 11 mph)  
 PDOF Angle -50 °  
 Energy Dissipated = 42950 Joules ( 31674 Ft-Lb)  
 Barrier Equivalent Speed = 28.6 km/h ( 17.8 mph)  
 Calculated using size and stiffness categories.

General Information

	Vehicle #1	Vehicle #2
Year	1995	1990
Make	Plymouth	Eagle
Model	Voyager	Talon
CDC	01FDEW1	10LDEW2
Side Damaged	F	L
PDOF Angle	40 °	-50 °
Heading Angle	-90 °	180 °

Calculation method:	Size and Stiffness	Size and Stiffness
Size Category	4	2
Stiffness Category	7	2
Vehicle Weight	1645 kgs ( 3627 lbs)	1254 kgs ( 2765 lbs)


# Damage Information

	Vehicle #1	Vehicle #2
	Yes	Yes
Vehicle Damage Known		
Crush Length	177.0 cm ( 70 in)	320.0 cm ( 126 in)
C1	16.0 cm ( 6 in)	0.0 cm ( 0 in)
C2	15.0 cm ( 6 in)	0.0 cm ( 0 in)
C3	14.0 cm ( 6 in)	0.0 cm ( 0 in)
C4	12.0 cm ( 5 in)	0.0 cm ( 0 in)
C5	8.0 cm ( 3 in)	0.0 cm ( 0 in)
C6	6.0 cm ( 2 in)	0.0 cm ( 0 in)
D	0.0 cm ( 0 in)	17.0 cm ( 7 in)
D'	-13.2 cm ( -5 in)	17.0 cm ( 7 in)


# Vehicle Dimensions

	Vehicle #1	Vehicle #2
Length	452.5 cm ( 178 in)	438.0 cm ( 172 in)
Width	183.0 cm ( 72 in)	168.9 cm ( 66 in)
Wheelbase	285.3 cm ( 112 in)	246.9 cm ( 97 in)
Weight	1645 kgs ( 3627 lbs)	1254 kgs ( 2765 lbs)
CG to Front of Veh	251.0 cm ( 99 in)	211.6 cm ( 83 in)
Engine Displacement	3.0 liters	2.0 liters
Moment of Inertia	304524 kgs ( 26954 lbs)	217342 kgs ( 19237 lbs)
Vehicle Mass	1645 kgs ( 9.4 lb-s <sup>2</sup> /in)	1254 kgs ( 7.2 lb-s <sup>2</sup> /in)

1990 Eagle Talon



1995 Plymouth Voyager



Enval

74195J00000011 969.0400000000000210510000001123096031097082197 96010168000  
00100000001016815 0305  
74195J00010012 969.0410000000000120F0201L  
74195J01000021 9.04 0000000009509442202P4GH 01999 9600 12  
1214131012010166032188  
74195J01000022 9.04 0000000001020216015600000000000009000001003018-014-01  
2040499840160301  
74195J01000031 9.04 000000000010201FDEW01 177019016014012009009  
000 17715528515601000401040101001000  
74195J01000041 9.04 00000000000110110000012222202123221011111110121111101  
74195J01000042 9.04 000000000  
210030804002110  
74195J01010051 9.04 0000000004929999991110000004400002000000211001111011-01  
42101011214109131410000000000006500000000000001021011  
74195J01010161 9.04 0000000003752802220532100  
74195J01020051 9.04 0000000000611320252130000001400004000000211001111011-01  
422010121141011323100000000000033161970000000004021141  
74195J01020161 9.04 0000000002640234661801100  
74195J01020261 9.04 0000000002392006151801100  
74195J01020361 9.04 0000000002390202151801100  
74195J01020461 9.04 0000000002290202181801100  
74195J02000021 9.04 0000000009010037034E3CT 01999 9600 12  
0214131012010117091189  
74195J02000022 9.04 00000000010101100120000000000000000009001003024-015+01  
8043099840290301  
74195J02000031 9.04 000000000010110LDEW02  
99825024714501000201010101001000  
74195J02000041 9.04 00000000006110010000012222230122111202611111021111110  
74195J02000042 9.04 000000000111823111113110613  
230000009301110  
74195J02010051 9.04 0000000002221500521110000004303110112114000000000000 00  
0000000000030216231000000000000142000300000000004151011  
74195J02010161 9.04 0000000003190402122032100  
74195J02010261 9.04 0000000003640678186032300  
74195J02010361 9.04 0000000007790402120511102  
74195J02010461 9.04 0000000007890402120511102  
74195J00000066 9.04 000000000CAR-CAR/ANGLE COLLISION  
74195J00000171 9.04 000000000VEHICLE 1 WAS HEADED EAST ON A FIVE LANE DIVI  
ED STREET. VEHICLE 2 WAS  
74195J00000271 9.04 000000000  
74195J00000371 9.04 000000000HEADED NORTH ON A UNDIVIDED TWO WAY STREET. I  
UE TO CONSTRUCTION, VEHICLE 2  
74195J00000471 9.04 000000000  
74195J00000571 9.04 000000000WAS TRAVELLING NORTH ON A SOUTHBOUND LANE. AS  
VEHICLE 2 ENTERED THE  
74195J00000671 9.04 000000000  
74195J00000771 9.04 000000000INTERSECTION, IT WAS STRUCK ON THE LEFT SIDE I  
Y THE FRONT OF VEHICLE 1.  
74195J00000871 9.04 000000000  
74195J00000971 9.04 000000000BOTH VEHICLES WERE HEADED NORTH AFTER THE ACC  
DENT. BOTH VEHICLES WERE TOWED  
74195J00001071 9.04 000000000  
74195J00001171 9.04 000000000DUE TO DAMAGE. THE DRIVER OF VEHICLE 2 AND TI  
E PASSENGER OF VEHICLE 1 WERE  
74195J00001271 9.04 000000000





FORM NAME	NUMBER OF DOLLAR SIGNS	NUMBER OF LEVEL 1 ERRORS	NUMBER OF LEVEL 2 ERRORS	VERSION NUMBER CONSISTENT
Accident	0	0	0	Y
General Vehicle	0	0	0	Y
Vehicle Exterior	0	0	0	Y
Vehicle Interior	0	0	0	Y
Occupant Assessment	0	0	1	Y
Occupant Injury	0	0	1	Y
Total Inter Errors		0	3	
Total Case Errors	0	0	5	



**NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM**

HS Form 434B (1/96)


































































































































































[illegible]


















































GRAND POLICE DEPARTMENT

INVESTIGATION - SPECIFIC CASE - SUPPLEMENTARY

Case No. 100-100000-100000

File No. 100-100000-100000

Investigator's Name: [ ]

Investigator's Title: [ ]

Investigator's Office: [ ]

Investigator's Date: [ ]

Investigator's Signature: [ ]

Investigator's Initials: [ ]

Investigator's Phone: [ ]

Investigator's Address: [ ]

Investigator's City: [ ]

Investigator's State: [ ]

Investigator's Zip: [ ]

Investigator's Email: [ ]

Investigator's Fax: [ ]

Investigator's Mobile: [ ]

Investigator's Pager: [ ]

Investigator's Home: [ ]

Investigator's Work: [ ]

Investigator's Cell: [ ]

Investigator's Other: [ ]

Investigator's Notes: [ ]

Investigator's Comments: [ ]

Investigator's Remarks: [ ]

Investigator's Observations: [ ]

Investigator's Findings: [ ]

Investigator's Conclusions: [ ]

Investigator's Recommendations: [ ]

Investigator's Disposition: [ ]

Investigator's Status: [ ]

Investigator's Date: [ ]

Investigator's Time: [ ]

Investigator's Location: [ ]

Investigator's Weather: [ ]

Investigator's Conditions: [ ]

Investigator's Equipment: [ ]

Investigator's Supplies: [ ]

Investigator's Tools: [ ]

Investigator's Materials: [ ]

Investigator's Resources: [ ]

Investigator's Information: [ ]

Investigator's Knowledge: [ ]

Investigator's Skills: [ ]

Investigator's Abilities: [ ]

Investigator's Qualifications: [ ]

Investigator's Experience: [ ]

Investigator's Training: [ ]

Investigator's Education: [ ]

Investigator's Background: [ ]

Investigator's History: [ ]

Investigator's Record: [ ]

Investigator's Reputation: [ ]

Investigator's Character: [ ]

Investigator's Personality: [ ]

Investigator's Temperament: [ ]

Investigator's Manner: [ ]

Investigator's Demeanor: [ ]

Investigator's Bearing: [ ]

Investigator's Appearance: [ ]

Investigator's Attitude: [ ]

Investigator's Behavior: [ ]

Investigator's Conduct: [ ]

Investigator's Actions: [ ]

Investigator's Reactions: [ ]

Investigator's Responses: [ ]

Investigator's Interactions: [ ]

Investigator's Communications: [ ]

Investigator's Relationships: [ ]

Investigator's Connections: [ ]

Investigator's Network: [ ]

Investigator's Contacts: [ ]

Investigator's Associates: [ ]

Investigator's Allies: [ ]

Investigator's Enemies: [ ]

Investigator's Friends: [ ]

Investigator's Family: [ ]

Investigator's Community: [ ]

Investigator's Society: [ ]

Investigator's Culture: [ ]

Investigator's Values: [ ]

Investigator's Beliefs: [ ]

Investigator's Opinions: [ ]

Investigator's Views: [ ]

Investigator's Attitudes: [ ]

Investigator's Perspectives: [ ]

Investigator's Outlook: [ ]

Investigator's Vision: [ ]

Investigator's Mission: [ ]

Investigator's Purpose: [ ]

Investigator's Goal: [ ]

Investigator's Objective: [ ]

Investigator's Aim: [ ]

Investigator's Intent: [ ]

Investigator's Desire: [ ]

Investigator's Wish: [ ]

Investigator's Hope: [ ]

Investigator's Dream: [ ]

Investigator's Vision: [ ]

Investigator's Mission: [ ]

Investigator's Purpose: [ ]

Investigator's Goal: [ ]

Investigator's Objective: [ ]

Investigator's Aim: [ ]


Investigator's Intent: [ ]

Investigator's Desire: [ ]


Investigator's Wish: [ ]


Investigator's Hope: [ ]

Investigator's Dream: [ ]































































































































































































**NATIONAL ACCIDENT SAMPLING SYSTEM  
CRASHWORTHINESS DATA SYSTEM**

HS Form 434B (1/96)























































































